



## Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M  
6 Benoi Place Singapore 629927  
Tel: 6861 0908 Fax: 6515 2948

Date: 21.05.2019

AXA Insurance Singapore Pte Ltd  
8 Shenton Way #27-01/02  
AXA Tower  
Singapore 068811

Attn: Motor Claims Dept

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2707R TOYOTA VELLFIRE HYBRID 2.5 (2018)

### To Supply

1 ) 1pc	Right front fender "Hybrid" emblem	\$	52.40
Sub total parts		\$	52.40
Less: 25% discount		\$	(13.10)
		\$	39.30

### To Supply S.Nett Parts

1 ) 1pc	"Prime Royal" sticker	\$	80.00
Sub total S.Nett Parts		\$	80.00

### L/charges

1 )	To tuff kote.	\$	50.00
2 )	To knock & repair right front fender & right front door. Align & adjust right front fender & right front door.	\$	400.00
3 )	To putty, respray painting right front fender & right front door in pearl white. To polish.	\$	400.00

Sub total L/charges	\$	850.00
Estimated Grand total	\$	969.30

Tanpin 9749574  
WP  
22/5/19 1242 Spn  
02 days  
Resurvey after repair  
Tanpin 11/11/2019