

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

16/05/2019

Owner: ANC MOTORING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SLT3640K

1pc rear RH door
2pcs rear RH door hinge @\$141.45
1pc rear RH door frame sticker
1pc rear RH door handle base
1pc rear RH door glass moulding
1pc rear RH door glass motor & gear
1pc rear RH door glass pillar
1pc rear RH door inner lock
1pc rear RH door inner rubber
1pc rear RH door inner panel
1pc rear RH door inner step garnish
1pc rear RH door outer step garnish
1pc rear RH door pillar
1pc RH side skirt
1pc RH side rocket panel
1pc rear RH fender
1pc rear RH fender air-duct
1pc rear RH fender inner shield
8pcs rear RH fender inner shield clip @\$5.00
1pc rear RH fender inner garnish
1pc rear RH wheel house

less 25%

remove & refit rear cushions
remove & refit rear RH fender glass & rear RH door glass
sealant
tuffkote
wiring
spray painting
labour charges
Total

By \$ 1,217.45 ✓
R \$ 282.90 X
M \$ 158.50 ✓
L \$ 281.50 X
BMS \$ 181.25 ✓
R \$ 374.45 ✓
\$ 181.25 ?
R \$ 581.90 X
M/L \$ 172.45 ✓
\$ 621.25 ?
R \$ 381.50 ✓ ?
M \$ 191.80 ✓
R \$ 852.50 X
BMS \$ 681.90 ✓
R \$ 852.50 ✓
R \$ 971.50 ✓
L \$ 178.85 X
S \$ 182.25 X
M \$ 40.00 X
L \$ 691.45 ✓
R \$ 561.60 X

\$ 9,638.75
\$ 2,409.69
\$ 7,229.06

\$ 180.00 100l
\$ 180.00 80l
\$ 80.00 40l
\$ 120.00 60l
\$ 120.00 20l
\$ 1,600.00 800l
\$ 1,600.00 1000l
\$ 11,109.06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modifications is allowed
- Supplementary cost must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

