

来發 (明 记) 摩 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE SUPPLEMENTARY

EST. No EST0018136
Sebastian Stella

Page 1 of 1
Your ref. : TP-YM 7813K ERGO
Job No : 69102
Our ref : 17.12.32
Payment :
Date : 10/1/2018

Attn

Vehicle No SGH 6754T
Vehicle Model . Toyota Vios
Accident on . 22/12/2017

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts.					
SUPPLEMENTARY ITEM.					
2.00	Pcs	Front shock absorber	444.80 222.40	25.00	333.60
2.00	Pcs	Rear shock absorber	350.6 175.30	25.00	262.95
2.00	Pcs	Front shock absorber support	124.40 62.20	25.00	93.30
2.00	Pcs	Suspension arm	452.2 226.10	25.00	339.15
1.00		Labour to remove and renew suspension, etc	320.00		320.00

Sub-Total 1,349.00
GST 7.00% 94.43
Total S\$ 1,443.43

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICC Deluxe oven heater for re-spraying all motor vehicles."