

22/03/2009

ASIS REC. BY:

REF:

CS/GAI19009CW8/H19d3lb

Special Instruction:

Surveyor: Tau RichASSIGNMENT (Office)From (Person): Sharon Ng

of

GAI

Date/Time:

22/5/2019 @ 10.54am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No.:

YN 9152R

Insured:

GBD 8436D

at Workshop m/s

VAX Auto

Tel:

6455 2957

of

26 Chia Ping Road

Policy No.:

Claim No.:

ELMOMVC 000003661

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2.17pm @ 22/5/19

Person Contacted:

Yee-Sing

Vehicle

IN/OUT

Date/Time

Action/Instruction

Estimate ✓YN 9152R-xGBD 8436D - CS/GAI19009CW8/H19d3lbD.O.A: 15/5/201923/5/19 @3.18pm revised to GAI by email.

Tanji

REI

GA

ASSIGNMENT

Form: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / UVA / HV / MV

To inspect Vehicle No: _____

at Workshop no: _____

at: _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 952K

IDAC Accident Report: Consistent? Yes or No

GIA / PR Secm: Consistent? Yes or No


Est. Repairs: 8 days Res: Yes or No

Lump Sum: % J Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT



Veh No: YN9152K at Trip: 2015 Sep

Type: M/Car / M/Cycle / Bus / Van / Conv / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Canter FEB21 2998

Color: white ABC Insured / STD / HI / NA

Sp Reading: 81856 (Radio) Insured / STD / HI / NA

Eng/Mod: FEB21E A/422

C/Mod: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NA / SARim / STD AIRim or

Tyre Size: F: 145/R15 R: 22 (D)

BS / DUN / EXNOVA / GY / ES / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CST tires

Front: 6 mm Rear: 6/6 mm

R/Bal: 6 mm L/Bal: 6/6 mm

D.O.A: 22/5/12 RES 15

Survey held at VFix Chp Pery

Des. of Damage: Front / Rear / O/S / H/S / U/C / Rooflop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: 11/11 Action / Instruction: 45810.500, 8 days e-mail to w/s (led to 2088.96, 66%)

RECEIVED 15 NOV 2019

Date/Time, File Pass to? ☐ : Prel. Report

n 15/11 transfer ☐ : Final Report

Date/Time, File Return to? _____

2)

Report Format: TP

Lump Sum / LPA: 10500

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Invs (\$) ☐ Weekend (\$)

Survey Fee: ☐ Transportation ☐ Photos ☐ Others

TOTAL: 450

Nivitha (LKK Auto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com> on behalf of Motor Claims <MotorClaims@sg.gaig.com>
Sent: Wednesday, 22 May 2019 10:54 AM
To: SUR
Cc: assignments; Ngian, Kelvyna
Subject: FW: Accident Involving YN9152R & GBD8436D || Our ref: CLMOMVC000003661
Attachments: NOA GAIG.docx

Dear LKK

Please survey TP veh no. YN9152R on a without prejudice basis. All 3 SAS provided in related OD assignment for GBD8436D sent earlier.

Please update Kelvyna, the officer-in-charge.

Regards
Sharon
Great American

From: ybsim@vfixauto.com.sg <ybsim@vfixauto.com.sg>
Sent: Wednesday, May 22, 2019 9:20 AM
To: Motor Claims <MotorClaims@sg.gaig.com>
Cc: alancik@vfixauto.com.sg; kentsh@vfixauto.com.sg; jessicassy@vfixauto.com.sg; jeffbz@vfixauto.com.sg
Subject: [External] Accident Involving YN9152R & GBD8436D

Dear Sir,

Please find attached copy. Kindly arrange survey for vehicle YN9152R.

Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Best regards,



Yee Bing
Accounts Assistant cum Admin
Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd
26 Chia Ping Road Singapore 619977
Contact: 6455 2957 | E: ybsim@vfixauto.com.sg

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shiau Chan (LKKAuto)

From: wskoh@vfixauto.com.sg
Sent: Thursday, 14 November 2019 1:31 PM
To: Taufikh (LKKAuto); Shiau Chan (LKKAuto)
Cc: ybsim@vfixauto.com.sg; jeffbz@vfixauto.com.sg; jessicassy@vfixauto.com.sg; kentsh@vfixauto.com.sg; alancik@vfixauto.com.sg
Subject: RE: ACCIDENT INVOLVING YN9152R & GBD8436D ON 15/5/2019
Attachments: LOD.pdf

Dear Taufikh,

Good day.

We accept your offer COR 1/s\$10,500 and 8 repair days.

Kindly refer the attached LOD for your kind perusal.

Original copies we will post up to Great American Insurance directly.



Thank You.

Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,

Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | **Vfix** Auto Service Pte Ltd | **Vfix** Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

From: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Sent: Friday, 8 November 2019 4:56 PM
To: wskoh@vfixauto.com.sg
Cc: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING YN9152R & GBD8436D ON 15/5/2019

Hi Weng,

Refer attached, COR 1/s\$10,500 , 8 days.

Please forward the after repair photos, thank you.

Regards
Taufikh
Lkk Auto

From: wskoh@vfixauto.com.sg [mailto:wskoh@vfixauto.com.sg]
Sent: Wednesday, 30 October 2019 3:22 PM
To: 'SUR'; taufikh@lkkauto.com
Cc: ybsim@vfixauto.com.sg; jessicassy@vfixauto.com.sg; jeffbz@vfixauto.com.sg;
alancnk@vfixauto.com.sg; kentsh@vfixauto.com.sg
Subject: RE: ACCIDENT INVOLVING YN9152R & GBD8436D ON 15/5/2019

Hi Taufik,

Kindly let us have the status.

Much appreciated if you could processing of this claim .

Thank You.



Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,

Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | **Vfix** Auto Service Pte Ltd | **Vfix** Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

From: wskoh@vfixauto.com.sg <wskoh@vfixauto.com.sg>
Sent: Friday, 4 October 2019 3:27 PM
To: 'SUR' <sur@lkkauto.com>
Cc: 'ybsim@vfixauto.com.sg' <ybsim@vfixauto.com.sg>; 'jessicassy@vfixauto.com.sg' <jessicassy@vfixauto.com.sg>; 'jeffbz@vfixauto.com.sg' <jeffbz@vfixauto.com.sg>; 'alancnk@vfixauto.com.sg' <alancnk@vfixauto.com.sg>
Subject: RE: ACCIDENT INVOLVING YN9152R & GBD8436D ON 15/5/2019

Dear Taufik ,

Kindy refer the attached question mark photo for your kind perusal.



Thank You.

Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,

Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

From: wskoh@vfixauto.com.sg <wskoh@vfixauto.com.sg>

Sent: Saturday, 24 August 2019 10:18 AM

To: 'SUR' <sur@lkkauto.com>

Cc: 'ybsim@vfixauto.com.sg' <ybsim@vfixauto.com.sg>; 'jessicassy@vfixauto.com.sg' <jessicassy@vfixauto.com.sg>; 'jeffbz@vfixauto.com.sg' <jeffbz@vfixauto.com.sg>; 'alancik@vfixauto.com.sg' <alancik@vfixauto.com.sg>; 'Admin A' <admin-a@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING YN9152R & GBD8436D ON 15/5/2019

Dear Taufik,

Any status update from your side ?

Thank You



Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,

Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

From: wskoh@vfixauto.com.sg <wskoh@vfixauto.com.sg>

Sent: Tuesday, 20 August 2019 9:46 AM

To: 'SUR' <sur@lkkauto.com>

Cc: 'ybsim@vfixauto.com.sg' <ybsim@vfixauto.com.sg>; 'jessicassy@vfixauto.com.sg' <jessicassy@vfixauto.com.sg>; 'jeffbz@vfixauto.com.sg' <jeffbz@vfixauto.com.sg>;

'alanclk@vfixauto.com.sg' <alanclk@vfixauto.com.sg>

Subject: ACCIDENT INVOLVING YN9152R & GBD8436D ON 15/5/2019

Dear Taufik,

Good day.

Kindly find attached estimate and after paint photo for proceed COR.

Thank you.



Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,

Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | **Vfix** Auto Service Pte Ltd | **Vfix** Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 23 May 2019 3:18 PM
To: 'Motor Claims'; SUR
Cc: assignments; 'Ngian, Kelvyna'
Subject: RE: RE: FW: 3rd party : SFA9928M/GBD8436D/YN9152R || Our ref: CLMOMVC000003661
Attachments: CSGAI19009008T1qd3.pdf

Dear Sir/Madam,

Enclosed herewith preliminary advice of YN 9152R.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 22 May 2019 3:37 PM
To: 'Motor Claims' <MotorClaims@sg.gaig.com>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>
Subject: RE: RE: FW: 3rd party : SFA9928M/GBD8436D/YN9152R || Our ref: CLMOMVC000003661

Resend

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not In the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) [<mailto:admin-d@lkkauto.com>]
Sent: Wednesday, 22 May 2019 3:15 PM
To: 'Motor Claims' <MotorClaims@sg.gaig.com>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>
Subject: RE: RE: FW: 3rd party : SFA9928M/GBD8436D/YN9152R || Our ref: CLMOMVC000003661



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CLMOMVC000003661

Date: 23rd May 2019

Our Ref: CS/GAI19009008/T1qd3

The Motor Claims Department
Great American Insurance Company

Attn: Sharon

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. YN 9152R .

We thank you for the instruction on 22/05/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/05/2019 at the premises of M/s VFIX AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>30,798.96</u> .
Revised Estimate Amount	: S\$ <u>8,632.45</u> .
"Check" Items Amount	: S\$ <u>7,898.23</u> .
Market Value	: S\$ <u>-</u> .
Salvage Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages at the front portion.



Comments/ Present Status:
Damages consistent.
We have NOT authorise repair.

Yours faithfully

Mohd Taufikh
Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5389H
Vehicle Details	
Vehicle No.:	YN9152R
Vehicle to be Exported:	No
Intended Deregistration Date:	23 May 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	4P10B80986
Chassis No.:	FEB21EA10422
Maximum Power Output:	-
Open Market Value:	\$28,557.00
Original Registration Date:	09 Sep 2015
First Registration Date:	09 Sep 2015
Transfer Count:	1
Actual ARF Paid:	\$1,428.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Sep 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$5,323.00
COE Rebate Amount:	\$3,350.00
Total Rebate Amount:	\$3,350.00

The information contained herein is correct as at 23 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/05/2019 17:33
Date Of Accident	15/05/2019 15:45
Exact Location Of Accident	ANG MO KIO INDUSTRIAL PARK 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN9152R
Insured/Policyholder	
Name Of Registered Owner	HOE HUAT EQUIPMENT PTE. LTD.
Co Reg No	201615389H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63855397
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	CANTER FEB21ER4SDEB (CBU)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103650312
Cover Note Number	

Driver

Name of Driver	ISLAM AKIDUL
Passport No/FIN	G2282617X
Date Of Birth	17/01/1994
Occupation	OUTDOOR
Date Of Driving Pass	09/04/2018
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83555661
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	15 CHANGI NORTH STREET 1 #01-03
Postcode	498765
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE STATEMENT ON THE SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD8436D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RETHINAM BALASUBRAMANIAN
NRIC/Passport Number	0 35171568
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SFA9928M
-----------------------------	----------

Vehicle Make/Model/Colour	MERCEDES BENZ R300L
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHAN SOON KHEONG
NRIC/Passport Number	
Contact Number	96740860
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and in copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, receipts or notices to me, which could involve disclosure of certain personal data about me to being about delivery of the same as well as the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purpose(s); and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to other third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purpose(s);
- (d) my Personal Information will also be collected and used to compile claim history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (c) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Person(s) Signature
Name
NRIC/FIN No
CPF:

Sketch Plan Pg. 2

SKETCH PLAN



Vehicle A YN9152R
Vehicle B G6D543ED
Vehicle C SFAP188M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: YN9152R	ACCIDENT DATE & TIME: 15/03/19, 1545hrs
CONTACT NUMBER:	E-MAIL ADDRESS:
LOCATION: Ang Mo Kio Industrial Park 2	
On 15/03/19 around 1545hrs, vehicle A driving straight at Ang Mo Kio Industrial Park 2. Suddenly vehicle B was turning out from right side, vehicle B did not stop before turning out, so vehicle B crashed to vehicle A and also crashed to vehicle C which parked at the parking lot.	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.	
Please state:	
☒ I Claim Own Policy	☐ I Claim Third Party
☐ I Claim CO/TP as other involved	☐ Reporting Only

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(driver is not the policyholder)
Date & Time:

Reporting Officer's Signature
Name:
NRIC/ID No.:





Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5103650312

Cover : Third Party

- | | |
|---|--------------------------------|
| 1. Index mark and Registration Number of Vehicle | : YN9152R |
| Chassis Number | : FEB21EA10422 |
| 2. Name of Policyholder | : HOE HUAT EQUIPMENT PTE. LTD. |
| 3. Effective Date of Insurance | : 09 Sep 2018 |
| 4. Expiry Date of Insurance | : 08 Sep 2019 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession. | |
| (b) Use for the carriage of passengers or goods in connection with the Policyholder's business. | |

This Policy does not cover

- (a) Use for hire or reward
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
INSURE WITH COE	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Agency : TIMES INS. BROKERS (MOTOR BUSINESS) (00000690643)
 Date of Issue : 06 Sep 2018 11:51 hrs.

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive





Vfix Auto Pte Ltd
26 Chia Ping Road
Singapore 619977
Email : contact@vfixauto.com.sg
Tel : 6448 9268 Fax: 6445 2368
UEN / GST Reg No. : 201830761R

ESTIMATE

DATE :
ACC DATE :
REF NO :
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO :YN9152R MITSUBISHI FUSO

DESCRIPTION	AMOUNT S\$
1 FRONT WINDSCREEN	726.50 <i>con</i>
1 FRONT WINDSCREEN RUBBER	271.60 <i>ad</i>
2 FRONT WIPER ARM	170.00 <i>LH-bt</i> 340.00 <i>RH-X</i>
2 FRONT WIPER ARM COVER	39.00 <i>LH-mis</i> 78.00 <i>RH-X</i>
2 FRONT WIPER BLADE	68.00 136.00 <i>X</i>
1 FRONT WIPER MOTOR	674.30 <i>?</i>
1 FRONT WIPER LINK	379.40 <i>?</i>
2 FRONT SPRAY NOZZLE	40.00 80.00 <i>X</i>
1 FRONT PANEL	672.70 <i>bt</i>
1 FRONT PANEL TOP APRON GARNISH	369.10 <i>dp</i>
10 FRONT PANEL TOP APRON GARNISH CLIP	5.00 50.00 <i>us</i>
1 FRONT PANEL ENBLEM (FUSO)	172.40 <i>he</i>
2 FRONT CORNER PANEL	374.00 748.00 <i>con</i>
2 FORNT SIDE MIRROR BRACKET	360.00 720.00 <i>X</i>
1 FRONT PARKING MIRROR LH	79.00 <i>mg</i>
1 FORNT GRILLE	481.60 <i>con</i>
1 FRONT GRILLE BADGE	141.30 <i>ad</i>
1 FRONT GRILLE EMBLEM (CANTER)	189.70 <i>ad</i>
10 FRONT GRILLE CLIP	3.00 30.00 <i>ad</i>
2 HEAD LAMP	597.30 1,194.60 <i>con</i>
2 FRONT SIGNAL LAMP	227.10 454.20 <i>con</i>
2 FRONT CORNER REFLECTOR LAMP	150.00 300.00 <i>mg</i>
1 FRONT BUMPER	672.90 <i>bt</i>
2 FRONT BUMPER BRACKET	142.00 284.00 <i>bt</i>
2 FRONT BUMPER SIDE PAD	210.00 420.00 <i>dis</i>
1 HORN	120.00 <i>?</i>
1 CABIN CROSS BAR	572.00 <i>?</i>
2 CABIN CROSS BAR MOUNTING	450.00 900.00 <i>?</i>
1 AIR CON CONDENSER	1,615.30 <i>X</i>
1 CONDENSER AIR CON PIPE	294.60 <i>X</i>
1 CONDENSER SUCTION PIPE	320.10 <i>X</i>
1 CONDENSER DISCHARGE PIPE	318.50 <i>X</i>
1 CONDENSER DRYER	217.00 <i>X</i>
1 RADIATOR	1,210.00 <i>X</i>
1 RADIATOR FAN COWLING	347.00 <i>X</i>
1 RADIATOR FAN BLADE	86.00 <i>X</i>
1 RADIATOR FAN CLUTH	672.00 <i>X</i>

2	FRONT BRAKE OIL PIPE	230.00	260.00 x
1	FRONT CLUTCH OIL PIPE		198.00 x
1	FRONT DOOR PANEL LH		654.00 RY
1	FRONT DOOR LH		1,158.50 RY
2	FRONT DOOR HINGE LH	120.00	240.00 RY
1	FRONT DOOR WEATHERSTRIP LH		224.30 x
1	FRONT DOOR BOTTOM STEP GARNISH LH		270.00 <i>act</i>
1	DASH BOARD		980.30 ?
1	DASH BOARD CENTER CONSOLE GARNISH		452.30 ?
1	DASH BOARD CENTER CROSS PANEL		695.00 x
1	AIR CON BLOWER		1,210.00 ?
1	AIR CON EVAPORATOR		976.00 ?
1	FRONT FLOOR PANEL		1,430.00 RY
4	ENGINE MOUNTING	250.00	1,000.00 x

25%
 LESS 20% \$ 26,086.20
 \$ 20,868.96

DESCRIPTIONS	UNIT PRICE	AMOUNT \$\$
<u>SPECIAL NETT</u>		<i>40 btr</i>
1 <u>FRONT NUMBER PLATE</u>	\$	60.00
1 <u>RADIO</u>	\$	740.00 x
1 <u>FRONT DOOR COMPANY STICKER</u>	\$	250.00 <i>150 net</i>
1 <u>RADIATOR COOLANT</u>	\$	100.00 ?
	\$	<u>1,150.00</u>

LABOUR & MISCELLANEOUS :		AMOUNT S\$
1	To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	2,500.00 1200
2	To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	1,800.00/000
3	To remove, refit cabin	2,000.00
4	To remove, refit front windscreen	180.00 120
5	To remove, refit carpet, seat and interior	250.00 600
6	To remove, refit dash board	450.00 plastic 2000
7	To remove, refit air con and evaporator	350.00 150?
8	To remove, refit front door part	150.00 600
9	To remove, refit engine mounting	300.00 200 7 plastic
10	To reset and diagnosis fault code	800.00 200
		\$ 8,780.00

GRAND TOTAL : \$ 30,798.96

Vfix Auto Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary items must be resurveyed and subject to final approval from Insurance Company

Witnessed by Repairer
Date:

Tan Jiah
23/5/19
97455749
WP
22/5/19 1720
Resurvey after repair
8 days
sure@lkkauto.com



Vfix Auto Pte Ltd
26 Chia Ping Road
Singapore 619977
Email : contact@vfixauto.com.sg
Tel : 6448 9268 Fax: 6445 2368
UEN / GST Reg No. : 201830761R

ESTIMATE

DATE :
ACC DATE :
REF NO :
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO :YN9152R MITSUBISHI FUSO

DESCRIPTION		AMOUNT S\$
1 FRONT WINDSCREEN		726.50 <i>con</i> ✓
1 FRONT WINDSCREEN RUBBER		271.60 <i>con</i> ✓
2 FRONT WIPER ARM	170.00 <i>LH-bt</i> ✓	340.00 <i>RH-X</i> ✓
2 FRONT WIPER ARM COVER	39.00 <i>LH-mis</i> ✓	78.00 <i>RH-X</i> ✓
2 FRONT WIPER BLADE	68.00	136.00 <i>X nn</i> ✓
1 FRONT WIPER MOTOR		674.30 <i>? X nn</i> ✓
1 FRONT WIPER LINK		379.40 <i>? X</i> ✓
2 FRONT SPRAY NOZZLE	40.00	80.00 <i>X nn</i> ✓
1 FRONT PANEL		672.70 <i>bt</i> ✓
1 FRONT PANEL TOP APRON GARNISH		369.10 <i>dp</i> ✓
10 FRONT PANEL TOP APRON GARNISH CLIP	5.00	50.00 <i>uc</i> ✓
1 FRONT PANEL ENBLEM (FUSO)		172.40 <i>he</i> ✓
2 FRONT CORNER PANEL	374.00	748.00 <i>con</i> ✓
2 FORNT SIDE MIRROR BRACKET	360.00	720.00 <i>X nn</i> ✓
1 FRONT PARKING MIRROR LH		79.00 <i>mis</i> ✓
1 FORNT GRILLE		481.60 <i>con</i> ✓
1 FRONT GRILLE BADGE		141.30 <i>ne</i> ✓
1 FRONT GRILLE EMBLEM (CANTER)		189.70 <i>ve</i> ✓
10 FRONT GRILLE CLIP	3.00	30.00 <i>ue</i> ✓
2 HEAD LAMP	597.30	1,194.60 <i>con</i> ✓
2 FRONT SIGNAL LAMP	227.10	454.20 <i>con</i> ✓
2 FRONT CORNER REFLECTOR LAMP	150.00	300.00 <i>nn</i> ✓
1 FRONT BUMPER		672.90 <i>bt</i> ✓
2 FRONT BUMPER BRACKET	142.00	284.00 <i>bt</i> ✓
2 FRONT BUMPER SIDE PAD	210.00	420.00 <i>dis</i> ✓
1 HORN		120.00 <i>dis</i> ✓ <i>? X</i> ✓
1 CABIN CROSS BAR		572.00 <i>? R X</i> ✓
2 CABIN CROSS BAR MOUNTING	450.00	900.00 <i>? bt</i> ✓
1 AIR CON CONDENSER		1,615.30 <i>1345.50</i> <i>X bt</i> ✓
1 CONDENSER AIR CON PIPE		294.60 <i>X nn</i> ✓
1 CONDENSER SUCTION PIPE		320.10 <i>194.51</i> <i>X bt</i> ✓
1 CONDENSER DISCHARGE PIPE		318.50 <i>X bt</i> ✓
1 CONDENSER DRYER		217.00 <i>X X nn</i> ✓
1 RADIATOR		1,210.00 <i>X bt</i> ✓
1 RADIATOR FAN COWLING		347.00 <i>X</i> ✓
1 RADIATOR FAN BLADE		86.00 <i>X</i> ✓
1 RADIATOR FAN CLUCTH		672.00 <i>X</i> ✓

2	FRONT BRAKE OIL PIPE	230.00	260.00 x nn
1	FRONT CLUTCH OIL PIPE		198.00 x nn
1	FRONT DOOR PANEL LH		654.00 Rx
1	FRONT DOOR LH		1,158.50 Rx
2	FRONT DOOR HINGE LH	120.00	240.00 Rx
1	FRONT DOOR WEATHERSTRIP LH		224.30 x nn
1	FRONT DOOR BOTTOM STEP GARNISH LH		270.00 cut
1	DASH BOARD		980.30 ? x nn
1	DASH BOARD CENTER CONSOLE GARNISH		452.30 ? x nn
1	DASH BOARD CENTER CROSS PANEL		695.00 x nn
1	AIR CON BLOWER		1,210.00 ? CRB
1	AIR CON EVAPORATOR		976.00 ? x nn
1	FRONT FLOOR PANEL		1,430.00 Rx
4	ENGINE MOUNTING	250.00	1,000.00 x nn

13414.51

10060.88

25%
LESS 20%

\$ 26,086.20
\$ 20,868.96

DESCRIPTIONS	UNIT PRICE	AMOUNT S\$
<u>SPECAIL NETT</u>		40 b7
1 <u>FRONT NUMBER PLATE</u>		\$ 60.00
1 <u>RADIO</u>		\$ 740.00 x nn
1 <u>FRONT DOOR COMPANY STICKER</u>		\$ 250.00 150 one
1 <u>RADIATOR COOLANT</u>		\$ 100.00 P nu
		\$ 1,150.00 290

LABOUR & MISCELLANEOUS :

AMOUNT S\$

1	To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	2,500.00 1200
2	To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	1,800.00/000
3	To remove, refit cabin	2,000.00 2000 ²⁰⁰
4	To remove, refit front windscreen	180.00 ¹²⁰
5	To remove, refit carpet, seat and interior	250.00 ⁶⁰
6	To remove, refit dash board	450.00 ^{photo 200} 200 ²⁰⁰ 200
7	To remove, refit air con and evaporator	350.00 ¹⁵⁰ 150
8	To remove, refit front door part	150.00 ⁶⁰
9	To remove, refit engine mounting	300.00 ²⁰⁰ 200 ^{wh.} 200 ^{photo}
10	To reset and diagnosis fault code	800.00 ²⁰⁰
		\$ 8,780.00 2790

GRAND TOTAL : \$ 30,798.96

Vfix Auto Pte Ltd

10060.88
290
2790

13140.88
2/5/10,500#
8 days #

Tanplm 97495749
WP
22/5/19E 1720
Resum after repair
8 days
sur@11kanton



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI19009008/T1qd3e2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 25-11-2019		
		Code : GAI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 8436D	Veh. Inspected	YN 9152R	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000003661	Excess (\$)	0.00	
Assign From	SHARON NG	Assign Date	22/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER FEB21	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	FEB21EA10422	Colour	WHITE	
Odometer	81856	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	CST TIRES	6 mm	
L/H Front Tyre	195 R15	CST TIRES	6 mm	
R/H Rear Tyre	195 R15 (D)	CST TIRES	6/6 mm	
L/H Rear Tyre	195 R15 (D)	CST TIRES	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/05/2019	Inspection Date	22/05/2019	
Survey held at	26 CHIA PING ROAD			
Repairer	VFIX AUTO SERVICE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 9152R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WINDSCREEN	CRACKED	726.50	726.50
1	FRONT WINDSCREEN RUBBER	NECESSARY	271.60	271.60
2	FRONT WIPER ARM @\$170.00	N/S BENT / O/S NOT NECESSARY	340.00	170.00
2	FRONT WIPER ARM COVER @\$39.00	N/S MISSING / O/S NOT NECESSARY	78.00	39.00
2	FRONT WIPER BLADE @\$68.00	NOT NECESSARY	136.00	-
1	FRONT WIPER MOTOR	NOT NECESSARY	674.30	-
1	FRONT WIPER LINK	BENT	379.40	379.40
2	FRONT SPRAY NOZZLE @\$40.00	NOT NECESSARY	80.00	-
1	FRONT PANEL	BENT	672.70	672.70
1	FRONT PANEL TOP APRON GARNISH	DEFORMED	369.10	369.10
10	FRONT PANEL TOP APRON GARNISH CLIP @\$5.00	NECESSARY	50.00	50.00
1	FRONT PANEL EMBLEM (FUSO)	NECESSARY	172.40	172.40
2	FRONT CORNER PANEL @\$374.00	CRACKED	748.00	748.00
2	FRONT SIDE MIRROR BRACKET @\$360.00	NOT NECESSARY	720.00	-
1	FRONT PARKING MIRROR LH	MISSING	79.00	79.00
1	FRONT GRILLE	CRACKED	481.60	481.60
1	FRONT GRILLE BADGE	NECESSARY	141.30	141.30
1	FRONT GRILLE EMBLEM (CANTER)	NECESSARY	189.70	189.70
10	FRONT GRILLE CLIP @\$3.00	NECESSARY	30.00	30.00
2	HEAD LAMP @\$597.30	CRACKED	1,194.60	1,194.60
2	FRONT SIGNAL LAMP @\$227.10	CRACKED	454.20	454.20
2	FRONT CORNER REFLECTOR LAMP @\$150.00	MISSING	300.00	300.00
1	FRONT BUMPER	BENT	672.90	672.90
2	FRONT BUMPER BRACKET @\$142.00	BENT	284.00	284.00
2	FRONT BUMPER SIDE PAD @\$210.00	DISTORTED	420.00	420.00
1	HORN	DISTORTED	120.00	120.00
1	CABIN CROSS BAR	TO REPAIR SEE LABOUR	572.00	-
2	CABIN CROSS BAR MOUNTING @\$450.00	BENT	900.00	900.00
1	AIR CON CONDENSER	BENT	1,615.30	1,345.50

Report Ref No. CS/GAI19009008/T1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CONDENSER AIR CON PIPE	NOT NECESSARY	294.60	-
1	CONDENSER SUCTION PIPE	BENT	320.10	194.51
1	CONDENSER DISCHARGE PIPE	BENT	318.50	318.50
1	CONDENSER DRYER	NOT NECESSARY	217.00	-
1	RADIATOR	BENT	1,210.00	1,210.00
1	RADIATOR FAN COWLING	NOT NECESSARY	347.00	-
1	RADIATOR FAN BLADE	NOT NECESSARY	86.00	-
1	RADIATOR FAN CLUTCH	NOT NECESSARY	672.00	-
2	FRONT BRAKE OIL PIPE	NOT NECESSARY	260.00	-
1	FRONT CLUTCH OIL PIPE	NOT NECESSARY	198.00	-
1	FRONT DOOR PANEL LH	TO REPAIR SEE LABOUR	654.00	-
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,158.50	-
2	FRONT DOOR HINGE LH @\$120.00	TO REPAIR SEE LABOUR	240.00	-
1	FRONT DOOR WEATHERSTRIP LH	NOT NECESSARY	224.30	-
1	FRONT DOOR BOTTOM STEP GARNISH LH	CUT	270.00	270.00
1	DASH BOARD	NOT NECESSARY	980.30	-
1	DASH BOARD CENTER CONSOLE GARNISH	NOT NECESSARY	452.30	-
1	DASH BOARD CENTER CROSS PANEL	NOT NECESSARY	695.00	-
1	AIR CON BLOOWER	CRACKED	1,210.00	1,210.00
1	AIR CON EVOPORATOR	NOT NECESSARY	976.00	-
1	FRONT FLOOR PANEL	TO REPAIR SEE LABOUR	1,430.00	-
4	ENGINE MOUNTING @\$250.00	NOT NECESSARY	1,000.00	-
	LESS 20% DISCOUNT		-5,217.24	-
	LESS 25% DISCOUNT		-	-3,353.63
			20,868.96	10,060.88
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	BENT	60.00	40.00
1	RADIO (SN)	NOT NECESSARY	740.00	-
1	FRONT DOOR COMPANY STICKER (SN)	NECESSARY	250.00	150.00

Report Ref No. CS/GAI19009008/T1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR COOLANT (SN)	NECESSARY	100.00	100.00
			1,150.00	290.00
	LABOUR			
	TO REMOVE DAMAGED BODY PANEL WITH ALL NECESSARY COMPONENTS / ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN FRONT DOOR PILLAR, REPAIR / RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS / ATTACHMENTS. INCLUSIVE OF THE REPAIR OF CABIN CROSS BAR, FRONT DOOR PANEL LH, FRONT DOOR LH, FRONT DOOR HINGE LH AND FRONT FLOOR PANEL.		2,500.00	1,200.00
	TO SPRAY PAINT REPLACED / REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.		1,800.00	1,000.00
	TO REMOVE, REFIT CABIN.	NOT NECESSARY	2,000.00	-
	TO REMOVE, REFIT FRONT WINDSCREEN.		180.00	120.00
	TO REMOVE, REFIT CARPET, SEAT AND INTERIOR.		250.00	60.00
	TO REMOVE, REFIT DASH BOARD.	NOT NECESSARY	450.00	-
	TO REMOVE, REFIT AIR CON EVAPORATOR.		350.00	150.00
	TO REMOVE, REFIT FRONT DOOR PART.		150.00	60.00
	TO REMOVE, REFIT ENGINE MOUNTING.	NOT NECESSARY	300.00	-
	TO RESET AND DIAGNOSIS FAULT CODE.		800.00	200.00
			8,780.00	2,790.00
GRAND TOTAL			30,798.96	13,140.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,500.00

Report Ref No. CS/GAI19009008/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.