

## Supplementary or Omitted List



VEHICLE NUMBER: **SLA3733B**

MODEL                      Touran Comfortline 1.4

### CLAIMS DETAILS

|              | LABOUR DESCRIPTION | AMOUNT |      |               |
|--------------|--------------------|--------|------|---------------|
|              |                    | Qty    | Unit | Amount        |
|              |                    |        |      |               |
|              |                    |        |      |               |
|              |                    |        |      |               |
|              |                    |        |      |               |
|              |                    |        |      |               |
|              |                    |        |      |               |
|              |                    |        |      |               |
|              |                    |        |      |               |
| <b>Total</b> |                    |        |      | <b>\$0.00</b> |

| <u>No.</u>    | <u>Item No.</u> | <u>Description</u>           | <u>Qty</u> | <u>Unit Pricing</u> | <u>Discount</u> | <u>Amount</u>   |
|---------------|-----------------|------------------------------|------------|---------------------|-----------------|-----------------|
| 1             | 5C6919491D      | Sensor Bracket ✓             | 1          | \$15.07             | ✓               | \$15.07         |
| 2             | 5C6919491E      | Sensor Bracket ✓             | 1          | \$15.07             | ✓               | \$15.07         |
| 3             | 5C6919491E      | Sensor Bracket ✓             | 2          | \$15.07             | ✓               | \$30.14         |
| 4             | D 180KU2A1      | 2k-Plastic Adhesive ✓        | 1          | \$74.29             | ✓               | \$74.29         |
| 5             | D 822150A1      | Bonding Agent For Plastic ✓  | 1          | \$56.90             | ✓               | \$56.90         |
| 6             | 5C6807393E      | TAILLIGHT LOWER BRACKET LH ✓ | 1          | \$78.37             | ✓               | \$78.37         |
| 7             | 5C6807394E      | TAILLIGHT LOWER BRACKET RH ✓ | 1          | \$78.37             | ✓               | \$78.37         |
| <b>TOTAL:</b> |                 |                              |            |                     |                 | <b>\$348.21</b> |

**Total Labour & Parts**

**\$348.21**

Survey By

GUO XIANG