

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 25 Jun 2019

Preliminary Advice

Insured Vehicle No	: SDP42Y		
TP Vehicle No	: SHD6425C	Accident Date	: 19/05/2019
Make	: TOYOTA PRIUS TAXI	Assignment Date	: 22/05/2019
Date of Inspection	: Smrt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building Singapore 757047	Est. Duration of Repair	: 10 days
Inspection At	: 25/05/2019		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion, n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	76,328.84
Revised Amount	:S\$	19,966.57
Check Items (Estimated)	:S\$	44,867.52
Total	:S\$	64,834.09

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Book Value	:S\$	72,911.40
COE / PARF Rebate	:S\$	30,775.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,136.40

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP Repairer able to undertake the repair cost not exceeding \$ 42,000.00 on part by part basis.