

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 28 May 2019

Preliminary Advice

Insured Vehicle No	: SDX2326Z		
TP Vehicle No	: SJG7835G	Accident Date	: 17/05/2019
Make	: TOYOTA VIOS EA	Assignment Date	: 22/05/2019
Date of Inspection	: 23/05/2019	Est. Duration of Repair	: 7 days
Inspection At	: Sk Automobile Pte Ltd 8 Kaki Bukit Ave 4, #08-46 Premier @ Kaki Bukit Singapore 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,849.53
Revised Amount	:S\$	8,683.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,683.30

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.