

K/C

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLM 6655K
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No: ES1991567/YISHUN

Date: 28 May 2019

Policy No: 5088592353-02

Veh Reg No: SLM6655K

Make/Model: TOYOTA COROLLA
AXIO 1.5G CVT

Chassis No: NRE1610023403

Engine No: 2NR8697794

Reg. Date: 17/03/2017

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 21/05/2019

TP Veh Reg No: SFS5322S

Not Notified
Punary Bypain
4-5 days

\$ 3129.15

Estimate Repair Cost to Vehicle No :SLM6655K

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	598.50	1 PC	598.50	—
2 REAR BUMPER RH REFLECTOR	59.10	1 PC	59.10	—
3 REAR BUMPER SIDE RETAINER	96.20	1 PC	96.20	—
4 REAR BUMPER CLIPS	3.50	6 PCS	21.00	—
5 RH TAILLAMP	548.40	1 PC	548.40	—
6 REAR BOOT EMBLEM (G)	38.90	1 PC	38.90	—
7 RH TAILLAMP LOWER RETAINER	49.10	1 PC	49.10	—
8 RH TAILLAMP CLIP	4.80	1 PC	4.80	—
9 REAR BOOT	684.80	1 PC	684.80	—
10 REAR BOOT EMBLEM (COROLLA)	49.50	1 PC	49.50	—
11 REAR BOOT EMBLEM (AXIO)	51.50	1 PC	51.50	—
12 REAR BOOT LOGO	50.40	1 PC	50.40	—
13 REAR BOOT INNER LOCK	94.80	1 PC	94.80	X
14 REAR END PANEL	602.40	1 PC	602.40	X
15 REAR END PANEL INNER TOP GARNISH	218.20	1 PC	218.20	X
			3,167.60	
		Less 25%	791.90	2,375.70
Special Net				
16 REVERSE SENSOR	200.00	1 SET	200.00	200.00
Labour				
17 PANEL BEATING	700.00	1 LA	700.00	540
18 PUTTY & RESPRAY PAINTING	800.00	1 LA	800.00	700
19 RUSTPROOFING	60.00	1 LA	60.00	X
			1,560.00	1,560.00
			Total	S\$ 4,135.70
			Add GST @ 7%	289.50
			Total Amount Payable	S\$ 4,425.20

\$1689.15
\$200
\$1260
\$3149.15

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

COR -
Turb-CMC - 5x\$100
CMA - 8