

Hsiao Tong (LKKAuto)



From: Hsiao Tong (LKKAuto)
Sent: Sunday, 8 March 2020 3:01 PM
To: sinsheng engineering services
Cc: Admin A
Subject: <REJECTION> Acknowledgement Your ref : YP165C Our ref :S9M01O7H MC/RA
//LKK REF: CC4/ASM19009095/T1pb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We have reviewed the matter and we are of the view that BOLA 26 is applicable for this matter. Your client who is opening vehicle door should exercise more caution.

OPENING/ CLOSING OF VEHICLE DOOR (Anywhere)				
26.		Vehicle X – Driver / passenger opening/closing the vehicle door into path of other traffic – Driver / passenger inside / outside the vehicle Vehicle Y – Moving Reason: Driver should not obstruct / cause danger to passing vehicles	100%	0%
26. (a)	<u>For Car park</u> 	Vehicle X -Stationary - Opening / closing of any door in the car park and caused damages to adjacent parked vehicle Vehicle Y – Stationary/ Moving Reason: Driver of Vehicle X should exercise greater caution Applicable whether driver is inside or outside of vehicle	100%	0%

In view of the above, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sinsheng engineering services <sinsheng1981@gmail.com>

Sent: Thursday, 5 March 2020 12:31 PM

To: Admin A <admin-a@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: Acknowledgement Your ref : YP165C Our ref :S9M01O7H MC/RA

Hi Admin,

Kindly please update the status of claim.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You

Regards

Pei Jin

Sin Sheng Engineering Services

No 8 Tuas Ave 18

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

Tel: 6863 9595

Fax: 6863 6477

On Mon, 17 Feb 2020 at 12:49, sinsheng engineering services <sinsheng1981@gmail.com> wrote:

Hi Shu Pei,

Please be informed that we have email scene photos to you on dated 05/11/2019.

Can you please update us your liability / offer to us.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You

Regards

Pei Jin

*Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel: 6863 9595
Fax: 6863 6477*

On Wed, 11 Dec 2019 at 16:24, sinsheng engineeringservices <sinsheng1981@gmail.com> wrote:

Hi Shu Pei,

Please be informed that we have email scene photos to you on dated 05/11/2019.
Can you please update us your liability / offer to us.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

*Thank You
Regards*

Pei Jin

*Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel: 6863 9595
Fax: 6863 6477*

On Tue, 5 Nov 2019 at 15:46, sinsheng engineeringservices <sinsheng1981@gmail.com> wrote:

Hi Shu Pei,

Please find attached the scene photos.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

*Thank You
Regards*

Pei Jin


*Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)*

On Thu, 31 Oct 2019 at 08:58, Shu Pei (LKKAuto) <shupeil@lkkauto.com> wrote:

Dear Pei Jin,

Kindly refer to the below OI accident statement for your easy reference.

SKETCH PLAN



Vehicle
A - XE397T
B - YP165C

Legend
Vehicle (represented by a rectangle with a triangle) Lorry (represented by a rectangle with a circle)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/5/2019, Around 1:30pm. I came out from cargo Airport and stopped at the custom. I was reversing my truck into parking lot and go into a custom office to clear my permit. After done clear my permit, I prepare to go out from parking lot but I heard some sound while I move forward a bit. I then came out from my truck and realise a lorry B (YP165C) back door is open and hit onto ~~to~~ my truck chassis. I wish state that my truck is stationary on my lane and the lorry B's door open already out of his lane.

Thank you

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sinsheng engineerservices <sinsheng1981@gmail.com>

Sent: Wednesday, 30 October 2019 5:41 PM

To: SUR <sur@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Re: Acknowledgement Your ref : YP165C Our ref :S9M0107H MC/RA

Hi Hsiao Tong,

We would like to request your insurer's accident report. Thanks

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You

Regards

Pei Jin

Sin Sheng Engineering Services

No 8 Tuas Ave 18

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

Tel: 6863 9595

Fax: 6863 6477

