

ASS. REC. BY:

REF: CS/LPC/K009114/Jg d352

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Ong Li Li

of LPC

Date/Time: 23.5.19 4.22 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XD 8062 M

Insured:

at Workshop n/s LYS Engineering

Tel: 97308695

of 24 Sungei Kadut Street 4

Policy No:

Claim No: 18/19/19/VC10/021796

Sum Insured:

Excess: 1500

Make of Vch:
(Client's Record)

D.O.A. 13.5.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 23.5.2019 5.16 p.m

Person Contacted:

Steven

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	XD 8062 M - NA/IN (K008565/r3) DOA - 13/05/2019
28/5/19 @	3pm revert to Ong Li Li by email.
18/6/19 @	10.41am Ong Li Li informed that they will recommend total loss as they use MV, & 60K & some parts not available.
18/6/19	Submit Total Loss Report. (Uneconomical.)

(08/11/13)

ASS. REC. BY: Free JieREF LPC**ASSIGNMENT**From: _____ Date: 24.5.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: XD 8062mat Workshop m/s LYS Engineeringof 24 sungei kadui street 4

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: Sevin 97308695 morning After 10.00

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: bon

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: XD8062m Yr Regn: 18 Nov 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer orMake: UD Trucks C.C. 10837Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 336795 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GKB5E00159Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SR / STD A/Rim orTyre Size: F: 295/80R22.5

R: _____

BS / DUN / EXNOVA / GYLFS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7/7 mmL/Bal. 7 mmL/Bal. 7/7 mm

D.O.A. _____

D.O.I. 24/5/19Survey held at LYSDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction

Do not that this workshop has agreed to use OEM (non-original) parts to save repair costs.

bon
MV - \$65000

PV - \$24835

NV - \$40165 35165

RECEIVED 18 JUN 2019

Date/Time, File Pass to?

☐ : Preli. Report1) 18/6 10.00☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 350

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : OD / TL / U

Lump Sum / I.B.I. (\$) _____

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 23 May 2019 4:22 PM
To: assignments@lkkauto.com; 'SUR' (sur@lkkauto.com)
Cc: MT_Claim_SG
Subject: OD CLAIM XD8062M (13/5/19) Our Ref: 18/19/19/VC10/021796 [External General]
Attachments: 21796 OD REPAIR ESTIMATE.pdf

Lonpac External - General

Dear Sir/Mdm

Please arrange OD survey (non-merimen case)

Do note that this workshop has agreed to use OEM (non-original) parts to save repair costs.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

Shiau Chan (LKKAuto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 18 June 2019 10:46 AM
To: Shiau Chan (LKKAuto); assignments; SUR
Cc: MT_Claim_SG
Subject: RE: OD CLAIM XD8062M (13/5/19) Our Ref: 18/19/19/VC10/021796 [External General]
Attachments: CCF_20190617_175035_009068.tif

Lonpac External - General


Dear Shiau Chan

From our research, MV is about \$60k and we understand that some parts may not be available.

Based on your surveyor's marking, our authorised workshop has estimated the cost of repair to be at \$38k.

Therefore, please submit your report and close file at your end.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.


From: ONG LI LI
Sent: Friday, 7 June, 2019 3:48 PM
To: 'Shiau Chan (LKKAuto)'; assignments; SUR
Cc: MT_Claim_SG
Subject: RE: OD CLAIM XD8062M (13/5/19) Our Ref: 18/19/19/VC10/021796 [External General]

Lonpac External - General

Dear Shiau Chan

Please kiv file until next week.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Friday, 7 June, 2019 3:44 PM
To: ONG LI LI; assignments; SUR
Cc: MT_Claim_SG
Subject: RE: OD CLAIM XD8062M (13/5/19) Our Ref: 18/19/19/VC10/021796 [External General]

Dear Ms Ong,

Any status of authorisation?

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 27 May 2019 5:31 PM
To: ONG LI LI <long@lonpac.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: OD CLAIM XD8062M (13/5/19) Our Ref: 18/19/19/VC10/021796 [External General]

Dear Ms Ong,

As per your requested.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 27 May 2019 4:03 PM
To: ONG LI LI <long@lonpac.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: OD CLAIM XD8062M (13/5/19) Our Ref: 18/19/19/VC10/021796 [External General]

Dear Ms Ong,

As spoken with youL

The estimate amount of Lump Sum repair is \$31,700.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI <long@lonpac.com>
Sent: Monday, 27 May 2019 3:03 PM

MAILING ADD: 65 CHESTNUT AVE #18-15 S 01/9024

To be continued 1. 1

WORKSHOP: 24 SUNGEEI KADUT ST 45 (729050)

FAX: 66748965 HP: 97308695 Email: lys88@yahoo.com.sg

Specialise In M/V Accident Claims, ROV Inspection & General

Insurance Agents Email: Lys88@yahoo.com.sg

Date: 23/05/2019

LON PAC INSURANCE BHD

300 Beach Road

#17-04/07

The Concourse

S 19555

Attn: M/V Claim Department

Fax: 62962767

Tel: 67507388 Fax: 62962706

ACCIDENT OF M/V XD8062M and YN648C on 13/05/2019 Accident
(OD CLAIM ON BEHALF OF M/V XD8062M OWNER)

We hereby wrote to inform you that we would like to claim against
M/V XD8062M own damage windscreen glass insurance claim.

Attached herewith all the necessary documents for your reference.

If you have any queries, please do not hesitate to call Mr Steven Loo
at Handphone 97308695.

Any inconvenience in this matter is much regretted.

Thank you.

Yours faithfully,

LYS ENGINEERING

Steven Loo

18/19/19/VC10/021796

LYS ENGINEERING

MAILING ADD: 65 CHESTNUT AVE #18-15 S 679524

WORKSHOP: 24 SUNGEI KADUT ST 4 S (729050)

FAX: 66748965 HP: 97308695 Email: lys88@yahoo.com.sg

Specialise In M/V Accident Claims, ROV Inspection & General

Insurance Agenrs Email: Lys88@yahoo.com.sg

Date: 23/05/2019

LONPAC INSURANCE BHD

300 Beach Road

#17-04/07

The Concourse

ST 9555

Attn: M/V Claim Department

Fax: 62962767

Tel: 62507388 Fax: 62962706

ACCIDENT OF M/V XD8062M and YN648C on 13/05/2019 Accident
(OD CLAIM ON BEHALF OF M/V XD8062M OWNER)

We hereby wrote to inform you that we would like to claim against
M/V XD8062M own damage windscreen glass insurance claim.

Attached herewith all the necessary documents for your reference.

If you have any queries, please do not hesitate to call Mr Steven Loo
at Handphone 97308695.

Any inconvenience in this matter is much regretted.

Thank you.

Yours faithfully,

LYS ENGINEERING

.....Steven Loo.....

**LONPAC INSURANCE BHD** (S98FC5635C)

(Incorporated in Malaysia)

Singapore Office: 300, Beach Road #17-04/07, The Concourse, Singapore 199555.

Tel: (65) 6250 7388 Fax: (65) 6296 3767 Website: www.lonpac.com.sg

GST Reg No.: F0-0005635-C

THE SCHEDULE*Insured's Copy*

Class of Policy : COMMERCIAL VEHICLE

Policy No. : Z/18/VC10/102563

Insured : SAB LOGISTICS PTE LTD

Type of Cover : COMPREHENSIVE

Address : 1 JALAN SAMULUM
SINGAPORE 629119

Replacing CN/Policy No. : Z/17/VC10/100820

Account No : Z10475 L/A

Business or Profession : TRANSPORTATION (CHAIN MGMT)

Period Of Insurance

(a) From 18/11/2018 To 17/11/2019 (both dates inclusive)

(b) Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium.

H.P. Owner : MAYBANK

Description of Vehicle**The Policy's Premium**

Vehicle/Trailer Regn. No. : XD 8062M

Premium : S\$ 4,700.00

Make & Model of Vehicle : UD TRUCKS GKB5ELDHNT

NCD 20.00 % : S\$ (940.00)

Type of Body : PRIME MOVER

Gross Premium : S\$ 3,760.00

Engine No. : GH11715367

Goods & Services Tax 7 % : S\$ 263.20

Chassis No. : GKB5E00159

Total Premium : S\$ 4,023.20

Year of Registration : 2013

c.c./Tonnage : 48.00


Seating Capacity : 02

Sum Insured : MARKET VALUE

Excess : S\$1500.00 (SECTION 1)
 S\$2500.00 (SECTION 1) ADDITIONAL EXCESS FOR YOUNG
 AND/OR INEXPERIENCED DRIVERS
 S\$200.00 WINDSCREEN EXCESS (EXCESS WILL BE DOUBLED
 ON 2ND AND SUBSEQUENT CLAIMS)

Condition : ACCIDENT REPAIRS AT LONPAC'S AUTHORISED WORKSHOPS

Named Drivers : 1. ALL AUTHORISED DRIVERS



LONPAC INSURANCE BHD

(S98FC5635C)

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MZ301/312

MOTOR VEHICLES (THIRD PARTY AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No. **Z/18/VC10/102563** CI No. **18107910**

Excess : AS STATED IN POLICY SCHEDULE.

1. Index Mark and Registration **UD-TRUCK PRIMEMOVER**
Number of Vehicle / Chassis **XD 8062M / GKB5E00159**
2. Name of Policy Holder **SAB LOGISTICS PTE LTD**
3. Period of Insurance **18/11/2018 To 17/11/2019 (Midnight)**
4. Persons or Classes of Persons entitled to drive*
ANY PERSON PROVIDED HE IS IN THE POLICYHOLDER'S EMPLOY AND IS DRIVING ON THEIR ORDER OR WITH THEIR PERMISSION

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle and provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

5. Limitations as to use*
USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS
USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD) IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS
USE FOR SOCIAL DOMESTIC AND PLEASURE PURPOSES
THE POLICY DOES NOT COVER:-
USE FOR RACING PACEMAKING RELIABILITY TRIAL OR SPEED TESTING
USE WHILST DRAWING A GREATER NUMBER OF TRAILERS IN ALL THAN IS PERMITTED BY LAW
USE FOR THE CARRIAGE OF PASSENGERS FOR HIRE OR REWARD

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

HP Co. : MAYBANK (COVER: COMPREHENSIVE)

LONPAC INSURANCE BHD



Authorised Signatory

PENSLEY ALLIANCE PTE LTD/ALYC
TEL: 65326722

Serial No: 201442

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 27 May 2019 3:00 PM
To: 'ONG LI LI'; assignments; SUR
Cc: 'MT_Claim_SG'
Subject: RE: OD CLAIM XD8062M (13/5/19) Our Ref: 18/19/19/VC10/021796 [External General]
Attachments: CSLPC19009114Jqd3.pdf; XD8062 EST.pdf

Dear Ms Ong,

Enclosed herewith preliminary advice of XD 8062M.
The vehicle repair on Lump Sum basis.

We have not authorise repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 23 May 2019 5:15 PM
To: 'ONG LI LI' <llong@lonpac.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>
Subject: RE: OD CLAIM XD8062M (13/5/19) Our Ref: 18/19/19/VC10/021796 [External General]

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed that repairer agreed to survey on 24/5/2019.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]
Sent: Thursday, 23 May, 2019 4:22 PM
To: assignments@lkkauto.com; 'SUR' (sur@lkkauto.com) <sur@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: OD CLAIM XD8062M (13/5/19) Our Ref: 18/19/19/VC10/021796 [External General]

Lonpac External - General

Dear Sir/Mdm

Please arrange OD survey (non-merimen case)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 18/19/19/VP10/021796

Date: 27th May 2019

Our Ref: CS/LPC19009114/Jqd3

The Motor Claims Department
Lonpac Insurance Bhd

Attn: Ong Li Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. XD 8062M

We thank you for the instruction on 23/05/2019.


Please be informed that we had conducted the inspection of the abovementioned vehicle on 24/05/2019 at the premises of M/s LYS ENGINEERING and have the following to report:-

Workshop Estimate Amount	: S\$ 46,452.50 .
Revised Estimate Amount	: S\$ 20,766.50 .
"Check" Items Amount	: S\$ 18,887.00 .
Market Value	: S\$ 65,000.00 .
LTA Reimbursement Value	: S\$ 24,835.00 .
Nett Value	: S\$ 40,165.00 .

39653.80

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

The vehicle repair on Lump Sum basis.

We have not authorised the repairs.

Yours faithfully

Hwee Jie
Automobile Assessor

Enquire Vehicle Registration Details

Vehicle Registration Detail Information

Owner Particulars

NRIC/Passport/Company Cert No.: 200403878N
 Owner ID Type: Company
 Owner Name: SAB LOGISTICS PTE. LTD.
 Registered Address: 1 JALAN SAMULUN SINGAPORE 629119
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: XD8062M
 Previous Vehicle No.: -
 Effective Date of Ownership: 18 Nov 2013
 Original Regn Date: 18 Nov 2013
 Registration Date: 18 Nov 2013
 Year of Manufacture: 2013
 Vehicle Type: Goods (Open) Prime Mover
 Vehicle Scheme: -
 Vehicle Attachment 1: No Attachment
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: UD TRUCKS
 Vehicle Model: GKB5ELDHNT
 Primary Colour: White
 Secondary Colour: -
 Passenger Capacity: 2
 Chassis No.: GKB5E00159
 Engine No.: GH11715367
 Engine Capacity / Power Rating: 10837 cc / -
 Maximum Power Output: -
 Propellant: Diesel
 Max Unladen Weight: 6980 kg
 Maximum Laden Weight: 55000 kg
 Open Market Value: \$81,118.00
 PARF Eligibility: No
 PARF Eligibility Expiry Date: -
 Minimum PARF Benefit: -
 No. of Transfers: 0
 IU Label No.: 2010459821
 COE No.: 2013120105000021N
 COE Expiry Date: 17 Nov 2023
 COE Category: C - Goods Vehicle & Bus
 COE Registration Category: C - Goods Vehicle & Bus
 Quota Premium (QP) / Prevailing Quota Premium: \$55,503.00 / -
 Actual QP Paid: \$55,503.00
 QP (Regn Cat): \$55,503.00
 OPC Cash Rebate Eligibility: No
 QP during COE Bidding Exercise: \$55,503.00
 Additional Registration Fee Rate: 5.00 %
 Actual ARF Paid: \$4,056.00
 Vehicle Lifespan Expiry Date: 17 Nov 2033
 CO2 Emission: -
 CO Emission: -
 HC Emission: -
 NOx Emission: -
 PM Emission: -
 Message: -

Print

OK

Save as PDF

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Company

3878N

Vehicle Details

Vehicle No.:

XD8062M

Vehicle to be Exported:

No

Intended Deregistration Date:

27 May 2019

Vehicle Make:

UD TRUCKS

Vehicle Model:

GKB5ELDHNT

Primary Colour:

White

Manufacturing Year:

2013

Engine No.:

GH11715367

Chassis No.:

GKB5E00159

Maximum Power Output:

-

Open Market Value:

\$81,118.00

Original Registration Date:

18 Nov 2013

First Registration Date:

18 Nov 2013

Transfer Count:

0

Actual ARF Paid:

\$4,056.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

17 Nov 2023

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$55,503.00

COE Rebate Amount:

\$24,835.00

Total Rebate Amount:

\$24,835.00

The information contained herein is correct as at 27 May 2019

OK

QUOTATION

Mailing Address:

65 Chestnut Ave #18-15, Singapore 679524
Tel: 6674 8965 Fax: 6674 8965 Hp: 9730 8695
Email: lys88@yahoo.com.sg

LYS ENGINEERING

Specialise in Motor Repairing, Welding, Panel Beating, Spray Painting, Side Guide, Accident Claims, General Insurance Agents, ROV Inspection, Insurance Claim.

MS CONFAC INSURANCE BHD
XD8062M

No: 1242

Terms: Cash/30 days

Date: 23/05/2018

B Reg. 48754100J

Quantity	Description	Unit Price \$ cts		Amount \$ cts	
CRA / 1pc	Front Windscreen Glass	380	00	380	00
NEC / 1pc	Front Windscreen rubber	350	00	350	00
BUC / 1pc	Front Big panel	580	00	580	00
BT / 1pc	Front W/WPR ARIM Assy	120	00	360	00
BT / 1pc	Front W/WPR BLADE Assy	35	00	105	00
CRA / 1pc	Front right side panel GRIP Hand	220	00	220	00
MIS / 1pc	Front grille Top	298	00	298	00
CRA / 1pc	Front grille Lower	285	00	285	00
MIS / 1pc	Front Logo (Mark) (Big)	120	00	120	00
MIS / 1pc	Front NISSAN DIESEL Emblem	60	00	60	00
BUC / 1pc	Front Bumper center	395	00	395	00
BUC / 1pc	Front Bumper left side	295	00	295	00
MIS / 3pc	Front Bumper Top Garish step	48	00	144	00
CRA / 1pc	Front left side corner panel	198	00	198	00
BUC / 1pc	Front Bumper inner Reinforcement Bracket	895	00	895	00
NEC / 5pc	Front Bumper Corner cover clips	6	50	32	50
MIS / 2pc	Front Bumper left side end cap cover	160	00	320	00
BT / 1pc	REAR CAB MOUNTING BRIDGE	650	00	650	00
CRA / 1pc	Front left side Fog lamp	180	00	180	00

Invoices not paid within 30 days of date, interest at the rate of 1.5% interest per month will be carry out until settled.
All cheques should be crossed & made payable to "LYS ENGINEERING".

5869.50

LYS ENGINEERING

Customer's Signature & Official Stamp

E. & O. E.

For LYS ENGINEERING

QUOTATION

Mailing Address:

65 Chestnut Ave #18-15, Singapore 679524
Tel: 6674 8965 Fax: 6674 8965 Hp: 9730 8695
Email: lys88@yahoo.com.sg

LYS ENGINEERING

Specialise in Motor Repairing, Welding, Panel Beating, Spray Painting, Side Guide, Accident Claims, General Insurance Agents, ROV Inspection, Insurance Claim.

M/S

COMPAC INSURANCE BHD
XD 8062M

No:

1243

Terms:

Cash/30 days

Date:

23/05/2019

B Reg. 48754100J

Quantity	Description	Unit Price \$ cts	Amount \$ cts
1pc	Front Left Side Signal Lamp	120.00	120.00
1pc	Front Bumper Left Side Garnish Cover	42.00	42.00
1pc	Front Left Side Head Lamp	280.00	280.00
1pc	Front Left Side Door Assy.	980.00	980.00
1pc	Front Left Side Lower Step	68.00	68.00
1pc	Front Left Side Lower Step Reflector	80.00	80.00
1pc	Front Left Side Upper Step	75.00	75.00
1pc	Front Left Upper Step Lower Fender	198.00	198.00
1pc	Front Left Upper Lower Fender Black Cover	40.00	40.00
1pc	Front Left Side Upper Fender Shield	180.00	180.00
1pc	Front Left Side Step Lower Big Y Bracket Support	450.00	450.00
1pc	Front Left Side Oil Cooler	450.00	450.00
1pc	Front Left Side Oil Cooler Bracket	85.00	85.00
2pc	Front Left Oil Cooler Oil Pipe	80.00	160.00
1pc	Front Left Oil Cooler Filter	35.00	35.00
1pc	Front Left Oil Cooler Bracket	48.00	48.00
1pc	Front Left Side Bumper Top Inner Black Cover Shield	85.00	85.00
1pc	Front Panel Cylinder Up Lower	1200.00	1200.00

as not paid within 30 days of date, interest at the
1.5% interest per month will be carry out until settled.
ques should be crossed & made payable to
ENGINEERING

Invoices not paid within 30 days of date, interest at the rate of 1.5% interest per month will be carry out until settled.
All cheques should be crossed & made payable to "LYS ENGINEERING".

Owner's Signature & Official Stamp

E. & O. E.

For LYS ENGINEERING

QUOTATION

LYS ENGINEERING

Mailing Address:

65 Chestnut Ave #18-15, Singapore 679524

Tel: 6674 8965 Fax: 6674 8965 Hp: 9730 8695

Email: lys88@yahoo.com.sg

Specialise in Motor Repairing, Welding, Panel Beating, Spray Painting, Side Guide, Accident Claims, General Insurance Agents, ROV Inspection, Insurance Claim.

M/S <u>L ON PAC INSURANCE BHD</u>		No: <u>1244</u>	
<u>XD 8062 M</u>		Terms: <u>Cash/30 days</u>	
B Reg. 48754100J		Date: <u>23/05/2019</u>	
Quantity	Description	Unit Price \$ cts	Amount \$ cts
1pc	Front Wiper Water Tank.	398.00	398.00
1pc	Front Wiper Water Tank motor.	120.00	120.00
1pc	Front inner (center panel) Lock Bracket.	145.00	145.00
2pc	Front left & right side Cabin Spring A/V Bolt	398.00	796.00
8pc	Front stabilizer bar bush. (upper & lower)	39.00	312.00
2pc	Front left & right side cabin Shock absorber	145.00	290.00
1pc	Front left Cabin wiring Box	180.00	180.00
1set	Front left Cabin wiring	300.00	300.00
1pc	Front left Top up Engine Oil Pipe	250.00	250.00
1pc	Front left oil pipe cover	38.00	38.00
1pc	Front left shock absorber Bracket	180.00	180.00
2pc	Front left Air con pipes	98.00	196.00
2pc	Front panel inner Lock Bracket	125.00	250.00
1set	Front W/WPR LINK ASSY.	380.00	380.00
1pc	Front W/WPR MOTOR	450.00	450.00
1pc	Front panel LATCH STRIKER	48.00	48.00

Amounts not paid within 30 days of date, interest at the rate of 1.5% interest per month will be carry out until settled. Cheques should be crossed & made payable to L ON PAC INSURANCE BHD

Invoices not paid within 30 days of date, interest at the rate of 1.5% interest per month will be carry out until settled. All cheques should be crossed & made payable to "LYS ENGINEERING".

4333

LYS ENGINEERING

Owner's Signature & Official Stamp

E. & O. E.

For LYS ENGINEERING

4

QUOTATION

Mailing Address:
65 Chestnut Ave #18-15, Singapore 679524
Tel: 6674 8965 Fax: 6674 8965 Hp: 9730 8695
Email: lys88@yahoo.com.sg

LYS ENGINEERING

Specialise in Motor Repairing, Welding, Panel Beating, Spray Painting, Side Guide, Accident Claims, General Insurance Agents, ROV Inspection, Insurance Claim.

M/S CONPAC INSURANCE BHD No: 1245
XD8602M
B Reg. 48754100J Terms: Cash/30 days
Date: 23/05/2019

1
?
?
?
DEF
BT
?
?
BUL
?
?
?
?
?
?
?
?
?
?
?
?
?
?

Quantity	Description	Unit Price		Amount	
		\$	cts	\$	cts
1pc	Front panel fable	140	00	140	00
1pc	Front Gearshift Lever Cable	298	00	298	00
1set	Front CAB TILT Cylinder UNK Assy	1280	00	1280	00
1pc	Front Left side mud cover	200	00	200	00
1set	Front CAB SUS CAB MTH LINK Assy	950	00	950	00
2pcs	Front Left & right CAB HINGE inner Bracket	480	00	960	00
1pc	Front CAB TORSION BAR	950	00	950	00
1pc	Front inner Big Air Intel Cooler	4800	00	4800	00
1pc	Front Radiator Assy	4500	00	4500	00
1set	Front Radiator Fan Cooling Shroud	895	00	895	00
1pc	Front Radiator Cooling Fan & Clutch	1300	00	1300	00
1pc	Front G/SHF CONT LINKAGE ROD	220	00	220	00
1pc	Front INSTRUMENT PANEL Assy	950	00	950	00
1pc	Front INSTRUMENT LWR Left	180	00	180	00
1pc	Front Center inner Air Ion Heater Assy	980	00	980	00
1pc	Front inner Air Ion Blower Assy	1200	00	1200	00
1pc	Front inner Air Ion Blower motor	480	00	480	00
1pc	Front inner Air-Ion Joint Duct	220	00	220	00
1pc	Front W/SHLD LWR panel	480	00	480	00

Invoices not paid within 30 days of date, interest at the rate of 1.5% interest per month will be carry out until settled. All cheques should be crossed & made payable to "LYS ENGINEERING".

20033

Customer's Signature & Official Stamp

E. & O. E.

LYS ENGINEERING

For LYS ENGINEERING

5

QUOTATION

Mailing Address:

65 Chestnut Ave #18-15, Singapore 679524

Tel: 6674 8965 Fax: 6674 8965 Hp: 9730 8695

Email: lys88@yahoo.com.sg

LYS ENGINEERING

Specialise in Motor Repairing, Welding, Panel Beating, Spray Painting, Side Guide, Accident Claims, General Insurance Agents, ROV Inspection, Insurance Claim.

M/S

CONPAC INSURANCE BHD
XD 8602M

No:

1246

Terms:

Cash/30 days

Date:

23/05/2019

B Reg. 48754100J

Quantity	Description	Unit Price \$ cts	Amount \$ cts
1pc	Front DASH PANEL TOP REFINE	380.00	380.00
1pc	Rear CAB MOUNTING BRIDGE	498.00	498.00
2pc	Rear Left right CAB HOLD-DOWN Bottom Bracket	180.00	360.00
1set	Rear CAB HOLD-DOWN MAIN Hook Assy.	480.00	480.00
2pc	Rear CAB Left right side Cabin Spring Air Boli	260.00	520.00
1pc	Rear Left Air CLEANER LWR DUCT	450.00	450.00
1pc	Front Left Side Door Assy	950.00	950.00
-	To Refill Air - Lin Gas	50.00	50.00
-	To Writing Front to Logo	80.00	80.00
-	To Provide Towing Service charge	150.00	150.00
-	To Disconnect & Reconnect Front Cabin Electrical Wiring Harness Wires - sockets & replaced Damaged Parts.		200.00

Invoices not paid within 30 days of date, interest at the rate of 1.5% interest per month will be carry out until settled. All cheques should be crossed & made payable to "LYS ENGINEERING".

2670

Owner's Signature & Official Stamp

E. & O. E.

LYS ENGINEERING

For LYS ENGINEERING

6

QUOTATION

Mailing Address:

65 Chestnut Ave #18-15, Singapore 679524
 Tel: 6674 8965 Fax: 6674 8965 Hp: 9730 8695
 Email: lys88@yahoo.com.sg

LYS ENGINEERING

Specialise in Motor Repairing, Welding, Panel
 Beating, Spray Painting, Side Guide, Accident
 Claims, General Insurance Agents, ROV
 Inspection, Insurance Claim.

M/S

COMPAC INSURANCE BHD
XD8062M

No:

1247

Terms:

Cash/30 days

Date:

23/05/2019

B Reg. 48754100J

Quantity	Description	Unit Price \$ cts	Amount \$ cts
-	To Remove & Replace Front Air-con system Air-con Blower Assy & Air- con Heater Assy		480 00
-	To Spray painting whole inner & outer Cabin & lower Base Chassis Frame.		1500 00 1000
	Labour charges		
-	To Remove & Replace the above Damaged Parts. Straighten & Knock out Realign And Repair Including cut panel & to Realign to the original position Using Power Tools.		4500 00 2200
-	To Repair & Align the Front Chassis Frame.		

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting

Invoices not paid within 30 days of date, interest at the
 rate of 1.5% interest per month will be carry out until settled.
 All cheques should be crossed & made payable to

LYS ENGINEERING

- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Owner's Signature & Official Stamp

Hue Jie-Lkk

24/5/19

L/S 12 days

Not Authorise

E.&O.E.

Excess : TBA

Total: 46,452-50

6480

44054.50

LYS ENGINEERINGFor **LYS ENGINEERING**