


SMRT Accident Vehicle Repair Estimates


Final estimate

SMRT Automotive Services Pte Ltd
90 Weedlands Industrial Park E4, Singapore 757705
FAX Number: 93085592
Estimator Telephonio Number: 98692023
Accident Reporting Number: 98852672

Date Generated : 21/11/2019 User ID : PehSuan

Registration Number	SHB5515T	
Case Reference Number	TAX/05/19/2053	
Registration Date	12/10/2017	
Company Type	SMRT Taxis Pte Ltd	
Make	тоуота	
Model	PRIUS4	
Name of Driver	GOH KWAN ENG	
Type of Accident	Head To Side	
Accident Date and Time	11/5/2019 4:00 PM	
Accident Reported Date and Time	13/5/2019 10:13 AM	
Is Surveyor Required?	Yes	
Survey by		
Vehicle is Towed Back?	No	
Towed Back Date and Time	11/5/2019 4:01 PM	
Replacement Vehicle issued?	No	
Job Card Number	24101476	
Special Instruction to ARC, if any	y TOWED BACK FROM TP COMPOUND \$90	
Prepared Date and Time	16/5/2019 8:27 AM	
Chassis Number		
Mileage		
Work Shop		
Repair Completion Date and Time		





kytaka

Summary of Repair Estimates			
	Quotation from ARC	Adjusted by Surveyor, if applicable	
Total Labour Cost	\$3,559.00	\$1,700.00	
Total Spray Cost	\$3,150.00	\$1,200.00	
Total Spare Part Cost	\$71,978.94	\$39,233.80	
Total Other Cost	\$3,176.00	\$1,210.00	
TOTAL COST	\$81,863.94	\$43,343.80 (P/P)	
Lump Sum Total	\$0.00	\$0.00	
Number of Repair Days	18.0	11.0	
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / China Taiping	
ARC / Surveyor Sign Off Date	17/05/2019 4:13 PM	17/05/2019 3:41 PM	
Signature	a.	J	
Remarks	,		



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Weedlands Industrial Park E4, Singapore 757705 FAX Number : 63665592 Estimator Telephone Number : 68662623 Accident Reporting Number : 68652672

Oate Generated : 21/11/2019 User(D : PohSuan

		tion and Accident Invoice Details	
Quotation Number	QN-1911-0367	Invoice Number	
Quotation Date	22.11.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section	on D - Details of Repair Estimates	
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR APRON PANEL LH	\$200.00	\$100.00 (540)
TO REMOVE & REFIT FRONT PORTION PARTS	\$1,500.00	\$600.00 (544)
TO REPAIR FRONT PORTION	\$1,859.00	\$1,000.00
Total Labour	\$3,559.00	\$1,700.00

Job Scope	Quotation from ARC	16 (C. 16) A C.
TO RESPRAY APRON PANEL LH	\$180.00	applicable \$100.00
O REPSRAY FRONT BUMPER	\$378.00	\$200,00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$100.00
TO RESPRAY FRT MEMBER,RH	\$180.00	\$0.00
TO RESPRAY FRT MEMBER,LH	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY APRON PANEL RH	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
O RESPRAY APRON PANEL LH	\$180.00	\$0.00
O RESPRAY FRONT PILLAR LH	\$180,00	\$0.00
O RESPRAY FRONT DOOR LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$3,150.00	\$1,200.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX AIR BAG SYSTEM	\$250.00	\$120.00 (Supp)
TOWING CHARGE	\$126.00	\$90.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$50.00
O DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00 .
TO TOP UP A/C GAS	\$120.00	\$50.00
O REMOVE / REFIT SEAT	\$240.00	\$50.00
O REMOVE / REFIT WINDSCREEN	\$120.00	\$100.00
O ALIGN CHASSIS	\$350.00	\$0.00
O PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$450.00	\$450,00
O CHECK & RESET SYSTEM FUNCTION	\$350.00	\$120.00
O REMOVE & REFIT ROOF LINING	\$120.00	\$80.00