

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 88662672

Date Generated : 21/11/2019

User ID : PohSuan

5328947072	COVER, RADIATOR	0.00	\$227.80	0.00	\$0.00	Replace	Check	X
5320547900	SUPPORT S/A UPPER	1.00	\$364.90	25.00	\$273.68	Replace	Replace	
5302847010	SUPPORT SUB-ASSY LOWER	0.00	\$397.40	0.00	\$0.00	Replace	Check	X
5320347901	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X
5320247901	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X
5321747030	BRACE, HOOD LOCK SUPPORT	0.00	\$76.20	0.00	\$0.00	Replace	Check	X
5321447050	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Check	X
5321347050	SUPPORT, RADIATOR UPPER RH	0.00	\$76.70	0.00	\$0.00	Replace	Check	X
8118547691	UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	
8114547691	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	
8105647690	COMPUTER SUBASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X
8101647690	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X
8651047050	HORN ASSY, HIGH	0.00	\$112.80	0.00	\$0.00	Replace	Check	X
8652047030	HORN ASSY, LOW	0.00	\$112.80	0.00	\$0.00	Replace	Check	X
8846010320	AIR CON CONDENSER ASSY	0.00	\$1,317.70	0.00	\$0.00	Replace	Check	X
8871047160	TUBE & ACCESSORY	0.00	\$574.40	0.00	\$0.00	Replace	Check	X
8870347080	HOSE SUB-ASSY, DISCHARGE	0.00	\$337.10	0.00	\$0.00	Replace	Check	X
	COOLANT	0.00	\$12.30	0.00	\$0.00	Replace	Check	X
1659237020	GUIDE, RADIATOR AIR	0.00	\$93.90	0.00	\$0.00	Replace	Check	X
1659437010	GUIDE, RADIATOR AIR, UPPER	0.00	\$44.70	0.00	\$0.00	Replace	Check	X
1659537050	GUIDE, RADIATOR AIR, LH	0.00	\$58.80	0.00	\$0.00	Replace	Check	X
1659337040	GUIDE, RADIATOR AIR, RH	0.00	\$54.60	0.00	\$0.00	Replace	Check	X
1640037310	RADIATOR ASSY	0.00	\$1,841.10	0.00	\$0.00	Replace	Check	X
9048040021	GROMMET (FOR RADIATOR LOWER	0.00	\$12.70	0.00	\$0.00	Replace	Check	X
1652337010	CUSHION, (FOR RADIATOR UPPER SUPPORT)	0.00	\$9.80	0.00	\$0.00	Replace	Check	X
1636137060	FAN RADIATOR, LH	0.00	\$181.80	0.00	\$0.00	Replace	Check	X
1636137070	FAN RADIATOR, RH	0.00	\$233.00	0.00	\$0.00	Replace	Check	X
1671137160	FAN SHROUD RADIATOR	0.00	\$219.30	0.00	\$0.00	Replace	Check	X
1636337060	MOTOR, COOLING FAN, LH	0.00	\$543.50	0.00	\$0.00	Replace	Check	X
1636336160	MOTOR, COOLING FAN, RH	0.00	\$443.40	0.00	\$0.00	Replace	Check	X
1657137210	HOSE, RADIATOR, NO.1	0.00	\$42.60	0.00	\$0.00	Replace	Check	X
1657237210	HOSE, RADIATOR, NO.2	0.00	\$40.20	0.00	\$0.00	Replace	Check	X
164A237012	TANK, RESERVE SEALED W/O CAP	0.00	\$127.00	0.00	\$0.00	Replace	Check	X
1626137150	HOSE, WATER BYPASS, NO.1	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
1626437120	HOSE, WATER BYPASS, NO.2	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
1626737090	HOSE, WATER BYPASS, NO.3	0.00	\$20.10	0.00	\$0.00	Replace	Check	X
1628137100	HOSE, WATER BYPASS, NO.4	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
1629637010	HOSE, WATER BYPASS, NO.8	0.00	\$37.90	0.00	\$0.00	Replace	Check	X
1626837100	PIPE, WATER BYPASS, NO.1	0.00	\$11.00	0.00	\$0.00	Replace	Check	X
1626837120	PIPE, WATER BYPASS, NO.2	0.00	\$11.00	0.00	\$0.00	Replace	Check	X
1627937020	PIPE, WATER BYPASS, NO.3	0.00	\$56.40	0.00	\$0.00	Replace	Check	X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/11/2019

User ID : PohSuan

16577370 90	PIPE, RADIATOR	0.00	\$32.90	0.00	\$0.00	Replace	Check	X
16573370 20	HOSE, RADIATOR , NO.3	0.00	\$29.60	0.00	\$0.00	Replace	Check	X
16282370 90	HOSE, WATER BYPASS, NO.5	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
16278370 20	PIPE, WATER BYPASS, NO.5	0.00	\$51.80	0.00	\$0.00	Replace	Check	X
16283370 21	HOSE, WATER BYPASS, NO.6	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
G904047 040	INVERTER WATER PUMP ASSY	0.00	\$432.00	0.00	\$0.00	Replace	Check	X
G922E47 010	HOSE, HV WATER PUMP INLET	0.00	\$37.90	0.00	\$0.00	Replace	Check	X
G922F47 010	HOSE, HV WATER PUMP OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check	X
G91H047 011	TANK ASSY, INVERTER RESERVE	0.00	\$371.30	0.00	\$0.00	Replace	Check	X
G922A47 010	HOSE, INVERTER COOLING INLET	0.00	\$43.10	0.00	\$0.00	Replace	Check	X
G922C47 010	HOSE, INVERTER COOLING OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check	X
G922H47 010	HOSE, INVERTER RADIATOR INLET	0.00	\$40.70	0.00	\$0.00	Replace	Check	X
G125A47 010	COOLER, MOTOR COOLING	0.00	\$249.10	0.00	\$0.00	Replace	Check	X
821H247 010	WIRE, AIR CONDITIONER	0.00	\$445.70	0.00	\$0.00	Replace	Check	X
8211147J 21	WIRE, ENGINE ROOM MAIN	0.00	\$6,138.00	0.00	\$0.00	Replace	Check	X
28800371 30	BATTERY	0.00	\$1,584.90	0.00	\$0.00	Replace	Check	X
74404470 30	CLAMP SUB-ASSY, BATTERY	0.00	\$41.40	0.00	\$0.00	Replace	Check	X
74482470 10	CLAMP, BATTERY, NO.2	0.00	\$43.30	0.00	\$0.00	Replace	Check	X
82621470 20	COVER, FUSIBLE LINK	0.00	\$28.30	0.00	\$0.00	Replace	Check	X
82620470 90	BLOCK ASSY, FUSIBLE LINK	0.00	\$99.80	0.00	\$0.00	Replace	Check	X
82671470 40	BLOCK, JUNCTION	0.00	\$15.80	0.00	\$0.00	Replace	Check	X
28850370 70	SENSOR ASSY, BATTERY STATE	0.00	\$256.80	0.00	\$0.00	Replace	Check	X
28859370 30	HOLDER, BATTERY CURRENT SENSOR	0.00	\$11.70	0.00	\$0.00	Replace	Check	X
17751371 10	INLET, AIR CLEANER, NO 1	0.00	\$130.50	0.00	\$0.00	Replace	Check	X
17752371 21	INLET, AIR CLEANER, NO 2	0.00	\$93.90	0.00	\$0.00	Replace	Check	X
17753370 10	INLET, AIR CLEANER, NO 3	0.00	\$35.30	0.00	\$0.00	Replace	Check	X
17893371 30	RESONATOR, INTAKE AIR	0.00	\$14.90	0.00	\$0.00	Replace	Check	X
17771370 20	BRACKET, AIR CLEANER	0.00	\$26.90	0.00	\$0.00	Replace	Check	X
17700373 30	AIR CLEANER ASSY	0.00	\$956.20	0.00	\$0.00	Replace	Check	X
90904060 08	TUBE, UNION (FOR AIR CLEANER HOSE)	0.00	\$19.40	0.00	\$0.00	Replace	Check	X
57101470 70	MEMBER SUB-ASSY, FR RH	0.00	\$2,012.70	0.00	\$0.00	Replace	Check	X
57102470 90	MEMBER SUB-ASSY, FR LH	0.00	\$1,959.50	0.00	\$0.00	Replace	Check	X
85319471 70	WIPER WASHER INLET	0.00	\$55.40	0.00	\$0.00	Replace	Check	X
85315471 60	WIPER WASHER JAR	0.00	\$183.60	0.00	\$0.00	Replace	Check	X
53801470 80	FENDER SUB-ASSY, FR , RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair	X
75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	/
53807470 20	SEAL SUB-ASSY, RH	1.00	\$50.20	25.00	\$37.65	Replace	Replace	/
53875470 70	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Check	X
53701471 11	APRON SUB-ASSY, FRONT FENDER, RH	0.00	\$944.20	0.00	\$0.00	Replace	Check	X
53802471 00	FENDER SUB-ASSY, FR , LH	1.00	\$933.10	25.00	\$699.83	Replace	Replace	/
75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	/