Vic (LKKAuto)

From: Vic (LKKAuto)

Sent: Monday, 23 September, 2019 3:28 PM

To: claimsdept@sg.cntaiping.com

Cc: Chong Boon Sen; Admin A; Vic (LKKAuto); Alfred Toh

Subject: <SEEK MANDATE> RE: Direct Settlement - Accident Involving GX6144U (OI : CTI -

TBA) and SJX2742J (TP: LKK REF - CC6/CTI19009132/Bha3) on 15/05/2019

Attachments: LKK INSPECTION REPORT.pdf; LKK ADJUSTMENT REPORT.pdf; LKK INSPECTION

PHOTOS.pdf; LKK REINSPECTION PHOTOS.pdf; LKK AFTER REPAIR PHOTOS.pdf; TP

LOD.pdf; LETTER TO OI.pdf

CTI REF - TBA

LKK REF - CC6/CTI19009132/Bha3

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES GX 6144U (OI) AND SJX 2742J (TP) ON 15/05/2019

We refer to the above matter.

It was reported that Insured vehicle reversed out from c/p lot when hit TP behind it.

We had spoken to the Insured Driver Mr Tan and was informed of the TP claim. A letter was sent out to the Insured company to notify TP claim and NCD issues. No feedback received till date.

As such, in view of BOLA 24, liability may not be to our Insured's favour and we have to settle the claim from the TP vehicle and the damages sustained to TP vehicle were consistent to the nature of the accident.

Summary to offer to repairer **GUAN MOTOR WORKS** is as follows:

TP CLAIMED		REVISED - TO OFFER
Cost of Repair	\$ 4,124.49	\$ 2,500.00
Loss of Rental (\$100 x 6 days)	\$ 600.00	\$ 600.00
LTA Search Fee	\$ 7.49	\$ 7.49
TOTAL	\$ 4,731.98	\$ 3,107.49

Breakdown of days is as follows:

ТО	TAL 6 days
Weekends / Downtime	1 day
Recommended Days	5 days

Relevant supporting claim documents are attached herewith for your perusal and reference.

For your approval and/or further instructions please.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: <u>vicalpeh@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)





Save the Earth Print only when necessary

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Mei Kwan (LKKAuto)

Sent: Thursday, 30 May, 2019 2:06 PM To: claimsdept@sg.cntaiping.com

Cc: Chong Boon Sen; Vic (LKKAuto); CS A Team; Admin A

Subject: Direct Settlement - Accident Involving GX6144U (OI: CTI - TBA) and SJX2742J (TP: LKK REF -

CC6/CTI19009132/Bha3) on 15/05/2019

'WITHOUT PREJUDICE' SAVE AS TO COSTS

Dear Sir /Madam,

We refer to the above matter.

We have inspected TP vehicle SJX 2742 at M/s Guan Motor Works - Sin Ming on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)