

Surveyor:

KSL

DOI:

ASSIGNMENT

23/5/19

Date / Time:

23/5/19

Registered in Mactan:

24/5/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLX 7233E

Name of Insured:

WSS2AMAH BTE ABON 41.14

Insured Tel No.:

HP:

Claim No.:

Policy No.:

Make / Model:

Excess Sec II : S5

D.O.A.:

23/05/19

Place of Accident:

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: ☒ YES / ☐ NO)OI GIA REPORT: ☒ YES / ☐ NO ; TP GIA REPORT: ☐ YES / ☐ NO

Insured Liability:

%

Final ? Yes / No

SLX498J



INSRS:

WSP:

Tel:

Liability:

RMKS:

Cheng Hoe



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SLX498J - X

SLX 7233E - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(

days) Reduction:

%

Confirm by:

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

Email

Call

Repair Cost: (w/bst)

S\$ 5464.17

If NO or B 28, Ass, Lia:

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$ 400.00

(\$ 80 x 5 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$ 8.60

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$ 5872.17

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 5872.17

Name 1:

Cheng Hoe Motor Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320

COPY SENT 26/9/19

my 24/9

ASS. REC. BY:

REF:

A/G 1

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

1.3.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLC 5498J

Yr Regn:

02, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Peugeot 5008

c.c. 1560

Colour:

M Silver

A/C: Insured / Std / NI / NA

Sp. Reading:

19640

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF 306B142T.GS201170

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

215/50R17

R:

BS / DON / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

23/5/19

D.O.I.

23/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

PIP - \$5106.70 (Red \$283.20 / 51.)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

5 + RS. \$1

Fuel

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLL5498J

70/176

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

Estimate No: ES1991542/WS

Date: 23 May 2019

Policy No:

Veh Reg No: SLL5498J

Make/Model: PEUGEOT PEUGEOT
 5008 1.6

Chassis No: VF30EBHGTGS201170

Engine No:

Reg. Date: 28/02/2017

WS Ref: TP AIG

Claim Type: Third Party

Accident Date: 23/05/2019

TP Veh Reg No: SLX7233E B5106.70 4 days

Estimate Repair Cost to Vehicle No :SLL5498J

| Description | U/Price | Quantity | List Price | Amount |
|--|----------|----------|----------------------|-------------|
| | | | SS | SS |
| List Price | | | | |
| 1 REAR TAILGATE | 1,750.00 | 1 PC | 1,750.00 | ✓ |
| 2 TAILGATE INNER LOCK | 350.00 | 1 PC | 350.00 | ✓ |
| 3 TAILGATE EMBLEM - BLUE Hd | 195.00 | 1 PC | 195.00 | ✓ |
| 4 TAILGATE EMBLEM -5008 | 98.00 | 1 PC | 98.00 | ✓ |
| 5 REAR BUMPER | 1,050.00 | 1 PC | 1,050.00 | ✓ |
| 6 REAR BUMPER REINFORCEMENT | 520.00 | 1 PC | 520.00 | ✓ |
| 7 REAR BUMPER REFLECTOR LH | 148.00 | 1 PC | 148.00 | ✓ |
| | | | 4,111.00 | |
| | | Less 10% | 411.10 | 3,699.90 |
| Special Net | | | | |
| 8 REVERSE SENSOR | 280.00 | 1 SET | 280.00 | ✓ |
| 9 REAR WINDSCREEN GLASS SEALANT | 40.00 | 1 PC | 40.00 | ✓ |
| | | | 320.00 | 320.00 |
| Labour | | | | |
| 10 REMOVE AND REFIX REAR WINDSCREEN GLASS | 120.00 | 1 LA | 120.00 | ✓ |
| 11 TO PANEL BEATING | 500.00 | 1 LA | 500.00 | 450 |
| 12 TO PUTTY AND RESPRAY ON REAR BUMPER, TAILGATE, RR PANEL, RR REFLECTOR | 700.00 | 1 LA | 700.00 | 600 |
| 13 TO REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM | 50.00 | 1 LA | 50.00 | ✓ |
| | | | 1,370.00 | 1,370.00 |
| | | | Total | SS 5,389.90 |
| | | | Add GST @ 7% | 377.29 |
| | | | Total Amount Payable | SS 5,767.19 |

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

CO-R-
 LOU 4+1 5x80

OneMotoring

Rebate PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

| | |
|----------------|----------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 3778D |

Vehicle Details

| | |
|-------------------------------|---------------------------|
| Vehicle No.: | SLL5498J |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 23 May 2019 |
| Vehicle Make: | PEUGEOT |
| Vehicle Model: | 5008 1.6 BLUEHDI EAT6 S/R |
| Primary Colour: | Grey |
| Manufacturing Year: | 2016 |
| Engine No.: | 10JBHX3012994 |
| Chassis No.: | VF30EBHGTGS201170 |
| Maximum Power Output: | 88.0 kW (118 bhp) |
| Open Market Value: | \$23,710.00 |
| Original Registration Date: | 28 Feb 2017 |
| First Registration Date: | 28 Feb 2017 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$15,194.00 |

Intended PARF Rebate Details

| | |
|-------------------------------|-------------|
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 27 Feb 2027 |
| PARF Rebate Amount: | \$11,395.00 |

Intended COE Rebate Details

| | |
|-----------------------------|--------------------------------------|
| COE Expiry Date: | 27 Feb 2027 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$49,430.00 |
| COE Rebate Amount: | \$38,367.00 |
| Total Rebate Amount: | \$49,762.00 |

The information contained herein is correct as at 23 May 2019

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLL5498J

78/176

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1991542/WS

Date: 23 May 2019

Policy No:

Veh Reg No: SLL5498J

Make/Model: PEUGEOT PEUGEOT
5008 1.6

Chassis No: VF30EBHZTGS201170

Engine No:

Reg. Date: 28/02/2017

WS Ref: TP AIG

Claim Type: Third Party

Accident Date: 23/05/2019

TP Veh Reg No: SLX7233E

Not Authair

Presum B4poin
4 days

Estimate Repair Cost to Vehicle No :SLL5498J

| Description | U/Price | Quantity | List Price | Amount |
|--|----------|----------|------------|------------|
| | | | <u>S\$</u> | <u>S\$</u> |
| List Price | | | | |
| 1 REAR TAILGATE | 1,750.00 | 1 PC | 1,750.00 | ✓ |
| 2 TAILGATE INNER LOCK | 350.00 | 1 PC | 350.00 | ✓ |
| 3 TAILGATE EMBLEM - BLUE Hdi | 195.00 | 1 PC | 195.00 | ✓ |
| 4 TAILGATE EMBLEM -5008 | 98.00 | 1 PC | 98.00 | ✓ |
| 5 REAR BUMPER | 1,050.00 | 1 PC | 1,050.00 | ✓ |
| 6 REAR BUMPER REINFORCEMENT | 520.00 | 1 PC | 520.00 | ✓ |
| 7 REAR BUMPER REFLECTOR LH | 148.00 | 1 PC | 148.00 | ✓ |
| | | | 4,111.00 | |
| | | Less 10% | 411.10 | 3,699.90 |
| Special Net | | | | |
| 8 REVERSE SENSOR | 280.00 | 1 SET | 280.00 | ✓ |
| 9 REAR WINDSCREEN GLASS SEALANT | 40.00 | 1 PC | 40.00 | ✓ |
| | | | 320.00 | 320.00 |
| Labour | | | | |
| 10 REMOVE AND REFIX REAR WINDSCREEN GLASS | 120.00 | 1 LA | 120.00 | ✓ |
| 11 TO PANEL BEATING | 500.00 | 1 LA | 500.00 | 4501 |
| 12 TO PUTTY AND RESPRAY ON REAR BUMPER, TAILGATE , RR PANEL, RR REFLECTOR | 700.00 | 1 LA | 700.00 | 6001 |
| 13 TO REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM | 50.00 | 1 LA | 50.00 | ✓ |
| | | | 1,370.00 | 1,370.00 |

Total S\$ 5,389.90

Add GST @ 7% 377.29

Total Amount Payable S\$ 5,767.19

For Cheng Hoe Motor Pte Ltd

Liability Consultants hence notify
the Repairer of the following:
• To resurvey before after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No legal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

CC4/A1619009158/Kda3

Jim Lee

PAYMENT ADVICE

| | |
|--|--|
| Your Ref : AIG Vehicle no. | : SLX7233E |
| Claimant Vehicle No. | : SLL5498J |
| Date of Accident | : 23/05/2019 |
| Traffic Accident involving vehicle/s No. | : SLIP ROAD - SLE TOWARDS SEMBAWANG ROAD |

BREAKDOWN OF PAYMENT/S

| <u>S/No.</u> | <u>Items</u> | <u>Amount</u> | <u>Remark</u> |
|--------------|--------------|--------------------|-----------------|
| 1 | Repair cost | \$ 5,464.17 | |
| 2 | Loss of Use | \$ 400.00 | (\$80 x 5 days) |
| 3 | LTA Search | \$ 8.00 | |
| TOTAL | | \$ 5,872.17 | |

All payment should be made payable to Cheng Hoe Motor Pte Ltd.

Service Adviser : LKK
Contact No. : 6256 3561



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG19009158/Kda3

08 JULY 2019

ROSZANAH BTE ABDOL LATIFF
BLK 159 JALAN TECK WHYE
#01-141
SINGAPORE 680159

Dear Sir/Madam,

ACCIDENT INVOLVING SLX 7233E & SLL 5498J ALONG/AT MANDAI ROAD TO SEMBAWANG ROAD ON 23/05/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLL 5489J against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as it is head to rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE
Case Handler
DID: 6749 5792
FAX: 6741 4108
Email: JiaLe@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I, Teo Hoo Seng (the third party claimant) of 3 Jalan Jambu
Batu Singapore 588722 (address), owner of SLL5498J (vehicle no.) hereby
authorize CHENG HOE MOTOR PTE LTD ("the workshop") to act for me with respect to
my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SLL5498J that
was damaged pursuant to the accident which occurred on 23/5/2019 (date) along Slip Rd - SLE
towards Sembawang Rd (location) involving vehicle no/s SLV7233E ("the accident").


I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the
workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s
being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice
and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is
concerned.

Dated this 23 (day) of May (month) 2019 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER

(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

"We/I, **CHENG HOE MOTOR PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$5464.17** (Repair Cost), **S\$400.00** (Loss of Use), **S\$8.00** (Disbursement), for vehicle no **SLL5498J** that was damaged pursuant to the accident which occurred **23/5/2019** (date) along **Slip Road – SLE towards Sembawang Road** (location) involving vehicle no/s **SLV7233E**.

This is pursuant to the inspection conducted on **23/5/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **Teo Hoo Seng** ("the third party claimant") of vehicle no **SLL5498J** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage **SLL5498J** (vehicle no.) as a result of the accident.


We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 20 (day) of September (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

Cheng Hoe Motor Pte Ltd

Blk 1019, Vishnu Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

NO: CL8190905
Date: 27 Aug 2019
Policy No: DMPPHQ19-001006
Veh Reg No: SLL5498J
Make/Model: PEUGEOT PEUGEOT
5008 1.6
Job No: JC1600379

WS Ref: TP AIG
Claim Type: Third Party
Accident Date: 23/05/2019
TP Veh Reg No: SLX7233E

| Description | Quantity | List Price | PAGE:1 Amount |
|---|----------|--------------|------------------|
| To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor) | 1 PC | S\$ 5,106.70 | S\$ 5,106.70 |

| | |
|----------------------|--------------|
| Total | S\$ 5,106.70 |
| Add GST @ 7% | 357.47 |
| Total Amount payable | S\$ 5,464.17 |

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|---|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 23 May 2019 Edit Reg | | 23 May 2019 00:00 Edit Adj Rpt | \$55,106.70 Edit Estimates | \$55,106.70 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

| | | | |
|-----------------------------|---|------------------------|--|
| Insured: | ROSZANAH BTE ABDOL LATIFF, ID: S1551081A | | |
| Main Claimant: | TEO HOO SENG, ID: S0223778D | | |
| Vehicle Reg. No.: | SLL5498J | Date of Loss: | 23/05/2019 00:00 - :59 [26 Months and 25 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / 9497890523SG | Policy/Cover Note No.: | (Comprehensive) |
| Vehicle Reg. No. (Insured): | SLX7233E | Policy No. (Claimant): | DMPPHQ19-001006 |
| | | Excess: | |
| Repairer: | Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142 | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com | | |
| Claimant's Insurer: | EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/06/2019] | | |

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (27/05/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents






*SLL5498J (9497890523SG)
[SLX7233E]
TP
TEO HOO SENG
May 23 2019 12:00AM
[ROSZANAH BTE ABDOL LATIFF]
Cheng Hoe Motor Pte Ltd

| | | | | | | |
|------------------|---------------|--------------------|--------------|--------------|------|-----------------|
| Upload Documents | Upload Photos | Compose New Letter | Upload Video | Upload Audio | View | View in Browser |
|------------------|---------------|--------------------|--------------|--------------|------|-----------------|

| Letters/Correspondences | | | | | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|--------------|--|---|-----------|------------|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print | |
| 1 | (Draft) | Third Party Express Settlement - Payment Breakdown | 1 | Edit | | |

| Photos/Images | | | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|---|-----------|-------------------------------------|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print | |
| 1 | 17/09/19 16:58 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 2 | 17/09/19 16:58 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 3 | 17/09/19 16:58 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 4 | 17/09/19 16:58 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 5 | 17/09/19 16:58 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 6 | 17/09/19 16:58 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 7 | 17/09/19 16:58 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 8 | 17/09/19 16:58 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 9 | 17/09/19 16:58 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 10 | 17/09/19 16:58 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 11 | 17/09/19 16:58 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 12 | 17/09/19 16:58 | Chassis Number | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 13 | 17/09/19 16:58 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 14 | 17/09/19 16:58 | Odometer Reading | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 15 | 17/09/19 17:02 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 16 | 17/09/19 17:02 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 17 | 17/09/19 17:02 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 18 | 17/09/19 17:02 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 19 | 17/09/19 17:02 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 20 | 17/09/19 17:02 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 21 | 17/09/19 17:05 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 22 | 17/09/19 17:05 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 23 | 17/09/19 17:05 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 24 | 17/09/19 17:05 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 25 | 17/09/19 17:05 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 26 | 17/09/19 17:05 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 27 | 17/09/19 17:05 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 28 | 17/09/19 17:05 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 29 | 17/09/19 17:05 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 30 | 17/09/19 17:05 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 31 | 17/09/19 17:05 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |
| 32 | 17/09/19 17:05 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> | |

| Documentation | | | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|--|---|-----------|------------|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print | |
| 1 | 24/05/19 14:22 | EMAIL FROM AIG DD 23.05.2019 | 1 | Load PDF | | |
| 2 | 24/05/19 14:22 | ACKNOWLEDGEMENT EMAIL TO AIG DD 23.05.2019 | 1 | Load PDF | | |
| 3 | 27/05/19 20:06 | TP ESTIMATE - MARKED | 1 | Load PDF | | |
| 4 | 27/05/19 20:06 | TP GIA REPORT | 1 | Load PDF | | |
| 5 | 08/10/19 10:16 | WORKSHOP INVOICE | 1 | Load PDF | | |
| 6 | 08/10/19 10:16 | AUTHORISATION TO ACT FORM | 1 | Load PDF | | |

| Letters/Correspondences | | | | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|----------------|---|--|---|-------------------------------------|
| No | Finalized On | | | Thumbnail | Print |
| 7 | 08/10/19 10:16 | LKK Auto Consultants Pte Ltd (HQ) | |  | Load PDF |
| | | Release Voucher | | | |
| 8 | 08/10/19 10:16 | LTA SEARCH | |  | Load PDF |
| 9 | 08/10/19 10:16 | LOD | |  | Load PDF |
| 10 | 08/10/19 10:16 | LETTER TO OI | |  | Load PDF |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | | Thumbnail | Print |
| 1 | 27/05/19 10:29 | OI GIA REPORT | |  | Load PDF |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|---|-------|------|-------|
| There are no document checklists configured. | | | |
| <div> <div>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</div> <div> <div></div> <div></div> </div> </div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

| | | | |
|-------------------|---------------------|--------|----------------------|
| Vehicle No: | SLX7233E (Insd veh) | Model: | PEUGEOT 5008 1.6 D |
| | SLL5498J (TP veh) | | BLUEHDI EAT6 S/R (A) |
| Date of Accident: | 23/05/2019 | | |

| | | | |
|-----------------------|------|------------------------------|--|
| Global Sum Settlement | : | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Repair Estimate | : \$ | 5,767.19 | |
| Final Repair Cost | : \$ | 5,464.17 | |
| Loss of Use | : \$ | 400.00 | 5.00 days at \$80.00 per day |
| Rental (if any) | : \$ | 0.00 | days |
| LTA / GIA Search Fee | : \$ | 8.00 | |
| Others: | : \$ | 0.00 | |
| | : \$ | | |
| Final Settlement Sum | : \$ | 5,872.17 | |

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

| Payment Instruction: Payee's Breakdown | | | |
|--|-------------------------|------|----------|
| 1) | Cheng Hoe Motor Pte Ltd | : \$ | 5,872.17 |
| 2) | | : \$ | |
| 3) | | : \$ | |

JOANNE LEE KHANG MIN

08 Oct
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19009158/KDA3Q2

Date: 08/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant SLL5498J

Insured Vehicle No : SLX7233E

Vehicle No : SLL5498J

Date of Loss: 23/05/2019

Nature of Claim: TP

Claim No: 9497890523SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL5498J

Make & Model: PEUGEOT 5008, 1.6 D BLUEHDI EAT6 S/R (A)

Engine No: 10JBHX3012994

Reg. Date: 28/02/2017 (Man. Year: 2016)

Chassis No: VF30EBHGTGS201170

Colour: Metallic Silver

Odometer: 19640 km

Engine Capacity: 1560 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17

Rear Tyre Size:

215/50 R17

Front Left Side: Dunlop 8 mm

Rear Left Side:

Dunlop 8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side:

Dunlop 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-----------------|-----------------|---------------|-------------|
| Parts | 4,019.90 | 3,886.70 | 133.20 | 3.31 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,370.00 | 1,220.00 | 150.00 | 10.95 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 5,389.90 | 5,106.70 | 283.20 | 5.25 |
| + GST 7.00/7.00% (S\$) | 377.29 | 357.47 | 19.82 | 5.25 |
| Nett Amount (S\$) | 5,767.19 | 5,464.17 | 303.02 | 5.25 |
| + Loss of Use (5.0 x S\$80.00/day) (S\$) | | 400.00 | | |
| + Doc/Search Fee (S\$) | | 8.00 | | |
| Nett Liability (S\$) | | 5,872.17 | | |

INSPECTION

Date of Assignment: 23/05/2019

Date Inspected: 23/05/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------|-------------|-------------|--------------|
| 1 | 1 | | *REAR TAILGATE | Bent | 1,750.00 FL | *1,750.00 FL |
| 2 | 1 | | *TAILGATE INNER LOCK | Dented | 350.00 FL | *350.00 FL |
| 3 | 1 | | *TAILGATE EMBLEM -BLUE HDI | Necessary | 195.00 FL | *195.00 FL |
| 4 | 1 | | *TAILGATE EMBLEM -5008 | Necessary | 98.00 FL | *98.00 FL |
| 5 | 1 | | *REAR BUMPER | Buckled | 1,050.00 FL | *1,050.00 FL |
| 6 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 520.00 FL | *520.00 FL |
| 7 | 1 | | *REAR BUMPER REFLECTOR LH | Serviceable | 148.00 FL | *- FL |
| 8 | 1 | | *SET REVERSE SENSOR | Shorted | 280.00 FS | *280.00 FS |
| 9 | 1 | | *REAR WINDSCREEN GLASS SEALANT | Necessary | 40.00 FS | *40.00 FS |

F=Franchise part, S=SpcNett, L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (\$) | 4,431.00 | 4,283.00 |
| - List Item Discount on L Items 10.00/10.00% (\$) | 411.10 | 396.30 |
| Total Parts (\$) | 4,019.90 | 3,886.70 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|---|----------|------------|----------|
| <u>Labour Items</u> | | | | |
| 1 | REMOVE AND REFIX REAR WINDSCREEN GLASS | New | 120.00 | 120.00 |
| 2 | TO PANEL BEATING | New | 500.00 | 450.00 |
| 3 | TO PUTTY AND RESPRAY ON REAR BUMPER, TAILGATE, RR PANEL, RR REFLECTOR | New | 700.00 | 600.00 |
| 4 | TO REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM | New | 50.00 | 50.00 |
| Gross Labour Cost (\$\$) | | | 1,370.00 | 1,220.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >