

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 13:46

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014940	Account: A0006 (T 0)		
		Date : 03/03/2020	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
		Order : SLC9990A			
		Term : 30			

Regn No: SLC9990A (V 28451)		Regn Date: 31/03/2016	Mileage: 54814	WIP No.: 54117	
Model: Q5 2.0 TFSI QU 8RB01A (230 bhp		Chassis: WAUZZZ8R8GA073297	Engine: CNC 148283	Dept: U	
You have been assisted by :- UB-Kelvin Khoo (138)					

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1000.00	1.00	-1,000.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	280.00	1.00	280.00
S	BODYWORK	M: TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGE	560.00	1.00	560.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, RHS HEADLIGHT, RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR. TO REPAIR RHS REAR FENDER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	3000.00	1.00	3,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, FRONT LOWER SPOILER, RHS FRONT FENDER, RHS FRONT DOOR, RHS REAR DOOR, RHS REAR FENDER, RHS REAR BUMPER, RHS WING MIRROR COVER AND DOOR COVER	3850.00	1.00	3,850.00
S	BODYWORK	M: TO CARRY OUT WHEEL ALIGNMENT. TO INSPECT RHS FRONT AND REAR SUSPENSION.	320.00	1.00	320.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
Q	OTHERS	M: TO SUPPLY TYRE (BY OWNER)	350.00	1.00	350.00
X	A8R0807065C GRU	(A) (SK) COVER 6/6/19 Less 020%	1.00	2353.00	1,882.40

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 13:46

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014940 Date : 03/03/2020 Order : SLC9990A Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLC9990A (V 28451) Regn Date: 31/03/2016 Mileage: 54814 WIP No.: 54117

Model: Q5 2.0 TFSI QU 8RB01A (230 bhp) Chassis: WAUZZZ8R8GA073297 Engine: CNC 148283 Dept: U

You have been assisted by :- UB-Kelvin Khoo (138)

		Details	Qty	Unit Price	Amount
X	A8R0807061F GRU	(SK) FR.SPOILER (LAST)	Less 020%	1.00	568.50
X	A8R0807278C	STRIP	Less 020%	1.00	33.10
X	A8R0807682J BJI	GRILL (LAST)	Less 020%	1.00	319.00
X	A8R0807284C	GUIDE	Less 020%	1.00	33.90
X	A8R0821106A	FENDER (LAST)	Less 020%	1.00	912.50
X	AN 0161857	POP-RIVET	Less 020%	6.00	3.00
X	A8R0821136	SUPPORT	Less 020%	1.00	78.30
X	A8R0821172K	WHEEL HOUS (LAST)	Less 020%	1.00	245.50
X	A8R0854960G GRU	007288/ (V) (SK) LINING	Less 020%	1.00	174.00
X	A8R0941044D	HEADLAMP (LAST)	Less 020%	1.00	2501.00
X	A8R0831052E	DOOR (LAST)	Less 020%	1.00	2829.00
X	A8R0837912L	SEAL (LAST)	Less 020%	1.00	184.50
X	AD 355205A2	BONAGENT	Less 020%	2.00	44.90
X	AD 00940104	CLEANER (LAST)	Less 020%	1.00	64.60
X	A8R0837249F	CHECK ROD	Less 020%	1.00	132.00
X	A4L0949102A	TURN SIGNAL	Less 020%	1.00	149.00
X	A8R0837208 GRU	007288/ (V) (SK) HANDLE	Less 020%	1.00	235.50
X	A8R0837240 2ZZ	TRIM (LAST)	Less 020%	1.00	116.50
X	A8R0833052B	DOOR (LAST)	Less 020%	1.00	2829.00
X	A8R0839912L	SEAL RH	Less 020%	1.00	192.50
X	A8R0839982C	FOIL (LAST)	Less 020%	1.00	70.60
X	A8R0839249F	007288/ (V) (SK) CHECK	Less 020%	1.00	132.00
X	A8R0853960L GRU	(A) (SK) COVER 6/6/19	Less 020%	1.00	467.00
X	A8R0853970L GRU	COVER (LAST)	Less 020%	1.00	373.50
X	A8R0010502CQ	LABEL	Less 020%	1.00	24.10
X	A191853586C	GROMMET	Less 020%	4.00	2.40
X	A8R0837210	007288/ (V) (SK) PACKIN	Less 020%	1.00	5.10
X	A8R0837278	007288/ (V) (SK) PACKIN	Less 020%	1.00	5.10
X	A8K0837199	CLIP	Less 020%	12.00	0.70
X	AWHT003497	BOLT	Less 020%	4.00	2.10
X	AWHT003237	BOLT	Less 020%	4.00	1.00
X	A3C0973737	HOUSING	Less 020%	1.00	28.40

Parts 12,156.32
Labour 350.00
Sublet 8,682.00
Menus 0.00
Lubricant 0.00

Sub-Total 20,188.32

7% GST 1,413.18

Grand Total 21,601.50



Received by

For & on behalf of
Premium Automobiles Pte Ltd