

AIG Asia Pacific Insurance Pte. Ltd
 78 Shenton Way
 #08-16
 Singapore(079120)

Register number : 201015366H

REPAIR PERFORMA INVOICE

Vehicle number	SLC1493X
Make / Model	HONDA HRV
Chassis number	MRHRU1830GP000050
Accident date	22 May 2019
Reference	1905-74

Qty Particulars Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	TAILGATE / DD	
1	TAILGATE LOCK / BT	
1	TAILGATE LOCK STRIKER X	
1	TAILGATE WEATHERSTRIP / TN	
1	TAILGATE INNER PULL COVER X	
2	TAILGATE HINGE X	
2	TAILGATE LAMP X ?	
1	TAILGATE EMBLEM - HR-V / AEC	
1	TAILGATE EMBLEM - IVTEC / AEC	
1	TAILGATE OUTER GARNISH ?	
1	TAILGATE INNER TRIM ?	
2	TAILGATE ABSOBER X	
1	WINDSCREEN MOUDLING / AEC	
2/1	REAR CORNER PANEL ?	
1	REAR BUMPER / DD	
1	REAR BUMPER REINFORCEMENT X	
1	REAR BUMPER UNDERCOVER X	
2/1	REAR BUMPER REFLECTOR ?	
2	REAR BUMPER RETAINER / BR	
1	END PANEL ?	
1	END PANEL TOP GARNISH / CNT	
1	REAR BUMPER CHROME GARNISH X	
1	EXHAUST SILENCER ?	
2	EXHAUST MOUNTING X	
1	EXHASUT HEATSHIELD ?	
2	REAR FENDER INNER TRIM X	
1	SPARE TYRE TOP BOARD X	
1	FLOOR PANEL X	
1	TAILGATE KEYLESS SENSOR ?	
1	KEYLESS SENSOR HOLDER ?	
1	RH/ Tailamp / CNT	
	Less 20%	
	Subtotal	0.00
	Balance C/F	0.00

PARTS REPLACEMENT - SPECIAL NETT ITEMS

		Balance B/F	0.00
1 SET	REVERSE SENSOR / BR		400.00
1	REAR NUMBER PLATE X		80.00
1 SET	REAR BUMPER CLIP / ALEC	30	40.00
1 SET	REAR TAILGATE INNER TRIM CLIP / ALEC	20	30.00
1	JOINT SEALANT - ALEC	30	150.00
1	WINDSCREEN SEALANT / ALEC	40	150.00
		Subtotal	850.00
		Balance C/F	850.00
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
		Balance B/F	850.00
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	30	60.00
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	50	200.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	20	150.00
4	REMOVE AND RENEW REAR EXHAUST ASSY	?	150.00
5	DIAGNOIS CHECK AND CLEAR FAULT CODE	X	400.00
6	REMOVE AND REFIT REAR WINDSCREEN	100	150.00
7	TRANSFER PARTS, ATTCHMENT FROM OLD TAILGATE TO NEW	50	200.00
8	PANEL BEATING ON AFFECTED AREAS	500	1600.00
9	SPRAY PAINTING ON AFFECTED AREAS	500	1400.00
10	APPLY ANTI RUST ON AFFECTED AREAS	30	150.00
		Subtotal	4460.00
		Grand total	5310.00

Steve CLKK) will provide 24/5/19, 3.00 pm
 5 days
 L/S
 Ry AF spny

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: