



張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)
Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-E
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
REG. NO. 275084 / 00X

EQ INSURANCE
5 Maxwell Road #17-00
Tower Block MND Complex
Singapore 069110
Tel: 62239433
Fax: 62221996
Email: weiyin.tan@eqinsurance.com.sg

will provide 24/5/19, 1.00 pm
3 days
L/S
Ry Al spy

Dear Sir/Madam

21.05.2019

RE: THIRD PARTY CLAIMS FOR FBN4169Z AGAINST YOUR
INSURED GBA6745R, ACCIDENT ON 08.05.2019 AT SERANGOON
AVENUE 2

PG 1

DESCRIPTION	AMOUNT
1 SIDE COVER 3 X CUT (Handy side R)	\$ 98.00
2 SEAT BAR / CUT	\$ 180.00
3 CASE AIR CLEANER X cut	\$ 69.00
4 MAIN STAND / CUT	\$ 120.00
5 MIRROR RH / CUT	\$ 42.00
6 BRAKE LEVER RH / CUT	\$ 22.50
7 HEAD LAMP ASSY / BR	\$ 600.00
8 LOWER BODY COWLING / CUT (RH)	\$ 45.00
9 FRONT COVER / CUT	\$ 82.50
10 BOARD FOOTREST / BR BR	\$ 60.00
11 MUFFLER PROTECTOR / CUT	\$ 57.00
12 FRONT BRAKE DISC BT /	\$ 155.00
13 FRONT RIM / BT	\$ 383.00
14 INT FLASHER ASSY / CUT	\$ 30.00
15 STAY 1 ?	\$ 150.00
16 BODY FRONT UPPER UNDER ?	\$ 58.00
17 SIDE COVER (\$75 X 2) / CUT	\$ 150.00
18 MOLE SIDE COVER X	\$ 38.00
19 FRONT COVER 2 (Seat to side RH) BR /	\$ 58.00
20 LEG SHIELD RH X	\$ 45.00
21 EMBLEM 3D / ALIC	\$ 27.00
22 COVER FENDER X CUT (Front)	\$ 60.00
23 EMBLEM FOR SIDE COVER(2 X \$25) / ALIC	\$ 50.00
24 END GRIP X	\$ 60.00

PG 2

25 MAT 4 / MIS	\$ 25.00 -
26 CLAMP / MIS	\$ 35.00 -
27 OIL SEAL / MLC	\$ 30.00 -
28 HANDLE BAR X	\$ 48.00
29 BODY COWLING 2 (Handle side on R) cut /	\$ 52.50 -
30 FRONT BODY UNDER 2 (Head side on R) cut /	\$ 37.50 -
31 BATTERY COVER (Side mirror cover) cut /	\$ 22.50 -
32 STAY FENDER 2 (Fork on R) cut /	\$ 42.00 -
33 MOLE SIDE COVER 2 (Side seat on R) BR X	\$ 25.50
34 COVER SIDE 2 (Seat low on R) BR	\$ 40.50 -
35 CAST WHEEL FRONT X	\$ 297.00
36 BEARING (\$30 X 2) / MLC	\$ 90.00 -
37 SIDE COVER 4 RH/LH (\$32 X 2) X	\$ 96.00
38 SEAT BAR X Reported	\$ 129.00
39 EMBLEM (2 X \$20) X Reported	\$ 21.00
40 EXHAUST PIPE / DD	\$ 1,100.00 -
41 EXHAUST GASKET / MLC	\$ 30.00 -
42 BOX 3 / BR	\$ 30.00 -
43 AIR BOX OUTER COVER 3 / cut	\$ 37.50 -
	<u>\$ 4,829.00</u>
Less 10%	\$ 482.90
Sub Total	<u><u>\$ 4,346.10</u></u>

Nett Item

1 TRANSPORT	\$ 60.00
2 LABOUR CHARGES	\$ 320.00
3 FORK OIL (2 X \$70)	\$ 140.00
Sub Total	<u><u>\$ 520.00</u></u>
Total	<u><u>\$ 4,866.10</u></u>

THANKS
TSP

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: