

Kd

Arthur Kenneth

# Cheng Hoe Motor Pte Ltd

Blk 1019, Vishnu Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST 201001158E RCB NO 201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120

TEL: 64193000 FAX: 64153727  
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK  
Claim Type: Third Party  
Accident Date: 24/05/2019  
TP Veh Reg No: GBF6097B

Estimate No: ES1991547/AMK  
Date: 24 May 2019  
Policy No: 5103456065 DC  
Veh Reg No: SGA1188Y  
Make/Model: HONDA FIT 1.5 A HYBRID  
Chassis No: GP53415782  
Engine No: LEB6070466  
Reg. Date: 30/08/2018

*Not Authorized*

*Resurvey By paint*

*Sdms*

## Estimate Repair Cost to Vehicle No :SGA1188Y

Description	U/Price	Quantity	List Price	Amount
			SS	SS
<b>List Price</b>				
1 REAR BUMPER	<i>Bu</i> 652.70	1 PC	652.70	✓
2 REAR BUMPER CLIP	<i>Ma</i> 3.90	5 PC	19.50	✓
3 REAR TAILGATE	880.40	1 PC	880.40	✓
4 TAILGATE INNER RUBBER	92.30	1 PC	92.30	✓
5 TAILGATE INNER LOCK	<i>R</i> 157.50	1 PC	157.50	✗
6 TAILGATE EMBLEM FIT	35.00	1 PC	35.00	✓
7 TAILGATE EMBLEM HYBRID	75.50	1 PC	75.50	✓
8 TAILGATE OUTER CHROME MOULDING	256.60	1 PC	256.60	✗
9 TAILGATE WINDSCREEN GLASS	<i>Shattered</i> 1,050.60	1 PC	1,050.60	✓
10 TAILGATE WINDSCREEN GLASS MOULDING	135.80	1 SET	135.80	✓
11 REAR END PANEL	<i>R</i> 390.60	1 PC	390.60	✗
			2941.80	
			Less 20% 588.36	
			2353.44	
<b>Special Net</b>				
12 REVERSE SENSOR	200.00	1 SET	200.00	✓
13 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
14 REAR WINDSCREEN GLASS TINTED FILM	250.00	1 PC	250.00	180.00
			490.00	420
<b>Labour</b>				
15 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
16 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	50.00	1 PC	50.00	✓
17 REMOVE & REFIX REAR BUMPER, TAIL LAMP, TAILGATE & ATTACHMENTS; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR FENDERS & REALIGN THE SAME	700.00	1 LA	700.00	500
18 PUTTY & RESPRAY REAR BUMPER, TAILGATE & SPOILER, REAR END PANEL, REAR FENDERS & AFFECTED AREAS	700.00	1 LA	700.00	600
19 RUSTPROOFING		1 LA	600.00	730
			1,620.00	1300

PARTS: 2353.44  
SA: 420  
L: 1300  
4073.44 ✓ ok

PIR: 4073.44/  
PLS CHECK & CONFIRM.

**Yik Auto Consultants** hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_