

Spare PartsVehicle No. : **SDF1103B**Submit By : **IDRAM**Make & Model : **MERCEDES C180 CGI**Year Manufacture : **2010**Chassis No. : **MR053HY9305002665**Engine No. : **27182030045478.00****Supplementary****Cost / List**

S/No.	Part Description	Qty	Cost Price	List Price	Disposition by Surveyor
S1	FRONT BUMPER <i>Dischd.</i>	1	\$ 1,099.00	✓	
S2	RH SIDE FRONT FENDER <i>Ryri</i>	1	\$ 720.00	✗	
S3	LHS HEADLAMP <i>only d</i>	1	\$ 880.00	✓	
S4	LHS HEADLAMP MOULDING <i>new</i>	1	\$ 50.00	✓	
S5	BONNET LOCK <i>new</i>	1	\$ 65.00	✗	
S6	REAR BUMPER RETAINERS CENTRE <i>2nd</i>	1	\$ 65.00	✓	
S7	REAR BUMPER RETAINERS RH <i>new</i>	1	\$ 45.00	✓	
S8	REAR TYRE MUDGUARD <i>new</i>	1	\$ 166.00	✗	
S9	EXHAUST SCREEN <i>coupled</i>	1	\$ 140.00	✓	
S10	SPARE TYRE WHEEL WELL <i>to n</i>	1	\$ 288.00	✓	
S11	PIRELLI P7 CINTURATO 225/45R17 <i>new</i>	1	\$ 280.00	✗	
	SUB TOTAL		\$ 3,798.00		
	COST +15%		\$ 569.70		
	TOTAL PARTS		\$ 4,367.70		
	SPECIAL NETT				
S1	REVERSE SENSOR MODULE <i>2nd</i>	1	\$ 250.00	✓	
S2	AIRCON GAS AND VACUUM <i>new</i>	1	\$ 80.00	✓	
S3	POWER STEERING OIL <i>new</i>	1	\$ 60.00	40	
	TOTAL SPECIAL NETT		\$ 390.00		
	SUPPLEMENTARY LABOUR				
S1	TO REPAIR REAR PANEL	1	\$ 750.00	400	
S2	TO PUTTY AND SPRAY RHS FRONT FENDER, REAR PANEL	1	\$ 500.00	400	
S3	COMPUTER WHEEL ALIGNMENT	1	\$ 150.00	✗	
	TOTAL LABOUR		\$ 1,400.00		
	TOTAL ON LABOUR		\$ 1,400.00		
	TOTAL PARTS		\$ 4,367.70		
	TOTAL SPECIAL NETT		\$ 390.00		
	SUB TOTAL		\$ 6,157.70		
	GST		\$ 431.04		
	GRAND TOTAL		\$ 6,588.74		

2567
2310.30

370

800

Adrian Lj
29/05/19Supplied by
3480.30

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.