

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP AXA

Claim Type: Third Party

Accident Date: 24/05/2019

TP Veh Reg No: SMK5743U

Estimate No: ES1991561/WS

Date: 28 May 2019

Policy No:

Veh Reg No: SLU7498Z

Make/Model: MIT MIT LANCER 1.6M

Chassis No: JMYSNCS3A8U006054

Engine No:

Reg. Date:

Estimate Repair Cost to Vehicle No :SLU7498Z

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Net Price				
1 REAR BUMPER	697.00	1 PC	697.00	✓
2 REAR BUMPER CENTRE BEAM	175.00	1 PC	175.00	?
3 REAR BUMPER SIDE RETAINER	49.00	2 PCS	98.00	✓
4 REAR BUMPER CLIP	3.50	6 PCS	21.00	✓
5 REAR RH TAILLAMP	421.00	1 PC	421.00	✓
6 REAR RH TAILLAMP SIDE CLIP	6.00	2 PCS	12.00	✓
7 REAR BOOT INNER LOCK	64.00	1 PC	64.00	✓
8 REAR BOOT INNER RUBBER	175.00	1 PC	175.00	?
9 REAR PANEL	495.00	1 PC	495.00	?
10 REAR PANEL INNER TOP GARNISH	156.00	1 PC	156.00	✓
			2,314.00	
		Less 10%	231.40	2,082.60
Special Net				
11 REAR BOOT LOGO	30.00	1 PC	30.00	✓
12 REVERSE SENSOR	200.00	1 PC	200.00	✓
			230.00	230.00
Labour				
13 TO PANEL BEATING	700.00	1 LA	700.00	?
14 TO PUTTY AND RESPRAY PAINTING	700.00	1 LA	700.00	5501
15 RUSTPROOFING	30.00	1 LA	30.00	?
			1,430.00	1,430.00

Total S\$ 3,742.60

Add GST @ 7% 261.98

Total Amount Payable S\$ 4,004.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

For Cheng Hoe Motor Pte Ltd