

Date : 29/05/2019
 TP Vehicle No. : SKM-9342-E
 To : AXA INSURANCE SINGAPORE PTE LTD
 Attn : Motor Claim Department

YVONNE
 ABWIN SERVICE PTE LTD
 DID:
 Fax:
 HP:

Owner : MARIA LIU MEI YOKE
 HL ASSURANCE PTE LTD

Certificate No. : MP309474

Vehicle No. : SKG-1819-G

Make & Model : TOYOTA VOXY HYBRID 1.8X CVT ABS D/AIRBAG 2WD 5D

Accident Date: 04/05/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	FRONT BUMPER 1450	\$1,500.00	—
10	FRONT BUMPER CLIP	\$50.00	—
1	FRONT BUMPER REATINER RH	\$85.70	—
1	FRONT BUMPER REINFORCEMENT	\$450.00	X
1	FRONT BUMPER SIDE garnish o/s	\$250.00	X
1	HEADLAMP RHS	\$1,750.00	—
1	HEADLAMP PANEL RH	\$290.00	X
10	HEADLAMP CLIP RH	\$50.00	X
1	FRONT FENDER RHS 850.10	\$950.00	—
1	FRONT FENDER INNER SHIELD RH	\$250.00	—
10	FRONT FENDER INNER SHIELD CLIPS	\$50.00	—
1	FRONT SHOCK ABSORBER (R/H)	\$500.00	X
1	FRONT SHOCK ABSORBER MOUNTING RHS	\$150.00	X
1	FRONT LOWER ARM RH	\$950.00	X
1	FRONT SHOCK ABSORBER TOP MOUNTING	\$250.00	X
1	FRONT FENDER EMBLEM HYBRID	\$55.00	—
Sub Total		\$7,580.70	
Discount 25% on Parts		(\$1,895.18)	4520.80
		\$5,685.53	

Special Nett

1	TYRE	\$350.00	X
1	RIM RHS	\$550.00	X
Sub Total		\$900.00	

Labour & Misc

TO CHECK & REFOCUS FRONT HEADLAMP & WIRING CHECK	\$150.00	30
TO CARRY OUT UNDERCARRIAGE REPAIR	\$450.00	X
TO CONDUCT 4 WHEEL ALIGNMENT	\$180.00	60

Date : 29/05/2019
 TP Vehicle No. : SKM-9342-E
 To : AXA INSURANCE SINGAPORE PTE LTD
 Attn : Motor Claim Department

YVONNE
 ABWIN SERVICE PTE LTD
 DID:
 Fax:
 HP:

Owner : MARIA LIU MEI YOKE
 HL ASSURANCE PTE LTD
 Certificate No. : MP309474
 Vehicle No. : SKG-1819-G
 Make & Model : TOYOTA VOXY HYBRID 1.8X CVT ABS D/AIRBAG 2WD 5D

Accident Date: 04/05/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	TO APPLY TUFF KOTE ON AFFECTED AREA.	\$150.00	40
	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,500.00	500
	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREA.	\$1,200.00	500
	Sub Total	\$3,630.00	
	Sub Total	\$10,215.53	
	GST 7%	\$715.09	
	Total	\$10,930.61	

Let's Auto Consultants hence notify the Repairer of the following:

- To reserve before/after spray painting
- To display damaged part(s) during resurvey
- Parts must be subject to confirmation
- This resurvey is on a "Without Prejudice" basis
- No repair modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-4785-80
 25%
 P-3589-35
 L-1130.00
 4719.35

SUPPLEMENTARY

Date : 03/06/2019
 TP Vehicle No. : SKM-9342-E
 To : AXA INSURANCE SINGAPORE PTE LTD
 Attn : Motor Claim Department

YVONNE
 ABWIN SERVICE PTE LTD
 DID:
 Fax:
 HP:

Owner : MARIA LIU MEI YOKE
 HL ASSURANCE PTE LTD

Certificate No. : MP309474

Vehicle No. : SKG-1819-G

Make & Model : TOYOTA VOXY HYBRID 1.8X CVT ABS D/AIRBAG 2WD 5D

Accident Date: 04/05/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	FRONT FENDER BRACKET RHS	<i>Ref</i> \$95.00	<i>Re</i> 
1	WASHER TANK	<i>Re</i> \$150.00	
	Sub Total	\$245.00	
	Discount 25% on Parts	(\$61.25)	
		\$183.75	
	Sub Total	\$183.75	
	GST 7%	\$12.86	
	Total	\$196.61	