

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKQ 7041 R

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 280.00 ✓
2	To remove front fittings, dismantle and renew front bumper, rhs front fender and align to position. To enew rhs headlamp assy. Reinstall all parts removed.	\$ 2,500.00 1400. ✓
3	To respray paint on front bumper, rhs front fender.	\$ 1,800.00 1400 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>4,772.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 7041 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>replaced</i>	\$ 2,100.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 234.00	+
3	RADIATOR GRILLE <i>new</i>	\$ 1,005.00	✓
4	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	\$ 64.00	+
5	FRONT FENDER - RH <i>Bracked</i>	\$ 904.00	✓
6	FRONT FENDER BRACE - RH <i>new</i>	\$ 107.00	X
7	FRONT FENDER BRACKET - RH <i>new</i>	\$ 48.00	X
8	FRONT FENDER DEFORMATION BRACKET - RH <i>new</i>	\$ 45.00	X
9	FRONT FENDER RIVET <i>new</i>	\$ 24.00	✓
10	FRONT FENDER STONE CHIP GUARD <i>new</i>	\$ 48.00	✓
11	HEADLIGHT - RH	\$ 2,152.00	+
12	HEADLIGHT BRACKET - RH <i>new</i>	\$ 96.00	+
13	HEADLIGHT MOUNTING - RH	\$ 107.00	+
14	FRONT NO. PLATE <i>new</i>	\$ 40.00	+
15	SUNDRIES <i>new</i>	S/N \$ 280.00	X NN
TOTAL SPARE PARTS CHARGES		: \$ 7,254.00	
TOTAL LABOUR CHARGES		: \$ 4,772.00	
GRAND TOTAL		: \$ 12,026.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 04/06/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant