

HOME

SERVICE REQUESTS

MESSAGES

CLAIMS

Claim	S9M01P09
Reference	CC4/ASM19009491/Uwa3s2
Loss Date	May 28, 2019
Report Date	May 29, 2019 10:50:24 AM
Request Date	May 29, 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration # SLM1674M

Make TPVD UNKNOWN

Model TBC

Service Address

Primary Contact/Insured

ALEXANDER K DAMIEN
BLK 218C BOON LAY AVENUE, #06-299,
643218, Singapore

slayer2damien@hotmail.com

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions NOT REPORTED

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type	Document SubType					
+ Upload Documents						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED		
Accident Statement	Reports & Statement		Merimen			
LKKInvoice1[1].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	September 19, 2019		
LKKAdjustment1a[1].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	September 19, 2019		
LKKInspection[1].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	September 19, 2019		
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	September 19, 2019		
RENTAL MILEAGE.pdf	Forms / Claim Documents	Letter of undertaking	LKK AUTO CONSULTANTS PTE LTD (TP)	September 19, 2019		
RENTAL RECEIPT.pdf	Forms / Claim Documents	Letter of undertaking	LKK AUTO CONSULTANTS PTE LTD (TP)	September 19, 2019		

English (default) ▾ LKK AUTO CONSULTANTS PTE LTD (TP) ▾				SUB-TYPE	AUTHOR	DATE UPLOADED
	SERVICE REQUESTS	MESSAGES	CLAIMS	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	September 19, 2019
 PAYMENT BREAKDOWN - EXPRESS SETTLEMENT FORM.pdf				Others	LKK AUTO CONSULTANTS PTE LTD (TP)	September 19, 2019
 AUTHORISATION TO ACT.pdf				POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	September 19, 2019
 LETTER TO OI.pdf				Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	September 19, 2019
 LKK Reinspection Photos.pdf				Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 15, 2019
 TP MANDATE IA-SLM 1674M.pdf				Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 15, 2019
 After paint Photos.pdf				Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 15, 2019
 MARKED ESTIMATE.pdf				Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 15, 2019
 LKK Inspection Photos.pdf				Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 15, 2019
 SLA1767S (4th) Front video.MOV				Videos	ANG Richard	July 6, 2019
 SLM6122G (7th) Front video.MP4				Videos	ANG Richard	July 6, 2019
 SLA1767S (4th) SAS Report.PDF				GIA Report	ANG Richard	July 6, 2019
 SJF1610H (2nd) SAS Report.PDF				GIA Report	ANG Richard	July 6, 2019
 SLM7392L (3rd) SAS Report.PDF				GIA Report	ANG Richard	July 6, 2019
 SHA1437S (1st) SAS Report.PDF				GIA Report	ANG Richard	July 6, 2019
 TP GIA REPORT-SLM1674M.PDF				GIA Report	LKK AUTO CONSULTANTS PTE LTD (TP)	June 3, 2019
 TP - IA.pdf				Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	May 30, 2019
 LKK SURVEY PHOTO.pdf				Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 30, 2019
 TP PRI FROM WORKSHOP.msg				Workshop	DHAKAL Raghav	May 29, 2019