



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS/EQI19009511/Avd3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110

Date : 06-08-2019



Code : EQI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SMF 3689H
Policy No.	DMPPHQ18-007725	Coverage (\$)	0.00
Claim No.	DM19HO01445-JG	Excess (\$)	600.00
Assign From	JOEL GOH	Assign Date	29/05/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA NOAH HYBRID	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	ZWR800336286	Colour	WHITE
Odometer	16224	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	6 mm
L/H Front Tyre	195/65 R15	GOODYEAR	6 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	6 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/05/2019	Inspection Date	30/05/2019
Survey held at	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700		

5a. Remarks

A) THE MARKET VALUE IS S\$120,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------