

Surveyor:

Fauziah

DOI:

ASSIGNMENT

29/7/19

Date / Time:

30/5/19

Registered in Merimen:

30/5/19

Pre-assign / CCU / FTE



Insured Vehicle No. : SHA 34020

Name of Insured : CTP

Insured Tel No. : HP:

Excess Sec II: S\$ D.O.A: 28/05/19

Is driver the owner? (YES / NO) Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No. : (V/L) YES / NO

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SKA 51740



INSRS:

WSP:

Tel:

Liability:

RMKS:

pml



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SKA 51740-X

SHA 34020 - CTP / III 1900 9509 / 5 July 2019; 001 617118
- CTP / III 2021179 / p63 : 001 201118

7/6/19

seek liability via merimen.

7/6/19

liability clear via merimen

7/6/19

email workshop liability clear.

19/7/19

- FCU -> type mandate

26/7/19

- FCU -> IUR to close

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(

Agreed / Assessed) BOLA S/N No.:

9

If NO or B 28, Ass. Lia:

Repair Cost: w/6/19

S\$

1964.52

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

3w-w (31w) x 3

days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4 35w-w.

Total:

S\$

2264.52

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

2264.52

Name 1:

Performance Motor Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

CC3/11119009569/T1wa3

Vivian

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 157431599A GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255285)

103, Alexandra Road
Sime Darby Performance Centre
Singapore 119942
Fax: 64747770

180, Empress Arany Road
East Coast Centre
Singapore 439185
Fax: 63449773

115, Alexandra Road
Sime Darby
Singapore 119942
Fax: 64746621
64746624
(ATTENTION)
(MOTORCARS)

Acknowledged by Repairer

Signature:

Date:

GST REG. NO : M2 - 0020081 - X

30 MAY 2019

ESTIMATE



Estimate No. : b1 51351
Date Estimated : 29/05/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Lok Lian Leong
1 Tanjong Rhu Road
#05-03

Singapore 436879

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ5174D	DX52304	31/01/2013	5201A	0

DESCRIPTION

Replacing right front door

VALUE

850 1,275.00

Spray right front door

796 885.00

To conduct checks on all doors and bootlid central locking system for proper function.

150 177.00

To carry out body cavity preservation.
(Per panel).

100 X 118.00

Sundries

40 X 80.00

Total Labour 1: 2,535.00

DESCRIPTION

FRT RH DOOR
SEAL DOOR FRT

QTY	PRIC
1	1,774.50
1	168.85

VALUE

Ry 1,774.50

Vn. x 168.85

Total Parts : 1,943.35



29/05/2019
Tanjong Rhu
97495749
Wf
3 days

Labour 1	:	2,535.00
Parts	:	1,943.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	313.48
Grand Total	:	4,791.83

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

HAR 35

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 51351**
Date Estimated : **29/05/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -

Lok Lian Leong
1 Tanjong Rhu Road
#05-03

Singapore 436879

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ5174D	DX52304	31/01/2013	520iA	0

DESCRIPTION	ACCOUNT:		
	ORIGINAL PRICE	DISC. %	NETT
To make good the front right door and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job	850.00	0	850.00
To respray front right door.	796.00	0	796.00
To conduct checks on all doors and bootlid central locking system for proper function.	150.00	0	150.00
Sundries	40.00	0	40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
				#
				#
				#

QD	USED PARTY	DATE
	Taufik	27/5/19
	Ltk	3

Total Labour : 1,836.00
Total Parts :
Total Repair Costs less Excess: 1,836.00
GST @7%: 128.52
Grand Total : 1,964.52

LOSS OF USE = \$100 X 3 DAYS

4M Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401339W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

285, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64796501 (After Sales)
64796624 (Motorrad)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Any damaged part(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

3020081 - X

30 MAY 2019

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.	: b1 51351	Page No. :	1 of 4
Date Estimated	: 29/05/2019		
Prepared By	: Joseph Yaguel		

- ESTIMATE REPAIR FOR -	- ACCOUNT - 219
Lok Lian Leong	India Int'L Insurance Pte Ltd
1 Tanjong Rhu Road	64 Cecil Street
#05-03	#04-05 IOB Building
Singapore 436879	Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ5174D	DX52304	31/01/2013	520iA	0

DESCRIPTION	VALUE
Replacing right front door	850 1,275.00
Spray right front door	796 885.00
To conduct checks on all doors and bootlid central locking system for proper function.	150 177.00
To carry out body cavity preservation. (Per panel).	100 ? 118.00
Sundries	? 80.00

Total Labour 1: 2,535.00

DESCRIPTION	QTY	PRIC	VALUE
FRT RH DOOR	1	1,774.50	RY 1,774.50
SEAL DOOR FRT	1	168.85	x 168.85
Total Parts :			1,943.35

Claim No. 01 / Uninsured losses / Direct Settlement

Form No. _____ Claim No. _____

Date & Time 29/7/19 11/15 Excess 35

Surveyor's Name Tanjun Sign Tanjun

Surveyor's Tel 97445749. Authored Yes / No

Approved Date 29/7/19 Time

REPAIR PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's Email Tanjun C. Chuan

No. of Working Days Recommended 3 days



Labour 1	:	2,535.00
Parts	:	1,943.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	313.48
Grand Total	:	4,791.83

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	30 May 2019 09:37	Cim Dtl Modified	Claimant's Name: -> LOK LIAN LEONG. Claimant's ID: -> S12347351.	[A] HOW MEI KWAN
2	30 May 2019 09:37	Cim Veh Model Changed	(204864) BMW 520I 2.0 D/AB 2WD 4DR GAS/D NAV (A).	[A] HOW MEI KWAN
3	30 May 2019 09:37	Cim Created	Reg No: SKQ5174D. Acct Date: 2019/05/28. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: AXA Insurance Pte Ltd (HQ). Workshop: Performance Motors Limited (Alexandra)	[A] HOW MEI KWAN
4	30 May 2019 09:37	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	30 May 2019 09:37	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/11	[A] HOW MEI KWAN
6	30 May 2019 09:37	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	30 May 2019 09:38	Label Added	(30653):Direct Settlement.	[A] HOW MEI KWAN
8	30 May 2019 09:38	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] HOW MEI KWAN
9	07 Jun 2019 12:03	Adj Mandate Request	Cur,Req:0.00:PODS Liability: 100% Remarks: BOLA 9. O/D coming out from minor road	[A] VIVIAN LAU PEI FENG
10	07 Jun 2019 12:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/11	[I] Sherini Pillai
11	07 Jun 2019 12:17	Adj Mandate Set	Approved:0.00.	[I] Sherini Pillai
12	30 Jul 2019 16:44	Cim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD. Insured ID: -> 9303821R.	[A] HOW MEI KWAN
13	23 Sep 2019 12:10	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
14	23 Sep 2019 12:10	Cim Dtl Modified	JPJ Reg. Date: -> 2013/01/31.	[A] JOANNE LEE KHANG MIN
15	23 Sep 2019 12:10	Cim Details Notified		[A] JOANNE LEE KHANG MIN
16	24 Sep 2019 10:07	Adj Mandate Request	Cur,Req:2264.52:PODS Liability: 100% Quantum: (a)CORw/GST: \$1,964.52 + (b)LOU (3days x \$100.00): \$300.00 = Total: \$2,264.52 Vehicle Model: BMW 520 (1997cc) 3 re commendation repair days For your approval please.	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type None



ACTIVITY

[07/06/2019 12:21] VIVIAN LAU PEI FENG:
liability clear via merimen
[07/06/2019 12:03] VIVIAN LAU PEI FENG:
seek liability via merimen

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2288155	23 Sep 2019	OD/TP Case	Motor	LKK Auto	LKK Auto	SKQ5174D	SHA3402D	11.77

Print Received Message

This mail is associated with :

***SKQ5174D (MCT19050849)**
[SHA3402D]

TP

LOK LIAN LEONG

May 28 2019 6:00PM

[COMFORT TRANSPORTATION PTE LTD]

Performance Motors Limited

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 24/09/2019 10:15 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2264.52) - SKQ5174D - Claim Handler: Sherini Pillai

Approved:2264.52.



redefining / insurance

TP

AXA Insurance Pte Ltd
 1600 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

account number
 00303

Certificate of Insurance

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1963 - Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	LOK LIAN LEONG	Certificate number	GA087200 / 1
Cover	Comprehensive	Chassis number	WBAXG12040DX52304
Plan name	Private	Engine number	A2310370N208208
NCD applicable	50%		
Vehicle registration number	SKQ51740		
Period of Insurance	from 31/01/2019 to 30/01/2020 (both dates inclusive)		
Finance loan company	UNITED OVERSEAS BANK LIMITED		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any Named Driver as stated in the Policy:
 1. YANG MARY
 (c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 400.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorized Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if you have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to this effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).
 The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.



India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
Attention: Motor Claims

"Without Prejudice"

Your Ref:

Our Ref:

Date:

Subject:

10 September 2019

ACCIDENT INVOLVING VEHICLES SKQ5174D & SHA3402D ON 28.05.2019

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$	1964.52
Loss of use	:	S\$	300.00 (S\$100.00 x 3 days)
Total	:	S\$	2264.52

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & Certificate of Insurance
3. Copy of Letter of Authorisation & Discharge Voucher

Performance Motors
Limited
1800-Call-BMW
(1800-2255-266)

www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel AfterSales:
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales:
6319 0527
Fax 6479 6624

280
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel AfterSales:
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Ventage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401559W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Cresendo Lagman
Customer Service Manager, Body & Paint

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SKQ 5174D & SHA3402D ON 28-05-19.

I, LOK LIAN LEONG owner of Vehicle Registration No. SKQ 5174D
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all
documents whatsoever in relation to this matter and to accept and receive any payment
due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement
amount in respect of such claim shall constitute the full discharge of my claim in respect of
such loss and damage.

Signed by:


Name: LOK LIAN LEONG (Date) 29/7/19
NRIC No.: S1234735I

In the presence of:


Name: JOSEPH YAGUEL (Date) 29/7/19
NRIC No.: _____

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III-Direct Settlement (PODS)

India Ref: MCT19050849
Claimant Ref: SKQ5174D

We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd Mr. Tan Jhi from LKK Auto Consultants P/L (name of Surveyor) with respect to the amount claimed for S\$ 1964.52 (repair cost), S\$ 300.00 (loss of use/~~rental~~), S\$ - (search fee), vehicle no. SKQ5174D that was damaged pursuant to the accident which occurred on 25-5-19 (date) at Jalan Raja M/Ialan Rama Ramg (location) involving vehicle no. SHN34020 (insured vehicle). This is pursuant to the inspection conducted on 29.7.19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Lok Lian Leong ("the third party claimant") of vehicle no. SKQ5174D to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKQ5174D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2264.52 to Performance Motors Ltd

Dated this 26th day of Sep 20 19

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

WITNESS:

Signature:



Signed by appointed Surveyor

Name:

NRIC:

Address:

Nationality:

Occupation:

LKK Auto Consultants Pte Ltd

199607198P

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park (P1902)

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 1974S1559W GST Reg: No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190833/830 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1383150

Date IN : 29/07/2019

Cust. Svc. Advisor: Joseph Yaguel

Page No. : 1 of 1

Invoice Number : 2145059 / WSB

Invoice Date : 04/09/2019

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Lok Lian Leong
1 Tanjong Rhu Road
#05-03

Singapore 436879

- INVOICE TO - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.
SKQ5174D

CHASSIS NO.
DX52304

REGN. DATE
31/01/2013

MODEL
520IA

MILEAGE
93690

- - - - LABOUR 1 - - - -

To make good the front right door and knock out dented area caused by the accident. To remove and install body parts in order to carry out paiting job.

To respray front right door.

To conduct checks on all doors and bootlid central locking system for proper function.

Sundries

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 2.5.2019. 3RD PARTY CAR : SHA3402D.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO CONSULTANTS PTE LTD ON 29.7.2019 AT 11.15 AM. AUTHORISED REPAIR BY MS VIVIAN LAU FROM LKK ON 7.6.2019 VIA E-MAIL.

PROPOSE LOSS OF USE = \$100X3. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.

NETT

850.00

796.00

150.00

40.00

0.00

0.00

Total Labour 1: 1,836.00

Labour Charges : 1,796.00
Parts Charges : 0.00
Lubricant/Misc : 40.00

Total Labour & Parts Charges : S\$ 1,836.00
Less Insurance Excess : S\$ 0.00
Invoice Total Amount Exclude GST : S\$ 1,836.00
GST @ 7% : S\$ 128.52
Invoice Total Amount Include GST : S\$ 1,964.52

Computer generated invoice. No signature is required.

Amount Payable Include GST : S\$ 1,964.52

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Sep 2019 Edit Reg		29 Jul 2019 00:00 Edit Adj Rpt	S\$1,836.00 Edit Estimates	S\$1,836.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	LOK LIAN LEONG, ID: S12347351								
Vehicle Reg. No.:	SKQ5174D	Date of Loss:	28/05/2019 18:00 - :59 [75 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19050849	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA3402D	Policy No. (Claimant):	-						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 11/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (24/09/2019): Alert - Adj Mandate Approved (S\$2264.52) - SKQ5174D - Claim Handler: Sherini Pillai - III_SG (07/06/2019): Alert - Adj Mandate Approved (S\$0.00) - SKQ5174D - Claim Handler: Sherini Pillai									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKQ5174D (MCT19050849)
[SHA3402D]
TP
LOK LIAN LEONG
May 28 2019 6:00PM
[COMFORT TRANSPORTATION PTE LTD]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter

View View in Browser

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/09/19 10:05	Odometer Reading	1	Load JPG	☒
2	24/09/19 10:05	Chassis Number	1	Load JPG	☒
3	24/09/19 10:05	General View	1	Load JPG	☒
4	24/09/19 10:05	General View	1	Load JPG	☒
5	24/09/19 10:05	General View	1	Load JPG	☒
6	24/09/19 10:05	General View	1	Load JPG	☒
7	24/09/19 10:05	General View	1	Load JPG	☒
8	24/09/19 10:05	General View	1	Load JPG	☒
9	24/09/19 10:05	General View	1	Load JPG	☒
10	24/09/19 10:05	General View	1	Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/05/19 09:38	TP ESTIMATE	1	Load PDF	
2	30/05/19 09:38	TP GIA REPORT	1	Load PDF	
3	30/07/19 22:03	TP ESTIMATE - MARKED	1	Load PDF	
4	23/09/19 14:21	WORKSHOP INVOICE	1	Load PDF	
5	23/09/19 14:21	LOD	1	Load PDF	
6	27/09/19 09:15	AUTHORISATION TO ACT FORM	1	Load PDF	
7	27/09/19 09:15	DISCHARGE VOUCHER	1	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	31/05/19 08:48	Singapore Accident Statement	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19009569/T1PA3Q2

Date: 27/09/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SKQ5174D Insured Vehicle No: SHA3402D
 Date of Loss: 28/05/2019 Nature of Claim: TP Claim No: MCT19050849

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKQ5174D
 Make & Model: BMW 520i, 2.0 D/AB 2WD 4DR GAS/D NAV (A) Engine No: A2310370N20B20B
 Reg. Date: 31/01/2013 (Man. Year: 2012) Chassis No: WBAXG12040DX52304
 Colour: Grey Odometer: 93690 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,023.35	40.00	1,983.35	98.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,455.00	1,796.00	659.00	26.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,478.35	1,836.00	2,642.35	59.00
+ GST 7.00/7.00% (S\$)	313.48	128.52	184.96	59.00
Nett Amount (S\$)	4,791.83	1,964.52	2,827.31	59.00
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
	Nett Liability (S\$)	2,264.52		

INSPECTION

Date of Assignment: 29/07/2019
 Date Inspected: 29/07/2019 Inspected At: Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2019)
Parts:	143	BMW 520I 2.0 D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ5174D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*40.00 FS
2	1		*FRT RH DOOR	Repair	1,774.50 FS	*- FS
3	1		*SEAL DOOR FRT	Not Necessary	168.85 FS	*- FS
F=Franchise part, S=SpcNett.						
Total Parts (S\$)					2,023.35	40.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACING RIGHT FRONT DOOR	New	1,275.00	850.00
2	SPRAY RIGHT FRONT DOOR	New	885.00	796.00
3	TO CONDUCT CHECKS ON ALL DOORS AND BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	177.00	150.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	0.00
Gross Labour Cost (\$\$)			2,455.00	1,796.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >