

Steve (LKK) W/L Reivudire 30/5/19, 1.45pm
83228813 5 days L/S
Ry Af spy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Blk 10, #01-20

Sin Ming Industrial Est. Sec C

Singapore 575645

Tel: 6452 1208

Fax: 6452 0614

97535832

Vehicle:	SGK9799D
Model:	MADZA3
Chassis:	

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	FRONT DOOR LH / DD	1	\$ 1,919.20	20%	\$ 1,535.36	
2	FRONT DOOR LH CHROME MLDG / CR4 (upper)	1	\$ 256.20	20%	\$ 204.96	
3	FRONT DOOR LH RUBBER BEADING ?	1	\$ 198.20	20%	\$ 158.56	
4	FRONT DOOR LH REGULATOR / DD	1	\$ 179.60	20%	\$ 143.68	
5	FRONT DOOR LH REGULATOR MOTOR X	1	\$ 358.00	20%	\$ 286.40	
6	FRONT DOOR LH LOCK ?	1	\$ 265.60	20%	\$ 212.48	
7	FRONT DOOR LH LOCK CABLE X	1	\$ 165.20	20%	\$ 132.16	
8	FRONT DOOR LH FRAME GARNISH (stick) NLC	1	\$ 152.00	20%	\$ 121.60	
9	FRONT DOOR LH PROTECTOR MLDG (lower) / CR4	1	\$ 85.58	20%	\$ 68.46	
10	FRONT DOOR LH HANDLE ?	1	\$ 185.30	20%	\$ 148.24	
11	FRONT DOOR LH TRIM ?	1	\$ 1,795.00	20%	\$ 1,436.00	
12	FRONT DOOR LH WINDOW SWITCH X	1	\$ 165.50	20%	\$ 132.40	
13	FRONT FENDER LH X R	1	\$ 858.70	20%	\$ 686.96	
14	ROCKER PANEL LH X	1	\$ 858.00	20%	\$ 686.40	
15	REAR DOOR LH / DD	1	\$ 1,920.30	20%	\$ 1,536.24	
16	REAR DOOR LH PROTECTOR MLDG X	1	\$ 85.58	20%	\$ 68.46	
17	B PILLAR LH X R	1	\$ 858.50	20%	\$ 686.80	
18	A PILLAR LH X R	1	\$ 1,030.20	20%	\$ 824.16	
19	FRONT DOOR LH HINGE UPPER ?	1	\$ 85.50	20%	\$ 68.40	
20	FRONT DOOR LH HINGE LOWER ?	1	\$ 85.50	20%	\$ 68.40	
20	FRONT DOOR LH CHECKER X	1	\$ 198.00	20%	\$ 158.40	
20	FRONT DOOR LH GLASS X	1		20%		
TOTAL:					\$ 9,206.13	

	SPECIAL NETT	QTY	PRICE	SURVEYOR MARKING
1	FRONT FENDER INNER SHIELD CLIP X		\$ 35.00	
2	FRONT DOOR LH TRIM CLIP / NLC		\$ 35.00	20
3	FRONT WINDSCREEN SEALANT X		\$ 50.00	
4	FRONT WINDSCREEN PRIMER X		\$ 15.00	
5	A AND B PILLAR SEALANT X		\$ 100.00	
SPECIAL NETT			\$ 235.00	

	LABOUR	PRICE	SURVEYOR MARKING
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	\$ 2,400.00	600
2	TRANSFER FRONT AND REAR DOOR LH COMPONENTS	\$ 250.00	50
3	R&R FRONT WINDSCREEN	\$ 150.00	X
4	RUSH PROOFING	\$ 150.00	30
5	CHECK WIRING	\$ 150.00	30
1	MOUNT WORKBENCH TO ASSIST REPAIR	\$ 250.00	X
2	TO DISMANTLE FRONT SEAT, SEAT BELT AND TRIM TO ASSIST REPAIR	\$ 300.00	X
3	TO DISMANTLE DASH BOARD TO ASSIST REPAIR A PILLAR	\$ 250.00	X
4	TO SPRAY PAINTING ON FRONT FENDER LH, FRONT DOOR LH INNER/OUTER, A PILLAR, B PILLAR, REAR DOOR LH, ROCKER PANEL MIRROR	\$ 1,600.00	800
5			
TOTAL:		\$ 5,500.00	

PARTS	\$ 9,206.13
-------	-------------