

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 03 Jun 2019

Preliminary Advice

Insured Vehicle No	: GY1427G	Accident Date	: 28/05/2019
TP Vehicle No	: SHD9884R	Assignment Date	: 30/05/2019
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 4
Date of Inspection	: 31/5/2019		
Inspection At	: TRANS-CAB AUTO SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	82,124.90
Revised Amount	:S\$	11,775.32
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,775.32

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.