

149 Cecilia

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

AXA

LKK
mon

10/06/19

after 11a

19/03/2019

Owner: SKYWAY MOTOR PTE LTD

Not withstanding
Resurvey After Repair
11 hrs @ 2250h 2 days

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLZ4352D

1pc	front RH headlamp	CM	\$ 1,759.40	✓
1pc	front RH headlamp lower bracket	CMT	\$ 45.00	✓
1pc	front RH headlamp top bracket		\$ 28.85	X
1pc	front centre grille base	RM	\$ 542.20	X
1pc	front centre grille chrome	RM	\$ 108.00	X
1pc	front centre grille outer garnish	RM	\$ 385.00	X
1pc	front centre grille "HONDA" logo	RM	\$ 58.85	X
1pc	front bumper	RM	\$ 927.50	✓
1pc	front bumper RH side retainer		\$ 38.10	✓
1pc	front bumper lower spoiler	RM	\$ 351.00	X
20pcs	front bumper clip @\$5.00	RM	\$ 100.00	50
1pc	front bumper reinforcement	RM	\$ 321.50	✓
2pcs	front bumper RH fog lamp cover	RM	\$ 85.58	✓

less 20%


\$ 4,750.98

\$ 950.20

\$ 3,800.78

wiring
tuffkote
spray painting
labour charges
Total

\$ 80.00 2cl
RM \$ 50.00 X
\$ 600.00 22cl
\$ 600.00 20cl
\$ 5,130.78



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature
Date