## ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	20:05HRS	BUS REGISTRATION NUMBER
ACCIDENT DATE	24-May-19	BUS TYPE (SD/DD)
BUS CAPTAIN NAME GOH SAN HNG		BUS ROUTE NUMBER
EMPLOYEE NUMBER		BUS ADVERTS (Y/N)
	and the second s	

\$8\$6357H
SD
N

## SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

Part No.	Part or Item Description	Quantity	<b>Total Cost</b>
77200612	SIDE MARKER LIGHT CAA	1	\$80.00
77014459	DOWEL (ANCHOR) repair	. 2	\$4.80
	27 1/2	The same of the sa	
The same of the sa	The state of the s		
1 - 1 - 1 - 1		9	
14			
	80	7% GST	\$5.94
	The second secon	FINAL TOTAL COST	\$90.74

## SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
TO REPLACE/REPAIR THE DAMAGED PARTS	3 DAYS	650 \$1,950.00
PUTTY AND SPRAY PAINTING	3 DAYS	750 \$1,850.00
at the second se	and the state of t	
		1400
	7% GST	\$273.00
	FINAL TOTAL COST \$4,173.00	

PAGE 1

## **ESTIMATED ACCIDENT REPAIR COST**



SECTION 3: REPAIRS TO BUS ADVERTISMENT VINYLS/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST

SECTION 4: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST

SECTION 5: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

Date In For Repairs **Date Out From Repairs** Number of Days Under Repair \$2,100.00

BUS TYPE (SD / DD)

LOSS OF USE COST

SU	MMARY	
SECTION NO.	COST	
1	\$90.74	
2	\$4,173.00	
3	Fall of parts	
4	A MALA SOLVE STATE	
5	\$2,100.00	
ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5)	\$6,363.74	

Passer

4p 20000068

3 days

10/06/19 P 1230

Resy after report

PAGE 2

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after topray painting

- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: