



Vivian

Section A - Accident Details

Registration Number	SHD6303X
Case Reference Number	TAX/05/19/2138
Registration Date	28/6/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YAP BOON KWEE
Type of Accident	Open Door Case
Accident Date and Time	30/5/2019 12:45 AM
Accident Reported Date and Time	30/5/2019 2:16 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	30/5/2019 12:30 PM
Replacement Vehicle issued?	No
Job Card Number	24101753
Special Instruction to ARC, if any	TOWED \$60
Prepared Date and Time	31/5/2019 10:41 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Top View

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$600.00
Total Spray Cost	\$1,314.00	\$650.00
Total Spare Part Cost	\$3,873.38	\$1,849.55
Total Other Cost	\$729.00	\$170.00
TOTAL COST	\$6,930.38	\$3,269.55 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / III
ARC / Surveyor Sign Off Date	31/05/2019 3:37 PM	31/05/2019 2:47 PM
Signature		
Remarks	p/p repair, photo before paint.	

P/P \$3269.55/- 5 days



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757706
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 15/06/2019

User ID : PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1906-0099	Invoice Number	
Quotation Date	10.06.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$600.00
Total Labour	\$1,014.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$50.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,314.00	\$650.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$84.00	\$60.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$50.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$40.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$729.00	\$170.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67002-47070	DOOR FRT/LH	1.00	\$894.40	25.00	\$670.80	Replace	Replace
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		75720-47021	DOOR BELT FRT/LH	1.00	\$69.20	25.00	\$51.90	Replace	Replace
		69210-74030	DOOR OUTER HANDLE FRT/LH	0.00	\$370.80	0.00	\$0.00	Replace	Not Given
		87940-47310	MIRROR ASSY, LH	1.00	\$1,224.90	25.00	\$918.68	Replace	Replace
		81740-52040	MIRROR LAMP LH	1.00	\$65.30	10.00	\$58.77	Replace	Replace
		87961-47150	MIRROR GLASS LH	0.00	\$142.50	0.00	\$0.00	Replace	Not Given
		87945-74010	COVER, OUTER MIRROR, LH	1.00	\$107.40	100.00	\$0.00	Replace	Repair
		67004-47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair
		75740-47021	DOOR BELT RR/LH	0.00	\$69.20	0.00	\$0.00	Replace	Not Given
		69211-74020	DOOR OUTER HANDLE RR/LH	0.00	\$69.80	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/06/2019

User ID : PohSuan

	61602-47091	FENDER RR/LH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	✓
		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
	62720-47031	QUARTER GLASS RR/LH	0.00	\$168.10	0.00	\$0.00	Replace	Not Given	X
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
Total				\$5,089.30		\$1,849.55			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1849.55
+ 600.00
+ 820.00

3269.55