

ASS. REC. BY:

REF: CS/CT19009747/ Kqd3n2 | Special Instruction:

Surveyor: Kunsh **ASSIGNMENT (Office)**From (Person): Elaine Chong of CTL Date/Time: 31.5.19 17.55p.m

Estimated Cost: _____ Bill to: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLT 23522 Insured: SCV 2299Rat Workshop m/s Accord Auto Tel: 64819517/85715140of 10 Amk Ind Park 2A #03-11Policy No: DMPCSN30TB13B00 Claim No: SNM19D702440C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29.5.2019
(Client's Record) 462019CA / REV / REP. / REV 24 HRS Rev H.O.D. Endorsement: _____Date/Time: 36 2019 3.30pm Person Contacted: Jessy Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLT 23522 - x</u>
	<u>SCV 2299R - CS/CT19009747/ R1vd3</u> <u>DOB - 29/05/2019</u>
<u>11/7</u>	<u>LI Sup @ 7400d encil @ confirmed (Red)</u>

ASSIGNMENT

From:

Date:

4.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 23522

at Workshop n/s Accord Auto

of 10 AMK Incl Park 2A #03-11

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

831K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

16 days

Res.: Yes or No

Lum Sum:

20 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLT 23522 Yr Regn: 09.11

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda A1 J12 C.C 1339

Colour:

N. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMG 68509S 238262

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size:

F: Dayton 195/55R15

R: B.1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

2 mm

R/Bal.

4 mm

L/Bal.

2 mm

L/Bal.

4 mm

D.O.A.

29/5/19

D.O.I.

4/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Benny Flor

RECEIVED 10 JUL 2019

Date/Time, File Pass to?

1) 18/7/19

Date/Time, File Return to?

2)

☐

Prel. Report

☐

Final Report

Days Of Repair:

16

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

T + RS, 31

Photos

Others

TOTAL

Report Format :

MER-TP

Lump Sum / I.B.F. (\$

7400

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 May 2019		31 May 2019 17:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant:	ACCORD CAR LEASING PTE. LTD., Co. Reg. No.: 201803722K								
Vehicle Reg. No.:	SLT2352Z	Date of Loss:	29/05/2019 17:00 - :59						
Claim Type:	TP / SNM19D202440C02	Policy/Cover Note No.:	DMPCSN3075131800						
Vehicle Reg. No. (Insured):	SCV2299R	Policy No. (Claimant):	5098053354-01						
		Excess:	S\$3,500.00						
Repairer:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point, 568047 Ang Mo Kio - Tel: 64819517/85715140								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

BMW PREMIUM SELECTION.

CERTIFIED PRE-OWNED BY PERFORMANCE PREMIUM SELECTION.

[Find out more](#)


Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)
[Almost 2018 Toyota C-HR Hybrid 1.8A GT 1.8W Interest!](#)


High Specifications G Model
Only 500km - 5Car And Hybrid
Battery Warranty!
Auto Zoom Enterprise


[Browse by Category](#)
[Sort by Date Posted](#) 20 results/page

5 vehicles

Honda Jazz

Search Selection	Model	Price	Depreciation	Reg Cost	Eng Cap	Mileage	Veh Type	Status
Honda Jazz		Any	Any	2011	Any	Any	Any	Available



Honda Jazz 1.3A L

\$30,800

\$9,680 /yr

24-Aug-2011

1,339 cc

131,423 km

Hatchback

Available

Japan Hottest Hatch! Genuine Low Mileage Done With Only 1 Owner! Beautiful Condition! Premium Dealing Contact/SMS Only Our Best Top Appointed Sales Person Directly For Viewing And Testing Immediately!

Posted: 05-Jun-2019 Tags: 2011 Honda Jazz, 2011 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda



Honda Jazz 1.3A L

\$28,800

\$8,630 /yr

11-Aug-2011

1,339 cc

124,415 km

Hatchback

Available

(100% Quality Buy!) Vehicle Fully Done With With Premium Grooming And Brand New Paint Coat. Purchase Comes With 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assistance. STA/VICDM/AA ...

Sincere Motoring

Posted: 03-Jun-2019 Tags: 2011 Honda Jazz, 2011 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda



Honda Jazz 1.3A L (OPC)

\$26,800

\$7,790 /yr

10-Aug-2011

1,339 cc

91,000 km

Hatchback

Available

Very Comfort Drive, Very Spacious And Clean Interior, Pristine Condition, Well Taken Care By Previous Owner, View To Believed, Hurry Call Now To Make An Appointment To View And Test Drive.

Edmund Motor Pte Ltd

Posted: 01-Jun-2019 Tags: 2011 Honda Jazz, 2011 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda



Honda Jazz 1.3A L

\$26,800

\$9,390 /yr

28-Mar-2011

1,339 cc

117,446 km

Hatchback

Available

Beautiful Metallic Purple, 2nd Careful Owner, Under Agent Warranty, Well Maintained, Seldom Used, Per Year 14,235 KM Only. Accident-Free, Undergone A 120 Points Safety Check By Our In House Mechanics ...

Jia Leong Trading Enterprise

Posted: 01-Jun-2019 Tags: 2011 Honda Jazz, 2011 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Honda Jazz 1.3A L

\$33,800

\$9,360 /yr

22-Dec-2011

1,339 cc

110,019 km

Hatchback

Available

New Arrival! Very Well Maintained Unit! Genuine Low Mileage! Elegant Silver Spray Paint! Very Well Maintained Interior! Flexible Loan Packages Available! Trade In Welcome! Don't Miss!

Posted: 31-May-2019 Tags: 2011 Honda Jazz, 2011 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Search Selection	Model	Price	Depreciation	Reg Cost	Eng Cap	Mileage	Veh Type	Status
------------------	-------	-------	--------------	----------	---------	---------	----------	--------

[For old advertisements, view Expired ads](#)
[20 results/page](#)
[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3722K
Vehicle Details	
Vehicle No.:	SLT2352Z
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	HONDA JAZZ 1.3L A
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	L13211038293
Chassis No.:	JHMGE685095238267
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$19,656.00
Original Registration Date:	23 Sep 2011
First Registration Date:	23 Sep 2011
Transfer Count:	4
Actual ARF Paid:	\$19,656.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Sep 2021
PARF Rebate Amount:	\$11,793.00
Intended COE Rebate Details	
COE Expiry Date:	22 Sep 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$51,000.00
COE Rebate Amount:	\$11,701.00
Total Rebate Amount:	\$23,494.00

The information contained herein is correct as at 06 Jun 2019

OK

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle No.:	SLT2352Z
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	HONDA
Vehicle Model:	HONDA JAZZ 1.3L A
Chassis No.:	JHMGE68509S238267
Propellant:	Petrol
Engine No.:	L13Z11038293
Engine Capacity:	1339 cc
Maximum Power Output:	73.0 kW (97 bhp)
Maximum Laden Weight:	1540 kg
Unladen Weight:	1090 kg
Year Of Manufacture:	2009
Original Registration Date:	23 Sep 2011
Lifespan Expiry Date:	-
COE Category:	A - Car (1600cc & below)
Quota Premium:	\$51,000.00
COE Expiry Date:	22 Sep 2021
Road Tax Expiry Date:	22 Sep 2019
PARF Eligibility Expiry Date:	22 Sep 2021
Inspection Due Date:	22 Sep 2020
Intended Transfer Date:	30 May 2019
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

[OK](#)
[Print](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/05/2019 13:37
Date Of Accident	29/05/2019 17:35
Exact Location Of Accident	TAMPINES AVENUE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT2352Z
Insured/Policyholder	
Name Of Registered Owner	ACCORD CAR LEASING PTE. LTD.
Co Reg No	201803722K
Email Address	ACCORDCARLEASING@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97679518
Alternative Phone No	OFFICE-64819518

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ 1.3L A
Exact Purpose for which vehicle was being used at time of accident	GRAB
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5098053354-01
Cover Note Number	

Driver

Name of Driver	CHAN KOK FAI
NRIC No	S9114479D
Date Of Birth	24/04/1991
Occupation	OUTDOOR
Date Of Driving Pass	12/04/2013
Driving Experience	6 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92313886
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 781 YISHUN RING ROAD #09-3548
Postcode	760781
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER & LEASEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK POLICE DIVISIONAL HQ (G DIVISION)
Police Station Address	ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2440000 - FAX NO: 64443009
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ACCIDENT STATEMENT AS ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCV2299R
Vehicle Make/Model/Colour	HONDA / CIVIC / RED
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUHAMMAD IRFAN BIN MAZLAN
NRIC/Passport Number	S9636731G
Contact Number	
Address	

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHA7533H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver CHEW YUEN ONN ZHAO YUAN 'AN
NRIC/Passport Number S7414772J
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name CHAN KOK FAI
Approximate Age 28
Injuries Sustain
Injured person in which vehicle? SLT2352Z
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address BLK 781 YISHUNG RING ROAD
#09-3548
Postcode 760781

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

ACCORD CAR LEASING PTE LTD

RO: NO. 201803722K

Policyholder's Signature: Quak Meng Lane 3

Date & Time: 20.05.2019 Singapore 159723

Driver's Signature
(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/TIN No.:


Joelle Tan

AMK AUTOPoint PTE LTD

20.05.2019

Sketch Plan #2

SKETCH PLAN Vehicle A: 3LT 43522 Vehicle B: SCV 2299R Vehicle C: 21W 95311



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date of Accident: 29/05/2019 Time of Accident: 19:35

Please refer to Police Report (Report No: 6120190529/7050).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

ACCORD CAR LEASING PTE LTD
 ROC NO. 351803722K
 1099 Bukit Merah Lane 3
 #01-80 Singapore 159723

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: J Delle Tan
NRIC/FIN No. AMK Auto Point Pte Ltd
30.05.2019

Police Report



**SINGAPORE
POLICE FORCE**



G-20190529-7050

1 of 2

POLICE REPORT (NP299)

Report No.: G/20190529/7050

Police Station Of Origin
Bedok Division HQ
30 Bedok North Road SINGAPORE 469878
Tel No. 1820 2440003

Date/Time Report Made 28/05/2019 20:50	Video Report No.	Station Diary No.
Name Of Informant CHAN KOK TAI	Address APT BLK 781 YISHUN RING ROAD #09-35-18 SINGAPORE 760781	
ID Type / ID No. NRIC NO / S9114478D	Contact No. Home/Office: Mobile: 92313886	
Nationality SINGAPORE CITIZEN	Email Address Marickf24@gmail.com	
Occupation Driver	Sex Male	Age 28
Institution/School Name	Date of Birth 24/04/1991	Race Chinese
Date/Time Of Incident 29/05/2019 17:35 - 26/05/2019 17:35	Location Of Incident TAMPINES AVENUE 2 SHELL TAMPINES AVENUE 2 SINGAPORE 626731	

Brief details.

I am a grab driver sending a passenger along tampines ave 2 (beside shell station), driving on the most left lane, and suddenly a Red honda civic bearing car plate no. SCV 2289 R, hit onto the rear of my car, honda fit (SLT 2352 Z). My car swerve to the centre lane. The Red honda civic (SCV 2289R) then continued forward and hit onto a comfort taxis (SHA 7533 H). I went to consult a doctor due to back and neck pain. I was given a 5 days MC.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 28/05/2019 20:50
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp

Police Report

SINGAPORE
POLICE FORCE

G/20190529/7050

2 of 2 ✓

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20190529/7050

Subjects Involved			
Victim			
Person Name	CHAN KOK FAI		
ID Type	NRIC NO	ID No	S9114479D
Gender	Male	Age	28
Race	Chinese	Language	English
Occupation	Driver	Address Type	
Address	APT BLK 761 YISHUN RING ROAD #09-3546 SINGAPORE 760761		Mobile No 92313896
Is Informant A Victim?	Yes		
Person Name	CHAN KOK FAI (Informant)		

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 26/05/2019 20:50
Officer In Charge Of Case:	Classification Of Case:
Authentication Stamp:	

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

29/05/2019

[illegible]

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#15-00 Springleft Tower
Singapore 079909
Attn: Accident Claims Department

Date : 31/05/2019
Vehicle No : SLT2352Z
Veh Make/Model : Honda Jazz 1.3L A
YOM : 2009
Chassis No : JHMGE68509S238267
Date of Accident : 29/05/2019

No	Qty	Description	Amount \$
Balance c/f			5,845.54
Special Nett Items:-			
1	1	Rear number plate with holder	\$ 55.00
2	1 Set	Rear reverse sensor	\$ 380.00
3	1	Tailgate windscreen glass solar flim.	\$ 300.00
4	1	Tailgate windscreen glass gum/sealant	\$ 80.00
5	1	Rear LH fender glass gum/sealant	\$ 60.00
6	1	Rear LH tyre	\$ 380.00
7	10	Tailgate inner trim board clip	\$ 60.00
8	10	Rear bumper clip	\$ 45.00
9	8	Rear LH fender splash shield clip	\$ 36.00
10	10	Rear LH inner trim board clip	\$ 60.00
11	6	End panel top trim clip	\$ 27.00
Total - SN Item			\$ 1,483.00
Labour Charges:-			
1		Spray painting on all affected area.	\$ 1,700.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,800.00
3		To adjust chassis alignment on car 'O' liner.	\$ 350.00
4		To apply anti rust treatment.	\$ 120.00
5		To check wiring system & light.	\$ 60.00
6		To remove and replace tailgate attachment and check water leaking.	\$ 120.00
7		To remove and replace reverse sensor.	\$ 120.00
8		To remove and reinstall tailgate windscreen glass.	\$ 150.00
9		To remove and reinstall rear LH fender windscreen glass.	\$ 80.00
10		To remove and reinstall rear seats to assist on repair.	\$ 250.00
11		Upholstery details cleaning.	\$ 220.00
12		To remove and replace rear LH suspension.	\$ 300.00
Total - L/C			\$ 5,270.00
Sub-Total			\$ 12,598.54
7% GST			\$ 881.90
Total			\$ 13,480.43

45m
20m
?
40m
30m
30m
—
—
—
—
—
1600
1700
250
✓
200
60
50
✓
60
120
x
?

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

L/Sun
\$ 7400 Max
16 days

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#15-00 Springleft Tower

Singapore 079909

Attn: Accident Claims Department

Date :

31/05/2019

Vehicle No :

SLT2352Z

Veh Make/Model :

Honda Jazz 1.3L A

YOM :

2009

Chassis No :

JHMGE68509S238267

Date of Accident :

29/05/2019

No	Qty	Description	Amount \$
<u>List Items:-</u>			
1	1	Tailgate	\$ B ₁ 685.39
2	1	Tailgate windscreen glass	\$ B ₁ 508.39
3	1	Tailgate windscreen glass moulding	\$ B ₁ 185.14
4	1	Tailgate center garnish	\$ W ₁ 243.50
5	1	Tailgate logo	\$ B ₁ 41.20
6	1	Tailgate "JAZZ" emblem	\$ B ₁ 48.22
7	2	Tailgate number plate lamp	\$ SA.10 108.20
8	2	Tailgate hinge	\$ D ₁ 98.20
9	1	Tailgate lock	\$ B ₁ 194.70
10	1	Tailgate weatherstrip	\$ D ₁ 192.30
11	1	Tailgate inner trim board	\$ B ₁ 155.70
12	1	LH tail lamp	\$ B ₁ 206.30
13	1	LH tail lamp inner panel	\$ B ₁ 242.71
14	1	RH tail lamp	\$ B ₁ 206.30
15	1	Rear bumper	\$ B ₁ 872.10
16	2	Rear bumper side retainer	\$ C ₁ 103.00
17	1	Rear RH fender	\$ B ₁ 391.51
18	1	Rear LH fender	\$ B ₁ 391.51
19	1	Rear LH fender inner panel	\$ B ₁ 539.15
20	1	Rear LH fender splash shield	\$ T ₁ 51.67
21	1	Rear LH inner trim board	\$ B ₁ 207.10
22	1	End panel	\$ A ₁ 250.18
23	1	End panel top trim	\$ B ₁ 60.80
24	1	Floor panel	\$ B ₁ 879.50
25	1	Floor panel board	\$ B ₁ 283.65
26	1	Rear LH shock absorber	\$ B ₁ 117.90
27	1	Rear LH shock absorber mounting	\$ B ₁ 42.60
Total - List Item			\$ 7,306.92
Less 20%			\$ 1,461.38
Total			\$ 5,845.54

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#15-00 Springleft Tower
Singapore 079909
Attn: Accident Claims Department

Date : 31/05/2019
Vehicle No : SLT2352Z
Veh Make/Model : Honda Jazz 1.3L A
YOM : 2009
Chassis No : JHMGE68509S238267
Date of Accident : 29/05/2019

No	Qty	Description	Amount \$
		Balance c/f	\$ 5,845.54
		Special Nett Items:-	
1	1	Rear number plate with holder	\$ 55.00
2	1 Set	Rear reverse sensor	\$ 380.00
3	1	Tailgate windscreen glass solar film.	\$ 300.00
4	1	Tailgate windscreen glass gum/sealant	\$ 80.00
5	1	Rear LH fender glass gum/sealant	\$ 60.00
6	1	Rear LH tyre	\$ 380.00
7	10	Tailgate inner trim board clip	\$ 60.00
8	10	Rear bumper clip	\$ 45.00
9	8	Rear LH fender splash shield clip	\$ 36.00
10	10	Rear LH inner trim board clip	\$ 60.00
11	6	End panel top trim clip	\$ 27.00
		Total - SN Item	\$ 1,483.00
		Labour Charges:-	
1		Spray painting on all affected area.	\$ 1,700.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,800.00
3		To adjust chassis alignment on car 'O' liner.	\$ 350.00
4		To apply anti rust treatment.	\$ 120.00
5		To check wiring system & light.	\$ 60.00
6		To remove and replace tailgate attachment and check water leaking.	\$ 120.00
7		To remove and replace reverse sensor.	\$ 120.00
8		To remove and reinstall tailgate windscreen glass.	\$ 150.00
9		To remove and reinstall rear LH fender windscreen glass.	\$ 80.00
10		To remove and reinstall rear seats to assist on repair.	\$ 250.00
11		Upholstery details cleaning.	\$ 220.00
12		To remove and replace rear LH suspension.	\$ 300.00
		Total - L/C	\$ 5,270.00
		Sub-Total	\$ 12,598.54
		7% GST	\$ 881.90
		Total	\$ 13,480.43

45m
20m
X
40m
30m
30m
—
—
—
—
—
—
1600
1700
250
200
60
50
150
60
120
X
X
1130

9450.30
+430.13

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119009767/KQD3N2

Date: 18/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3075131800	
Claimant Vehicle No :	SLT2352Z	Insured Vehicle No :	SCV2299R	
Date of Loss:	29/05/2019	Nature of Claim:	TP	Claim No: SNM19D202440C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT2352Z	Engine No:	L13Z11038293
Make & Model:	HONDA JAZZ, 1.3 (A)	Chassis No:	JHMGE68509S238267
Reg. Date:	23/09/2011 (Man. Year: 2009)	Odometer:	0 km
Colour:	Metallic Grey		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Dayton 2 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Dayton 2 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,328.54	5,866.45	1,462.09	19.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,270.00	4,130.00	1,140.00	21.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,598.54	9,996.45	2,602.09	20.65
Approved Total (Overridden) (\$\$)		7,400.00		
(S\$)	12,598.54	7,400.00	5,198.54	41.26
+ GST 7.00/7.00% (S\$)	881.90	518.00	363.90	41.26
Nett Amount (S\$)	13,480.44	7,918.00	5,562.44	41.26

INSPECTION

Date of Assignment:	31/05/2019	
Date Inspected:	04/06/2019	Inspected At: Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047

Estimated Period of Repair: 16.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2019)	
Parts: 144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLT2352Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Bent	685.39 FL	*685.39 FL
2	1	*TAILGATE WINDSCREEN GLASS	Serviceable	508.39 FL	*- FL
3	1	*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	185.14 FL	*185.14 FL
4	1	*TAILGATE CENTER GARNISH	Warped	243.50 FL	*243.50 FL
5	1	*TAILGATE LOGO	Necessary	41.20 FL	*41.20 FL
6	1	*TAILGATE JAZZ EMBLEM	Necessary	48.22 FL	*48.22 FL
7	1	*TAILGATE NUMBER PLATE LAMP	N/s Cracked	108.20 FL	*54.10 FL
8	2	*TAILGATE HINGE	Distorted	98.20 FL	*98.20 FL
9	1	*TAILGATE LOCK	Jammed	194.70 FL	*194.70 FL
10	1	*TAILGATE INNER TRIM BOARD	Buckled	155.70 FL	*155.70 FL
11	1	*LH TAIL LAMP	Broken	206.30 FL	*206.30 FL
12	1	*LH TAIL LAMP INNER PANEL	Bent	242.71 FL	*242.71 FL
13	1	*RH TAIL LAMP	Mtg Cracked	206.30 FL	*206.30 FL
14	1	*REAR BUMPER	Bent	872.10 FL	*872.10 FL
15	2	*REAR BUMPER SIDE RETAINER	Cracked	103.00 FL	*103.00 FL
16	1	*REAR RH FENDER	Buckled	391.51 FL	*391.51 FL
17	1	*REAR LH FENDER	Buckled	391.51 FL	*391.51 FL
18	1	*REAR LH FENDER INNER PANEL	Bent	539.15 FL	*539.15 FL
19	1	*REAR LH FENDER SPLASH SHIELD	Torn	51.67 FL	*51.67 FL
20	1	*REAR LH INNER TRIM BOARD	Buckled	207.10 FL	*207.10 FL
21	1	*END PANEL	Bent	250.18 FL	*250.18 FL
22	1	*END PANEL TOP TRIM	Dented	60.80 FL	*60.80 FL
23	1	*FLOOR PANEL	Bent/Buckled	879.50 FL	*879.50 FL
24	1	*FLOOR PANEL BOARD	Deformed	283.65 FL	*283.65 FL
25	1	*REAR LH SHOCK ABSORBER	Serviceable	117.90 FL	*- FL
26	1	*REAR LH SHOCK ABSORBER MOUNTING	Serviceable	42.60 FL	*- FL
27	1	*TAILGATE WEATHERSTRIP (50%)	Dented/Cut	153.84 FS	*96.15 FS
28	1	*REAR NUMBER PLATE WITH HOLDER	Missing	55.00 FS	*45.00 FS
29	1	*SET REAR REVERSE SENSOR	Dented	380.00 FS	*200.00 FS
30	1	*TAILGATE WINDSCREEN GLASS SOLAR FILM	Not Necessary	300.00 FS	*- FS
31	1	*TAILGATE WINDSCREEN GLASS GUM/SEALANT	Necessary	80.00 FS	*40.00 FS
32	1	*REAR LH FENDER GLASS GUM/SEALANT	Necessary	60.00 FS	*30.00 FS
33	1	*REAR LH TYRE (30%)	Cut	380.00 FS	*114.00 FS
34	10	*TAILGATE INNER TRIM BOARD CLIP	Necessary	60.00 FS	*60.00 FS
35	10	*REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
36	8	*REAR LH FENDER SPLASH SHIELD CLIP	Necessary	36.00 FS	*36.00 FS
37	10	*REAR LH INNER TRIM BOARD CLIP	Necessary	60.00 FS	*60.00 FS
38	6	*END PANEL TOP TRIM CLIP	Necessary	27.00 FS	*27.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **8,751.46** **7,144.78**
 - List Item Discount on L Items 20.00/20.00% (\$\$) **1,422.92** **1,278.33**

Total Parts (\$\$) 7,328.54 5,866.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	1,700.00	1,600.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,800.00	1,700.00
3	TO ADJUST CHASSIS ALIGNMENT ON CAR O LINER	New	350.00	250.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	120.00
5	TO CHECK WIRING SYSTEM & LIGHT	New	60.00	20.00
6	TO REMOVE AND REPLACE TAILGATE ATTACHMENT AND CHECK WATER LEAKING	New	120.00	60.00
7	TO REMOVE AND REPLACE REVERSE SENSOR	New	120.00	50.00
8	TO REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS	New	150.00	150.00
9	TO REMOVE AND REINSTALL REAR LH FENDER WINDSCREEN GLASS	New	80.00	60.00
10	TO REMOVE AND REINSTALL REAR SEATS TO ASSIST ON REPAIR	New	250.00	120.00
11	UPHOLSTERY DETAILS CLEANING	New	220.00	0.00
12	TO REMOVE AND REPLACE REAR LH SUSPENSION	New	300.00	0.00
Gross Labour Cost (S\$)			5,270.00	4,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >