

ASS. REC. BY:

REF:

CS/AWA (9009770/Rvd3)

n2

Special Instruction:

Surveyor:

Rusu

ASSIGNMENT (Office)

From (Person):

Ken Wong

of

AWA

Date/Time:

03/6/19

Estimated Cost:

Bill to:

OF / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLZ 938R

Insured:

FBN 17042

at Workshop m/s

N-51

Tel:

68420051 / 67440510

of

KAKI BUKIT

8823 5151

Policy No:

AVF MSB 000065180V

Claim No:

NSV1900268 / KW

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/5/19

CA / REV / REP. / REV 24 HRS

'WP'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate (✓)

SLZ 938R x

FBN 17042 x

26/7/19

LS \$1600 confirmed by email (Ref 3922.36, 7190)

RECEIVED 26 JUL 2019

Nivitha (LKK Auto)

From: Wong, Kin <Kin.Wong@awac.com> on behalf of Motorsurvey
<Motorsurvey@awac.com>
Sent: Monday, 3 June 2019 3:46 PM
To: 'assignments@lkkauto.com'
Cc: 'sur@lkkauto.com'; 'Chio Ziting'
Subject: TP Survey assignment for SLZ 938 R DOA: 30/05/2019 Our ref: NSV1900268/KW

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of Mr Adrain Ling as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SLZ 938 R
Insured Vehicle	:	FBN 1704 Z
Policy Number	:	AVFMSB0000651800
Name of Workshop	:	N-51 Automotive Pte Ltd
Contact Number	:	6842 0051/ 6744 0510
Person to Contact	:	Zi Ting
Estimated Cost of repairs	:	\$ NA

Regards,
Claims Division

Copy to Team N-51 Automotive Pte Ltd (Your Ref: SLR 938 R) via Email.

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards
Motor Claims
Claims Group
Global Market

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 26 July 2019 1:48 PM
To: Yeo Poh Kheng; SUR
Subject: RE: FW: SLZ 938R-DOA: 30/5/2019

Dear Mr Yeo,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to ALLIED WORLD.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yeo Poh Kheng <yeopk@n51.com.sg>
Sent: Friday, 26 July 2019 1:23 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Re: FW: SLZ 938R-DOA: 30/5/2019

Dear Veron

SLZ938R L/S \$1600.00 3 days confirm

Thanks

On Fri, 26 Jul 2019 at 12:53 PM, Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Mr Yeo,

WITHOUT PREJUDICE

Offer Lump Sum \$1600 @ 3 working days.

PARTS-\$1276.20 (less 25%)=\$957.15

SN-\$270

LABOUR-\$760

TOTAL-\$1987.15 (less 20%)=\$1589.72

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 24 July 2019 3:36 PM
To: 'sales' <sales@n51.com.sg>; SUR <sur@lkkauto.com>
Subject: SLZ 938R-DOA: 30/5/2019

Dear Sir/Madam,

WITHOUT PREJUDICE

Offer Lump Sum \$1600 @ 3 working days.

PARTS-\$1276.20 (less 25%)=\$957.15

SN-\$270

LABOUR-\$760

TOTAL-\$1987.15 (less 20%)=\$1589.72

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Regards,

Yeo Poh Kheng

N-51 Automotive Pte Ltd

Mobile : 8823 5151

Office : 6842 0051

www.n51.com.sg



bizSAFE₃

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/05/2019 12:22
Date Of Accident	30/05/2019 21:45
Exact Location Of Accident	TRAFFIC JUNCTION OF PASIR RIS DRIVE 1 AND 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ938R
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS PLUS (AUTO)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	
Driver	
Name of Driver	WEE TAI TIAN
NRIC No	S2003014C
Date Of Birth	27/05/1949
Occupation	OUTDOOR
Date Of Driving Pass	11/04/1967
Driving Experience	52 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92271869
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG PASIR RIS DR 1 AND WANTED TO MAKE A U TURN AT JUNCTION WITH PASIR RIS DR 10 . WHEN I STATIONARY FOR WAITING VEHICLE IN FRONT OF ME U TURN . SUDDENLY VEHICLE B COLLIDED ONTO REAR OF MY VEHICLE . NO INJURIES INVOLVED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	YES-RETRIEVING
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBN1704Z
Vehicle Make/Model/Colour	YAMAHA / NMAX155 ABS
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	DEVANKUMAR MOHGANAN
NRIC/Passport Number	G8752328X
Contact Number	84578536
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be shed outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER
JUN KEAT

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan

PAR R3
DR 10

A: QL2938R
B: FBM 7042

DR 10

↑ ↑ ↑ ↓

ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG PASIR RIS DR 1 AND WANTED TO MAKE A U TURN AT JUNCTION WITH PASIR RIS DR 10 . WHEN I STATIONARY FOR WAITING VEHICLE IN FRONT OF ME U TURN , SUDDENLY VEHICLE B COLLIDED ONTO REAR OF MY VEHICLE . NO INJURIES INVOLVED.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
WONG JUN KEAT

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

31 May 2019 at 11:15 AM

Date/Time:

31 May 2019 at 11:15 AM



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 92271869

ESTIMATE

Repair Code : CLM15278

Date in : 30/05/2019

Vehicle Num. : SLZ938R

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU60J026255/2ZR0B44919

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>de</i>	1	523.90	523.90 ✓
REAR BUMPER LOWER COVER <i>X su</i>	1	179.00	179.00
REAR BUMPER LOWER SPOILER <i>SCA</i>	1	721.00	<i>650</i> 721.00 ✓
REAR BUMPER REINFORCEMENT <i>X su</i>	1	205.70	205.70
REAR BUMPER REINFORCEMENT BRACKET L/R <i>X su</i>	2	139.60	279.20
REAR BUMPER SIDE RETAINER L/R <i>X su</i>	2	98.00	196.00
REAR END PANEL <i>X su</i>	1	781.45	781.45
REAR END PANEL ANTENNA SENSOR <i>X su</i>	1	485.00	485.00
REAR TAILGATE <i>repair</i>	1	929.60	929.60
REAR TAILGATE 'HYBRID' EMBLEM <i>su</i>	1	50.00	50.00 ✓
REAR TAILGATE 'PRIUS' EMBLEM <i>su</i>	1	52.30	52.30 ✓
Subtotal before discount		<i>1276.20</i>	4,403.15
Percentage discount 25%		<i>25%</i>	1,100.79
Sub-total 1		<i>957.15</i>	3,302.36
REAR BUMPER CLIPS - SET <i>su</i>	1	80.00	<i>40</i> 80.00 ✓
REAR BUMPER LOWER COVER CLIPS - SET <i>su</i>	1	30.00	30.00 ✓
REAR BUMPER REVERSE SENSOR <i>su</i>	1	350.00	<i>200</i> 350.00 ✓

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 92271869

ESTIMATE

Repair Code : CLM15278

Date in : 30/05/2019

Vehicle Num. : SLZ938R

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU60J026255/2ZR0B44919

Subtotal before discount	460.00
Percentage discount 0%	0.00
Sub-total 2	460.00
Parts-total	3,762.36

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,760.00
Parts & Labour Total	5,522.36

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

957.15
270.00
760.00
1987.15
202
1589.72
L/S - 1,600

Rasul
Hp 9000068
3 days
L/S
27/06/19 @ 1620
Resurvey after repair
3 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA19009770/R1vd3n2

(SINGAPORE BRANCH)

60 ANSON ROAD #08-01 (8th FLOOR)

MAPLE TREE ANSON

SINGAPORE 079914

Date : 29-07-2019



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBN 1704Z	Veh. Inspected	SLZ 938R
Policy No.	AVFMSB0000651800	Coverage (\$)	0.00
Claim No.	NSV1900268/KW	Excess (\$)	0.00
Assign From	KIN WONG	Assign Date	03/06/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS HYBRID	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTDZS3EU60J026255	Colour	BLUE
Odometer	113214	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HABILEAD	6 mm
L/H Front Tyre	205/60 R16	HABILEAD	6 mm
R/H Rear Tyre	205/60 R16	HABILEAD	6 mm
L/H Rear Tyre	205/60 R16	HABILEAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/05/2019	Inspection Date	27/06/2019
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 938R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	523.90	523.90
1	REAR BUMPER LOWER COVER	SERVICEABLE	179.00	-
1	REAR BUMPER LOWER SPOILER	SCRATCHED	721.00	650.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	205.70	-
2	REAR BUMPER REINFORCEMENT BRACKET L/R @\$139.60	SERVICEABLE	279.20	-
2	REAR BUMPER SIDE RETAINER L/R @\$98.00	SERVICEABLE	196.00	-
1	REAR END PANEL	SERVICEABLE	781.45	-
1	REAR END PANEL ANTENNA SENSOR	SERVICEABLE	485.00	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	929.60	-
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	50.00	50.00
1	REAR TAILGATE "PRIUS" EMBLEM	NECESSARY	52.30	52.30
	LESS 25% DISCOUNT		-1,100.79	-319.05
			3,302.36	957.15
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	40.00
1	SET REAR BUMPER LOWER COVER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	350.00	200.00
			460.00	270.00
<u>LABOUR</u>				
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR.		100.00	60.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPER (TO FR).	NOT NECESSARY	140.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		700.00	400.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR TAILGATE.		700.00	300.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	120.00	-
			1,760.00	760.00
GRAND TOTAL			5,522.36	1,987.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CS/AWA19009770/R1vd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.