Estimated Cost: Bill to: OD-1/TP / WS/TP RES / OD RES / EVA / INV / MV / CS To Inspect Vehicle No: SLZ 40/7 / Insured: SJP 48 at Workshop in/s 7cam kuto fro Tel: 6258 (of 160 s/m Dr # 0/-14 s (\$75722) Policy No: Claim No: C1000 3 198/370	and it has been been all the second property of the second party o
To Inspect Vehicle No: 827 40/74 Insured: 57/48 at Workshop in/s 7eam Auto Pro Tel: 6258(of 1605/m Dr #0/-145(575722)	and it has been been all the second particular to the second particular
of 1605/m Dr 4:01-145(575722)	951
of 1605/m Dr 401-145(575722)	
Policy No: Claim No: C1000 3198/70	
	V
Sum Insured: Excess:	
Make of Velt: D.O.A. 31/-	5/19.
CA / REV / REP. / REV 24 HRS (WP) H.O.D. Endorsement:	
Date/Time: Person Contacted: Vehicle IN/OUT	
Date/Time Action/Instruction Shimal ()	
SLZ 40177 x	•
. SJP 48176 × .	

Interview (\$

Tech. Invs (\$

Weekend (\$

Report Format:

Lump Sum / I.B.t. (\$ 3.200)

Photos

Others

TOTAL

Nivitha (LKK Auto)

From:

Ivy Ratilla <ivy.r@budgetdirect.com.sg>

Sent:

Monday, 3 June 2019 4:47 PM

To:

Admin-D (LKKAuto)

Cc:

SUR; Justin Wong

Subject:

Claim ref:C10003198/JW || OI- SJP4817G (Grey) TP- SLZ4017Y || Est:0.00 || Team

Autopro

Attachments:

2D.4017.4817.pdf

Hi Team,

We would like to arrange TP PRS for SLZ4017Y. Please see below email for reference.

Kindly confirm.

Regards,

Ivy Admin Executive, Claims

T +65 6540 2185 F +65 6725 0853 E ivy.r@budgetdirect.com.sg



Trusted Service Award

Customer Care +65 6221 2111 Claims +65 6221 2199 Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01 Singapore Shopping Centre Singapore 239924 budgetdirect.com.sq

auto 🗟 general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as <u>Budget</u> <u>Direct Insurance</u>.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: TeamAutoPro North <teamautopl@gmail.com>

Sent: Monday, 3 June 2019 4:28 PM

To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>

Cc: Albert Hong <albert.hong@budgetdirect.com.sg>; Claims <claims@budgetdirect.com.sg>; Justin Wong

<justin.wong@budgetdirect.com.sg>

Subject: Re: 2 Days Notice: SLZ 4017 Y (Our Ref) and SJP 4817 G (Your Ref) Dated 31st May 2019 || C10003198/JW

Dear Sirs,

With reference to your list of surveyors, we are agreeable with the appointment of <u>LKK</u> as the SJE for subject claim.

Kindly note our personnel in charge for the survey as follows:-

Contact Person	Alan Koh	9092 7279	
	Frederick Lim	9674 6635	
Email Address	teamautopl@gmail.co	<u>om</u>	
Survey Address	160 Sin Ming Dr,	#01-14 Singapore 575722	

Thank you for your kind attention to our request.

*The above settlement is in respect of our client for damage pertaining to his motor vehicle and	shall
not prejudice our client's claim in respect of damages and consequential loss in relation to his p	ersonal
injuries.*	

Cheers, Michelle Lim

Team AutoPro Pte Ltd

Tel: 6258 1955 Fax: 6258 1956

385 Sin Ming Drive #01-02 Vicom Inspection Centre Singapore 575718

 Virus-free.	www.avg.com

From: TeamAutoPro North < teamautopl@gmail.com >

Sent: Friday, 31 May, 2019 5:31 PM

To: Julie Mangubat < <u>julie.m@budgetdirect.com.sg</u>>; Albert Hong < <u>albert.hong@budgetdirect.com.sg</u>>; Customer

Care <help@budgetdirect.com.sg>

Subject: 2 Days Notice: SLZ 4017 Y (Our Ref) and SJP 4817 G (Your Ref) Dated 31st May 2019

Dear	Sir/	Ma	da	m,
------	------	----	----	----

Road Traffic Accident Involving SLZ 4017 Y (Our Ref) and SJP 4817 G (Your Ref) Dated 31st May 2019, Time around 06:35

@ BKE Near Rifle Range Road

We represent our client; Mark Nivan Singh, to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SLZ 4017 Y and your insured's vehicle registration number: SJP 4817 G.

Enclosed herewith a copy of our 2 Days Notice Letter and the relevant Singapore Accident Statement filed for your reference.

Please let us know within 2 working days from today, your list of at least ten (10) motor surveyors, via email to the following personnel:-

Survey Address	160 Sin Ming Dr,	#01-14 Sin Ming AutoCity Singapore 575722
Email Address	teamautopl@gma	<u>sil.com</u>
	Frederick Lim	9674 6635
Contact Person	Alan Koh	9092 7279

Thank you for your attention to this email and we look forward to your earliest reply.

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,

Michelle Lim

Team AutoPro Pte Ltd

Tel: 6258 1955

Fax: 6258 1956

385 Sin Ming Drive #01-02 Vicom Inspection Centre Singapore 575718

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

Virus-free	www.avg.com
11100 11001	

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

MNA419072396 / National Assessment Centre Services - Bukit Merah ENTRY DATE & TIME: 03/06/2019 17:31 SUBMITTED BY: ROSLI BIN ABDUL WAHAB

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- port at the centre and to copies of the report being made available

By the lodgement of this report to the insurers, you aforesaid.	u hereby consent to the archiving of this report at the centre and to copies of the report being made as	
	ACCIDENT STATEMENT	
Date Of Report	03/06/2019 17:31	
Date Of Accident	31/05/2019 06:35	
Exact Location Of Accident	BKE NEAR RIFLE RANGE ROAD	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLZ4017Y	
Insured/Policyholder		
Name Of Registered Owner	MARK NIVEN SINGH	
NRIC No	S7513699D	
Email Address	NOEMAIL	
Mobile Phone No	(LOCAL) +65-96876179	
Alternative Phone No	OTHERS-96876179	

Vehicle Particulars

MAZDA Manufacturer

3 Model

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken Vehicle Category

THIRD PARTY PRIVATE CAR

Insurance Company

AIG ASIA PACIFIC INSURANCE PTE. LTD. Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

1800055305 Policy Number

Cover Note Number

Driver

TAN CHENG GEK, CHRISTINE Name of Driver

S7138863H NRIC No 06/11/1971 Date Of Birth INDOOR Occupation 04/02/1991 Date Of Driving Pass

28 YEARS AND 3 MONTHS **Driving Experience**

FEMALE Gender

(LOCAL) +65-96876179 Mobile Number

Fax Number

OTHERS-96876179 Contact Number

NOEMAIL **EMail Address**

Address

38 ST.MICHAEL'S ROAD

#07-02

3280008 Postcode

Was driver an employee of the Insured's Company NO

SPOUSE If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLISION - HEAD TO REAR Type Of Accident

CLEAR Weather Conditions DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

NO YES

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO 1

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJP4817G

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

WONG FONG MING

NRIC/Passport Number

S1482137F

Contact Number

96371093

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the scrident to speed up the claims process
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver
- 3 Information provided must be as truthful and accurate as possible. Any willul misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 5 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available sprin application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

I understand, inknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers Tawyers/Taw firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing, funding and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal slata about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sided outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
 - (ii) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing frauli regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

Pulicyholder's Signature Date & Time Driver's Signature (if driver is not the pencyholider) flate & Time

Reporting Centre Pursoning & Significate April 1988

Accident Sketch Plan

	BRE New Rifle Range Road Vehicle A: SLZ 4017Y Vehicle B: SJP4817Ci
escribe circumstances of the accident	Vehicle B: SJP4817Ci
On the stated date and : I followed suit. Suddenly !	
I followed suit. Suddenly	VT
I followed suit. Suddenly	VT
On the stated date and :	VT
I followed suit. Suddenly	
I followed suit. Suddenly	
I followed suit. Suddenly	time, the vehicle infant of me stopped.
ertion.	Vehicle & hit onto my Vehicle rear
ertion.	
DECLARATION	and the same
/We declare the foregoing particulars are true in e	enature sensitive to the posicynology the substitute substitute to the posicynology to the substitute substitu
relicyholder's Signature Driver's Sig	ALL FOR THE PROPERTY OF THE PR
Date & Time Usts & Time	enature Reporting Centre Responding Suchastand L.



Mazda 3 1.5A Deluxe

\$800 Warranty Workshop Credits, 1 Year Warranty Cover Engine And Gear Box By Our Authorized Workshop, Well Maintain By Previous Owner, Can Arrange For STA Evaluation, Drive With Peace Of Mind! High Tr...

Accendore Autolution Pte Ltd

Posted: 16-May-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A Sunroof

\$56,500

\$9,100 /yr

12-May-2015

28,500 km

Sedan

Available

Elegant Blue, With Sunroof, Very Low Mileage Done, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In House

Prime Motor & Leasing

Posted: 29-May-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A Deluxe

21-May-2015 N.A

1,496 cc

1.496 cc

Sedan

SOLD

Deluxe Model! 5 Years Warranty! Enjoy Exclusive 1.98% Interest Rate! As Good As New. Fully Maintained And Warranty By Agent, Low Fuel Consumption, 1 Owner, Accident Free. Well Maintained Regularly One...

Posted: 16-Mar-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Save up to 25% on petrol

Compare the latest petrol discount credit cards on sgCarMart. Enjoy discounts as high as 25% on your petrol bills.



Mazda 3 1.5A Deluxe

N.A.

25-May-2015

1.496 cc

Sedan

SOLD

Posted: 28-Mar-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A

N.A

26-May-2015

1.496 cc

Sedan

SOLD

Posted: 03-May-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A

\$59,500

\$9,370 /vr 27-May-2015 1,496 cc

44,000 km

Available

Well Maintained By Owner, Non Grab/uber, Genuine Mileage, View To Believe It, Consignment Unit, Loan And Insurance Available! Trade In Welcome! Call Now For Viewing!

Prem Roy Motoring

Posted: 07-May-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A Deluxe

\$57,800

\$9,050 /yr 28-May-2015

1.496 cc

47,906 km

Sedan

Available

Low Mileage Done 47906 KM 1 Owner, Full Agent Serviced,

Posted: 24-May-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A Sunroof

\$54,999 \$8,790 /yr 28-May-2015

1.496 cc

83,100 km

Sedan

Available

1 Owner Nice Car Condition! Sporty Silver In Black Leather Interior! All New Mazda 3 1.5A With New SkyActive Technology And Sunroof Model! 100% Accident Free And Under Trans Eurokas Mazda Service From...

Posted: 13-May-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A Deluxe

10-Jun-2015

1,496 cc

Sedan

SOLD

Guaranteed Non-Leasing Unitl 1 Owner, Highest Specs & Like New Interior. Sunroof Model, Sporty Black Deluxe Model With Active Display, Navigation And Many More, Guarantee Condition, In House Loan Aval...

Posted: 04-May-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A Sunroof

15-Jun-2015

1,496 cc

Sedan

SOLD

All Potential Car Owners! Look At This All New Mazda 3, 1 Careful Owner, Loan With 100% Approval! Please Cal Anna Make A Booking Now! A Pleasurable Test Drive And Enjoy Special Offer From Us!

Hua Yang Credit Pte Ltd

Posted: 05-May-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A Sunroof (OPC)

15-Jun-2015

1,496 cc

SOLD

1 Owner, Deluxe Model. Accident Free! Done Only 10082KM, Still Got New Car Smell! See/Test Drive To Believe, Just Like New! 100% Best Condition In Market. Trade-In/Loan/Insurance. Call Now! No Disappo...

Posted: 30-Apr-2019 Tags: 2015 Mazda 3, 2015 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda

Sedan

SOLD

DERCT CONES

Mazda 3 2.0A Sport

N.A.

16-Jun-2015

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	3699D	
Vehicle No.:	SLZ4017Y	
Vehicle to be Exported:	No	
Intended Deregistration Date:	07 Jun 2019	
Vehicle Make:	MAZDA	
Vehicle Model:	MAZDA3 SEDAN 1.5 AT LED EU6	
Primary Colour:	Black	
Manufacturing Year:	2017	
Engine No.:	P520491391	
Chassis No.:	JM6BN22A8J0200027	
Maximum Power Output:	88.0 kW (118 bhp)	
Open Market Value:	\$17,223.00	
Original Registration Date:	30 Apr 2018	
First Registration Date:	30 Apr 2018	
Transfer Count:	0	
Actual ARE Paid: Intended PARE Rebate Details	\$17,223.00	
PARE Enginitity:	Yes	
PARF Eliginifity Expiry Date:	29 Apr 2028	
PARE Repair Amount:	\$12.917.00	
Intended COE Rebate Details	West Terris	
COL Expiry Date:	29 Apr 2028	
COF Category:	E - Open - all except motorcycle	
C (Eller rod Years):	10	
QP.Pakii	\$38,039.00	
C JE Reliate Amount:	\$32,909.00	
Total Reliate Amount:	\$45,826.00	

The information contained herein is correct as at 07 Jun 2019

OK

Aug dep 9070/4

llin_ 7/6/19

AC	INC	ltem	CON	AC	Qty
37	993626	Rear Number Plate			
		Rear Number Plate Base			
39		Rear Number Plate Garnish			
140		Reaf Number Plate Lamp		_	Ш
141	992958	Rear Bumper	CUI	1	\vdash
	993085	Rear Bumper Upper	-	_	Н
143		Rear Bumper Lower	CUT	V	\vdash
		Rear Bumper Side	-	_	Ш
	993103	Rear Bumper Tow Cover	Cul	V	\vdash
146	992341	Rear Bumper Clips	NEC	V	
147		Rear Bumper Bracket	NEC	1	2
148	993068	Rear Bumper Side Retainer	NE	1/	12
149	993045	Rear Bumper Reinforcement	_	1	\vdash
	992970	Rear Bumper Beam	-	-	-
151	993077	Rear Bumper Sponge Rear Bumper Damper	-	+	-
153	993040	Rear Bumper Protector	-	+	+-
	993036	Rear Bumper Pad	2	+-	+-
155	993026	Rear Bumper Moulding	-	+	-
156	993044	Rear Bumper Reflector	-	+	-
157		Rear Bumper Lower Spoiler	-	+	+-
158	994023	Reverse Sensor	1	1	10
159	993327	Rear End Panel	BR	1	12.
160	993339	Rear End Panel Top Garnish	100	1	1
1161	993333	Rear End Panel Inner Trim	1	+	\top
1162	990333	Boot Compartment Inner Trim	P	Т	T
1163	993851	Rear LH Taillamp	BR	· V	
1164	993853	Rear LH Taillamp Gamish			
1165	993859	Rear LH Taillamp Panel	_	-	-
1167	993110	Rear RH Taillamp	BF	2 4	1
1169	993833	Rear RH Taillamp Gamish Rear RH Taillamp Panel	-	+	+-
1169	993554	Rear Apron Panel	-		-
1170	997895	Bootlid	0	-	1-
		Bbotlid Emblem	110	X	1
		Bootlid Handle	Ne	4	1
		Bootlid Moulding	-	+	+
1174	990376	Bootlid Reflector	BA		10
1175	995222	Bootlid Lamp LH	100	S V	1-
1176	992899	Bootlid Lamp RH	+	+	1
1177	995243	Bootlid Lock	1.	1	
1178	990377	Bootlid Rubber	-		
		Bootlid Hinge			
		Bootlid Spoiler		4	_
		Tailgate	_	1	-
1182	991328	Tailgate Emblem Tailgate Outer Handle	-	+	-
1184	994640	Tailgate Moulding	-	-	-
		Tailgate Garnish	-	+	+
1186		Tailgate Reflector /	-	-	-
		Tailgate Lamp	-	+	-
1188	994646	Tailgate Protector	-	+	
		Tailgate Wiper Arm	-	+	1
1190		Tailgate Wiper Blade		-	
1191		Tailgate Wiper Nozzle	1	-	
		Tailgate Wiper Motor		1	1
		Tailgate Glass.	-	-	-
		Tailgate Glass Rubber	-	-	-
		Tailgate Glass Moulding	-	+	-
		7 Tailgate Glass Sealant	-	-	-
	_	7 Taligate Glass Sealant	-	-	-
		I Tailgate Rubber	-	+	-
		1 Tailgate Hinge	-	+	
11111	1 22901	i I rangate ringe			_
1199	99459	4 Tailgate Damper			

	100	e 1 er	1 .	10	11
		Vehilcle Not . SLZ		11	9
NAC	INC	Item	CON	AC	<u>v</u>
1202	993784	Spare Tyre Board			
		Spare Tyre Panel			
1204	995065	Spare Tyre	273215		_
1205	994326	Spare Tyre Lock Screw	- 10		_
1206	993787	Spare Tyre Cover			_
1207	995323	Triangle Breakdown Sign			_
1208	990507	CD Changer Assy			
		Antenna			00000
		Centre Exhaust Pipe Assy .			
		Centre Exhaust Mounting			
		Rear Exhaust Pipe			-
1212	993304	Rear Exhaust Chrome Pipe	_	\vdash	_
1214	993357	Rear Exhaust Mounting	_		-
1214	003358	Rear Exhaust Heat Shield			-
1215	005223	Rear LH Chassis Member	_		
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender		1	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel		T	
1221	903431	Rear LH Fender Inner Trim		T	
		Rear LH Fender Inner Garnish	1	1	1
		Rear LH Pender Inner Shield		T	
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			_
1227	995065	Rear LH Tyre		-	_
1228	993456	Rear RH Fender	-	-	-
1229	993450	Rear RH Fender Protector	-	-	-
1230	993420	Rear RH Fender Inner Panel	-	+	⊢
1231	993431	Rear RH Fender Inner Trim	-	+-	-
1232	993415	Rear RH Fender Inner Garnish	-	+-	-
1233	993423	Rear RH Fender Inner Shield Rear RH Mudflap	-	+	1
1234	00202	Rear RH Wheel Rim	1	+	1
		Rear RH Rim Cover	1	+	t
		Rear RH Tyre	1	+	1
		Rear Fender Extension Panel LH	1	200	
1230	00340	Rear Fender Extension Panel RH	1	13	1
1240	003430	Rear Fender Inner Top Gamish	1	-	1
1241	99367	Rear Pender 1/4 Glass .	1		3
1242	99345	Rear Fender 1/4 Glass Rubber	1	T	
1243	99345	Rear Fender 1/4 Glass Scalant			
1244	99394	Rear Windscreen Glass	-	-	1
1245	99397	Rear Windscreen Rubber	-	-	10
1246	99396	Rear Windscreen Moulding	-	-	100
1247	99395	Rear Windscreen Sealant	-	1	15
1248	99472	9 Third Brake Light	-	+	10
1249	99338	Rear Fender Air Grille	+-	-	1
1250	99216	7 Puel Lid	+-	+	1
1251	99216	8 Fuel Neck	1-	-	H
1252	99217	9 Fuel Tank / 4 Fuel Tank Bracket	+	1	1
1253	99218	Puel Tank Float	1	1	13
¥1669	99024	7 Sticker			100
210,00	12	Flid saisor	Di	· V	13
-	1000		B	21/	15
-	Jan	lamp braces	ATE	7	4
	Tail	your cup>	N	2/1	1
	Rear	bumper sture stry	1/3	-	9 18
<u></u>	-		+	-	1
<u></u>	-		-	+	-
_			-	-	
-			-	-	T
1	1		-	-	T
-				1 4	

No of Items:

Assessori .Talin

Mic 6/6/19



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to	Federation	Internationale	Des	Experts En /	Automobile
--	--	---------------	------------	----------------	-----	--------------	------------

AUTO & GENERAL INSURANCE (S) PL

Ref: CS/AGI19009780/Btd3n2

(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01

SINC	20120	NG CENTRESINGAPORE	Date: 17-07-2019			
2399	924		Code: AGI			
1.		Policy Particula	ars :- THIRD PARTY CLA	IM		
	Insured Veh.	SJP 4817G	Veh. Inspected	SLZ 4017Y		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	C10003198/JW	Excess (\$)	0.00		
ū	Assign From	IVY RATILLA	Assign Date	03/06/2019		
2.		Vehicle Pa	articulars & Condition			
	Make & Model	MAZDA 3 1.5	c.c	1496		
	Engine No.	HIDDEN	Year of Reg.	2018		
	Chassis No.	JM6BN22A8J0200027	Colour	BLACK		
	Odometer	19428	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3.	TO KEEP THE PARTY OF THE PARTY	Con	ditions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	225/45 R18	GOODYEAR	6 mm		
	L/H Front Tyre	225/45 R18	GOODYEAR	6 mm		
	R/H Rear Tyre	225/45 R18	GOODYEAR	6 mm		
	L/H Rear Tyre	225/45 R18	GOODYEAR	6 mm		
4.		Descr	iption of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.			
	DAMAGES SEE D	ETAILS.				
5.		Gen	eral Information			
	Accident Date	31/05/2019	Inspection Date	04/06/2019		
	Survey held at	t TEAM AUTOPRO PTE LTD				
	8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875					
5a.			Remarks			
	A)THE INSPECTION B)IN ACCORDANGE	ON WAS CONDUCTED ON A'CE TO YOUR INSTRUCTION	WITHOUT PREJUDICE" BAS S, WE HAVE NOT AUTHORI	SIS. SED REPAIRS.		
5b.		Estim	ate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 4017Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)	
	REPLACEMENT OF PARTS				
1	BOOTLID	TO REPAIR SEE LABOUR	856.70	2. 1	
1	BOOTLID LOGO	NECESSARY	58.30	58.30	
1	BOOTLID EMBLEM "MAZDA"	NECESSARY	45.60	45.60	
1	BOOTLID EMBLEM "3"	NECESSARY	33.10	33.10	
1	BOOTLID EMBLEM "SKYACTIV TECHNOLOGY"	NECESSARY	62.30	62.30	
2	BOOTLID REFLECTOR @\$235.60	BROKEN	471.20	471.20	
1	REAR BUMPER	DENTED	683.60	683.60	
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	232.00	1. -	
2	REAR BUMPER SIDE RETAINER @\$53.50	NECESSARY	107.00	90.60	
2	REAR BUMPER BRACKET @\$65.00	NECESSARY	130.00	86.00	
1	REAR BUMPER LOWER	NOT NECESSARY	185.60		
2	REAR BUMPER REFLECTOR @\$65.50	NOT NECESSARY	131.00		
1	REAR BUMPER TOW CAP	сит	68.50	60.00	
1	REAR END PANEL	DENTED	364.60	364.60	
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	145.00	1	
1	REAR FENDER AIR GRILLE LH	NOT NECESSARY	89.80	194	
2	TAILLAMP @\$352.00	N/S BROKEN / O/S NOT NECESSARY	704.00	352.00	
2	TAILLAMP BRACKET @\$86.50	NOT NECESSARY	173.00	9-	
1	BOOTLID SENSOR	BROKEN	130.00 185.60 131.00 68.50 364.60 145.00 89.80 704.00 173.00 200.00 -948.26	200.00	
	LESS 20% DISCOUNT		-948.26	-501.46	
	Control of the second of the s		3,793.04	2,005.84	
	SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NOT NECESSARY	60.00		
4	REVERSE SENSOR @\$200.00 (SN)	CUT (2 PCS ONLY)	800.00	200.00	
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00	
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	50.00		
2	TAIL LAMP CLIPS @\$50.00 (SN)	NECESSARY	100.00	50.00	
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00	
1	REAR BUMPER LOWER CLIPS (SN)	NECESSARY	50.00	30.00	
1	REAR BUMPER STICKER STRIP (SN)	NECESSARY	25.00	25.00	
			1,195.00	395.00	

Report Ref No. CS/AGI19009780/Btd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	R&R BOOTLID COMPONENT.		100.00	60.00
	R&R REVERSE SENSOR.		100.00	60.00
	R&R WIRE HARNESS TO FACILITATE REPAIR WORK AND CHECK FUNCTION.		80.00	50.00
	PANEL BEAT.INCLUSIVE OF THE REPAIR OF BOOTLID.		1,400.00	700.00
	RUST PROOFING.		100.00	60.00
	SPRAY PAINTING.		1,200.00	800.00
			2,980.00	1,730.00
	GRAND TOTAL		7,968.04	4,130.84

RECOMMENDED COST OF LUMP SUM REPAIRS	3,300.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/AGI19009780/Btd3n2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

Team AutoPro Pte Ltd 385 Sin Ming Drive #01-02 Vicom Inspection Centre Singapore 575718 Tel: 8269-9999 Email: teamautopl@gmail.com / teamautoffice@amail.com

Sentone	TAILER OF THE PARTY OF THE PART	_		Vehicle Nos:	SLZ 4017Y	
	of Survey :		Model : Year :		Mazda 3	
	of ReSurvey: After-Paint:					
Conta	cts:	_		Chassis No:		
AGI	REED Cost Of Repair and Repair Day/s with SJE *					
lmou	nt:	-		Working Day:		
Nos.	PARTS	Qty		Unit S\$	TOTAL	SŠ
1	Bootlid	1	\$	856.70	\$	856:70
2	Bootlid logo	1	\$	58.30	\$	/ 58.30
3	Bootlid emblem 'Mazda'	1	5	45.60	\$	V 45.60
4	Bootlid emblem '3'	1	\$	33.10	\$	√ 33.10
5	Bootlid emblem 'Skyactiv Technology'	1	5	62.30	\$	V 62.30
6	Bootlid reflector	2	\$	235.60	\$	471.20
7	Rear bumper	1	\$	683.60	\$ 0	683.60
8	Rear bumper reinforcement	1	\$	232.00	\$	-232.00
9	Rear bumper side retainer	2	\$	45.30 53.50	\$ 90.60	107.00
10	Rear bumper bracket	2	\$	65.00	\$ 86.00	130.00
11	Rear bumper lower	1	\$	185.60	\$	185.60
12	Rear bumper reflector	2	\$	65.50	\$	131.00
13	Rear bumper tow cap	1	\$	68.50	\$ 60.00	68.50
14	Rear end panel	1	\$	364.60	\$	√ 364.60
15	Rear end panel top garnish	1	\$	145.00	\$	-145.00
16	Rear fender air grille LH	1	\$	89.80	\$	89.80
17	Taillamp LH-BR, RH-NN	12	\$	352.00	\$ 352.00	704.00
18	Taillamp bracket	2	\$	86.50	S D MH	7-173.00
19	Bootlid Sensor \$ 200/	BR		Parts Sub Total:	\$ 2507.30	4,541.30
	V	20%		Discount	\$ 501+46	908.26
				PARTS TOTAL :	\$ 2005.84	3,633.04
Nos.	SPECIAL NETT	Qty		Unit S\$	TOTAL	
14031	Sundries	1	\$	60.00	\$	60.00
1	Sulfules				\$ 200.00	800.00
	Reverse sensor 2	A	\$	200.00		1000000
1	Reverse sensor 2 Rear bumper clips	A 1	\$	50.00	\$ 30.00	50.00
1 2	Reverse sensor 2	1 1	\$	50.00 50.00	\$ 30.00	-50.00
2	Reverse sensor 2 Rear bumper clips Rear end panel top garnish clips Tail lamp clips	A 1	\$	50.00	\$ 30.00	-50.00 100.00
1 2 3 4 5 6	Reverse sensor 2 Rear bumper clips Rear end panel top garnish clips Tail lamp clips Rear end panel sealant ?	1 1 2	\$ \$	50.00 50.00 25.00 50.00	\$ 30.00 \$ \$ 50.00 60	-50.00 100.00
1 2 3 4 5 6 7	Reverse sensor 2 Rear bumper clips Rear end panel top garnish clips Tail lamp clips Rear end panel sealant ? Rear bumper lower clips	1 1 2	\$ \$	50.00 50.00 25.00 50.00	\$ 30.00 \$ \$ 50.00 60: \$ 30.00	-50.00 100.00 % 50.00
1 2 3 4 5 6	Reverse sensor 2 Rear bumper clips Rear end panel top garnish clips Tail lamp clips Rear end panel sealant ?	1 1 2 1 1	\$ \$ \$	50.00 50.00 25.00 50.00 50.00 25.00	\$ 30.00	50.00 100.00 00 50.00
1 2 3 4 5 6 7	Reverse sensor 2 Rear bumper clips Rear end panel top garnish clips Tail lamp clips Rear end panel sealant ? Rear bumper lower clips	1 1 2 1 1	\$ \$ \$	50.00 50.00 25.00 50.00	\$ 30.00 \$ \$ 50.00 60: \$ 30:00 \$	50.00 100.00 00 50.00
1 2 3 4 5 6 7 8	Reverse sensor 2 Rear bumper clips Rear end panel top garnish clips Tail lamp clips Rear end panel sealant ? Rear bumper lower clips Rear bumper sticker strip LABOUR	1 1 2 1 1	\$ \$ \$	50.00 50.00 25.00 50.00 50.00 25.00	\$ 30.00 \$ \$ 50.00 60: \$ 30.00 \$ \$ 790:00	50.00 100.00 50.00 25.00 1,135.00
1 2 3 4 5 6 7 8 Nos.	Reverse sensor 2 Rear bumper clips Rear end panel top garnish clips Tail lamp clips Rear end panel sealant ? Rear bumper lower clips Rear bumper sticker strip LABOUR R&R bootlid component	1 1 2 1 1	\$ \$ \$	50.00 50.00 25.00 50.00 50.00 25.00	\$ 30.00 \$ 50.00 60: \$ 30:00 \$ 790:00 \$ \$ 60:00	50.00 100.00 50.00 25.00 1,135.00
1 2 3 4 5 6 7 8 Nos. 1	Reverse sensor 2 Rear bumper clips Rear end panel top garnish clips Tail lamp clips Rear end panel sealant ? Rear bumper lower clips Rear bumper sticker strip LABOUR R&R bootlid component R&R reverse sensor	1 1 2 1 1	\$ \$ \$	50.00 50.00 25.00 50.00 50.00 25.00	\$ 30.00 \$ 50.00 \$ 30.00 \$ 790.00 \$ \$60.00 \$ \$60.00	50.00 100.00 50.00 25.00 1,135.00
1 2 3 4 5 6 7 8 Nos. 1 2 3	Reverse sensor 2 Rear bumper clips Rear end panel top garnish clips Tail lamp clips Rear end panel sealant ? Rear bumper lower clips Rear bumper sticker strip LABOUR R&R bootlid component	1 1 2 1 1	\$ \$ \$	50.00 50.00 25.00 50.00 50.00 25.00	\$ 30.00 \$ 50.00 60: \$ 30.00 \$ 790:00 \$ 560:00 \$ 50:00	50.00 100.00 50.00 25.00 1,135.00 100.00 80.00
1 2 3 4 5 6 7 8 Nos. 1 2 3 4	Reverse sensor 2 Rear bumper clips Rear end panel top garnish clips Tail lamp clips Rear end panel sealant ? Rear bumper lower clips Rear bumper sticker strip LABOUR R&R bootlid component R&R reverse sensor R&R wire harness to facilitate repair work and check function Panel beat	1 1 2 1 1	\$ \$ \$	50.00 50.00 25.00 50.00 50.00 25.00	\$ 30.00 \$ 50.00 \$ 30.00 \$ 790.00 \$ 60.00 \$ 50.00 \$ 700.00	50.00 100.00 50.00 25.00 1,135.00 100.00 80.00
1 2 3 4 5 6 7 8 Nos. 1 2 3	Reverse sensor 2 Rear bumper clips Rear end panel top garnish clips Tail lamp clips Rear end panel sealant ? Rear bumper lower clips Rear bumper sticker strip LABOUR R&R bootlid component R&R reverse sensor R&R wire harness to facilitate repair work and check function	1 1 2 1 1	\$ \$ \$	50.00 50.00 25.00 50.00 50.00 25.00	\$ 30.00 \$ 50.00 60: \$ 30.00 \$ 790:00 \$ 560:00 \$ 50:00	-50.00 100.00

PARTS TOTAL: \$ 3,633.04 1,135.00 SPECIAL NETT TOTAL: \$

Prepared by Eric (8269-9999) Page 1 of 2

LABOUR TOTAL: \$

2,980.00

GRAND TOTAL: \$

7,748.04

7968.04

2005.84 Parts SN 790.00 Labour 2520.00 5315.84 1063.17 @ 20% 4252.67

43 4250/2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

? Photo Lump sum repair Repair days 6

Talin Mu 3/6/19 1511 lus

Re survey on 6/6/19 1600 hos