

QUOTATION FOR VEHICLE SHF 1559 Y

PARTS				
1	1	REAR BUMPER	\$ B1	996.72 ✓
2	1	REAR BUMPER SIDE REFLECTOR (RED)	\$ S2	43.20 X
3	1	REAR BUMPER SIDE REFLECTOR CHROME	\$ S2	16.20 X
4	2	REAR BUMPER SENSOR	\$ 200.62 not/shar	421.24 LTT
5	4	REAR BUMPER SENSOR BRACKET	\$ S2	73.60 X
6	1	REAR BUMPER CENTRE GRILLE	\$ CM	199.63 ✓
7	1	REAR BUMPER TOWING COVER	\$ H1	26.57 ✓
8	1	REAR BUMPER REINFORCEMENT	\$ B1	605.22 ✓
9	2	REAR BUMPER REINFORCEMENT BRACKET (RH/LH)	\$ B180 NISA	360.00 LTT
10	2	REAR TAILLAMP (RH/LH)	\$ 0.52148 NISA CM	1,066.96 LTT
11	1	REAR FENDER SHIELD (LH)	\$ CM	197.28 ✓
12	1	REAR END PANEL	\$ B1	1,151.95 ✓
13	1	REAR END PANEL TOP GARNISH	\$ S2	69.24 X
14	1	REAR SPARE TYRE PANEL	\$ R	1,023.36 X
15	1	REAR SPARE TYRE HOLDER	\$ CM	265.20 ✓
16	1	REAR SPARE TYRE SPONGE	\$ Reform	426.94 ✓
		SUB TOTAL	\$	6,943.31
		LESS 10%	\$	694.33
		DISCOUNTED SUB TOTAL	\$	6,248.98
S/NETT				
1	1	REAR BUMPER ADVERTISEMENT LOGO	\$ Nc	100.00 60sm
		SUB TOTAL	\$	100.00
LABOUR				
1		PANEL BEATING	\$	1,000.00 900
2		SPRAYPAINTING CHARGES	\$	800.00 750
3		WIRING CHARGES	\$	40.00 20
4		DASHBOARD WIRING DIAGNOSTIC	\$	400.00 180
5		TUFF KOTE	\$	100.00 30
6		REMOVE/REFIX REAR BUMPER SENSOR	\$	80.00 60
7		REMOVE/REFIX BATTERY CONTROLLER	\$	80.00 ?
		SUB TOTAL	\$	2,500.00
		GRAND TOTAL	\$	8,848.98

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE.
THEREFORE SHOULD THERE BE ANY ADDITIONAL PARTS
REQUIRE OR DISCOVER DAMAGE DURING OUR COURSE OF
REPAIRS. WE WOULD INFORM YOU ACCORDINGLY FOR THE
NECESSARY ACTIONS. PRICES OF PARTS QUOTED ARE
SUBJECT TO CHANGE WITHOUT NOTICE.

Not Authorized
11 Sep & 7
Person After Paint
6 days

SOON HOCK MOTOR PTE LTD
Blk 10 Ang Mo Kio Industrial Park 2
#01-05/06 AAK Autopoint
Singapore 568847
6483 6016 (3 Lines) Fax: 6483 6018
Reg. No. 199804869H

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: