



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 04/06/2019

Survey Details:

Date of loss	31-May-19
Date of appointment	3-Jun-19
Date of survey	3-Jun-19
Location of survey	SOON HOCK MOTOR PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHF 1559Y
Make and Model	BYD E6H
Date of registration	18/4/2017
Excess	
Market Value	\$0
Parf Rebate	\$53,488
Nett Loss	(\$53,488)

Repair details:

Initial Estimate	\$ 8,848.98
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 4,374.25
Check items (estimate)	\$ 80.00
Labour	\$ 1,940.00
Total	\$ 6,394.25
Lump Sum(if applicable)	\$ -

Number of days for repair	6
----------------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs. We will seek mandate after our surveyor have verify the check items.

Mandate:

Liability(TP)		%
Proposed repair cost	TBA	
Loss of use	TBA	no. of days
Loss of rental	TBA	no. of days
Loss of income	TBA	no. of days
LTA search fees	TBA	
Others	TBA	
Proposed Total		