

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : **SJR 8043K**

Model : **Avante**

Year :

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear bumper	1	\$ 767.00	\$ 767.00
2	Rear bumper clips	1	\$ 50.00	\$ 50.00
3	Rear bumper retainer	2	\$ 138.00	\$ 276.00
4	Rear bumper bracket	2	\$ 78.30	\$ 313.20
5	Rear bumper reinforcement	1	\$ 360.00	\$ 360.00
6	Rear bumper sponge	1	\$ 212.50	\$ 212.50
7	Rear end panel	1	\$ 672.00	\$ 672.00
8	Rear end panel top garnish	1	\$ 179.00	\$ 179.00
9	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00
10	Bootlid	1	\$ 986.00	\$ 986.00
11	Bootlid logo	1	\$ 93.00	\$ 93.00
12	Bootlid emblem 'Avante'	1	\$ 136.00	\$ 136.00
13	Bootlid emblem 'S'	1	\$ 58.00	\$ 58.00
14	Bootlid outer garnish	1	\$ 163.50	\$ 163.50
15	Bootlid reflector	2	\$ 168.00	\$ 336.00
			Parts Sub Total :	\$ 4,652.20
			20% Discount :	\$ 930.44
			PARTS TOTAL :	\$ 3,721.76

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

2,614

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 60.00	\$ 60.00
2	Rear end panel sealant NEC	1	\$ 100.00	\$ 100.00
3	Bootlid reflector seal	2	\$ 80.00	\$ 160.00
4	Bootlid outer garnish clips	1	\$ 50.00	\$ 50.00
5	Reverse sensor NEC	2	\$ 200.00	\$ 400.00
			SPECIAL NETT TOTAL :	\$ 770.00

260

Nos.	LABOUR	S\$
1	R&R reverse sensor	\$ 60.00 100.00
2	R&R wire harness to facilitate repair work, reconnect and check function	\$ 50.00 100.00
3	Mount bench work	\$ 300.00
4	Rust proofing	\$ 60.00 100.00
5	Spray painting	\$ 800.00 1,000.00
6	Panel beat	\$ 600.00 1,000.00
		LABOUR TOTAL : \$ 2,600.00

Resurvey on 13/6/19

1,570

Lump sum repair

Tatim bi

Repair day 5

L/P = 2,614
S/N = 260
L = 1,570

4,444
disc 20%

3,555/ 5 days.

PARTS TOTAL : \$ 3,721.76
SPECIAL NETT TOTAL : \$ 770.00
LABOUR TOTAL : \$ 2,600.00
GRAND TOTAL : \$ 7,091.76