



Your Ref : D19003639MFSH

Date: 18th June 2019

Our Ref : CS/FCI19009889/Gvd3s2

M/s MS First Capital Insurance Ltd

36 Robinson Road

#16-01 City House

Singapore 068877

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FY 4259S
INSURED VEHICLE SHD 3019L ACCIDENT ON 30/05/2019**

Instruction was received to inspect the vehicle Reg. No. FY 4259S. The inspection was conducted on 04/06/2019 at the premises of M/s Sanfu Motor Pte Ltd, 1 Kaki Bukit Avenue 6 #02-43 Autobay @ Kaki Bukit Singapore 417883.

The following vehicle information was recorded:

Registration Number	: FY 4259S
Make/Model	: Honda Wave 125R
Year of Registration	: 2004
Body Colour	: Black
Chassis Number	: NF125MP0004852
Engine Capacity	: 125 cc
Speedometer Reading	: 27111 km

The vehicle sustained damages at the front portion and o/s body. (Details see photographs enclosed)


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$	300.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	95.00)
Nett Liability	S\$	205.00

Vehicle Inspected By:



XING GUO QIANG
M.MATAI, AMSAE-A
Automotive Assessor



K.K. LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.