

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 10 Jun 2019

Preliminary Advice

Vehicle No	: SKX8139A	Accident Date	: 29/05/2019
Make	: CHEVROLET SONIC	Policy No.	: DMPCSN3018601900
Assignment Date	: 04/06/2019	Excess	: S\$500.00
Date of Inspection	: 06/06/2019	Est. Duration of Repair	: 0.00
Inspection At	: SIN YEW HUP AUTO PTE LTD (HQ) BLK D4 WOODLANDS ROAD 393M, YEW TEE INDUSTRIAL ESTATE SINGAPORE 677981		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s and n/s body. The body structure affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	46,000.00
COE / PARF Rebate	:S\$	45,893.00
Salvage Value	:S\$	
Margin for Repair	:S\$	107.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :