

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Yap, Weijoe

Date: 06 Jun 2019

Preliminary Advice

Vehicle No	: SKT3260K	Accident Date	: 29/05/2019
Make	: AUDI Q5	Policy No.	: 2100420888-03
Assignment Date	: 06/06/2019	Excess	: S\$0.00
Date of Inspection	: 04/06/2019	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD - ALEXANDRA (HQ) 281 ALEXANDRA PTE LTD, LEVEL B2 SINGAPORE 159938		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,007.00
Revised Amount	:S\$	12,517.00
Check Items (Estimated)	:S\$	1,296.00
Total	:S\$	13,813.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	112,000.00
COE / PARF Rebate	:S\$	86,024.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,976.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 7 June 2019 3:28 PM
To: Claims; SUR; Admin-D (LKKAUTO)
Subject: RE: SKT 3260 K AIG OD CLAIM

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKT 3260K (Excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Wednesday, 29 May 2019 2:43 PM
To: SUR <sur@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: SKT 3260 K AIG OD CLAIM

Dear all,

Kindly assist register AIG claim above mention case and arrange survey on 4/6/2019@10am - 281 Alexandra Road Singapore 159938.

Thank you.

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

281 Alexandra Road Singapore 159938

p. +65 6366 2323, option 1

e. Claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom 281 Alexandra Road Singapore 159938 p. +65 68362223

View Received Message

This mail is associated with :

*SKT3260K (5766788854SG)

OD

May 29 2019 8:30AM

[NILS MICHAELIS]

Premium Automobiles Pte Ltd - Alexandra

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 07/06/2019 15:24 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$12517.00) - SKT3260K - Claim Handler: Chan, Yoke Shi

Approved:12517.00:To commence repairs. All awarded parts and items to be justified with clear photographs

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/05/2019 14:13
Date Of Accident	29/05/2019 08:30
Exact Location Of Accident	JELITA SHOPPING CENTRE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT3260K
Insured/Policyholder	
Name Of Registered Owner	NILS MICHAELIS
Work Permit No	G5463960R
Email Address	MICHNILS@ME.COM
Mobile Phone No	(LOCAL) +65-97360050
Alternative Phone No	OTHERS-97360050

Vehicle Particulars

Manufacturer	AUDI
Model	Q5 2.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100420888-03
Cover Note Number	-

Driver

Name of Driver	PARENZEE-MICHAELIS PAMELA ELISE
Work Permit No	G5465004W
Date Of Birth	05/03/1979
Occupation	INDOOR
Date Of Driving Pass	28/11/2014
Driving Experience	4 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97360050
Fax Number	
Contact Number	
EMail Address	PARNZEE.MICHAELIS@ME.COM

Address	9 KEPPEL BAY VIEW #02-39
Postcode	098407
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE ACCIDENT STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 20/5/11

Reporting Centre Personnel's Signature
Name: Cori Fong
NRIC/ID No: G-2040147X



SKETCH PLAN

Damage Area

I WAS FOLLOWING ON THE BROKEN HANGING BOOM AT THE JELITA SHOPPING CENTRE CARPARK ENTRANCE WHEN I MISSED MISJUDGED THE PANEL OF THE ROLLER DOOR (DOOR TO CLOSE ~~ON~~ CARPARK) AND SCRAPED MY VEHICLE (LEFT SIDE) AGAINST THE PANEL OF THE ROLLER DOOR WHICH JUTTED OUT. I BROUGHT MY CAR TO AHD IMMEDIATELY. ACCIDENT TOOK PLACE AT 08.30 ON 29 MAY 2019.

I/We declare the foregoing particulars are true in every respect.

Driver's Signature
(If driver is not the policyholder)
Date & Time: 29 MAY 09:25

Reporting Centre Personnel's Signature
Name: DAI Fong
NRIC/FIN No.: G7040107X

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	3960R
Vehicle Details	
Vehicle No.:	SKT3260K
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jun 2019
Vehicle Make:	AUDI
Vehicle Model:	Q5 2.0 TFSI QUATTRO (EU6)
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	CNC055567
Chassis No.:	WAUZZZ8R2EA120319
Maximum Power Output:	165.0 kW (221 bhp)
Open Market Value:	\$44,918.00
Original Registration Date:	29 May 2015
First Registration Date:	29 May 2015
Transfer Count:	1
Actual ARF Paid:	\$54,886.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 May 2025
PARF Rebate Amount:	\$41,164.00
Intended COE Rebate Details	
COE Expiry Date:	28 May 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$78,001.00
COE Rebate Amount:	\$44,860.00
Total Rebate Amount:	\$86,024.00

The information contained herein is correct as at 04 Jun 2019

OK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0710/2019/DY/TF
Date : 01-Jun-19

Vehicle NOT IN workshop

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Nils Michaelis
Address : 9 Keppel Bay View
#02-39
Singapore 098407
Telephone : HP +65 97360050
Type of Claim : Own Damage Claims
2100420888-03
Vehicle No : **SKT 3260 K**
Model Code : Audi Q5 2.0 TFSI QU
Model / Year : May-15
Engine No : CNC 055567
Chassis No : WAUZZZ8R2EA120319
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-May-19
Place of Accident : Jelita Shopping Centre



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : NILS MICHAELIS
Period of Insurance : 10 Jul 2018 To 28 Nov 2019
Engine No. : CNC055567
Chassis No. : WAUZZZ8R2EA120319

Vehicle No. : SKT3250K
Policy No. : 2100420688-03
Endorsement No. : 00000000278154
Issued Date : 14 May 2019

ABOUT THE COVER

Make/Model : AUDI Q5 2.0 TFSI QU (FACELIFT)(DYNAMIC STEERING)
Engine Capacity/Tonnage : 1,984.00 CC Sum Insured : Market Value First Year of Registration : 2015
Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

at The Policyholder

or Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$1,500 as "Young and/or Inexperienced Driver Excess" ("YIDEX") if You are or Your Authorized Driver (named or unnamed) is under the age of 25 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing. The carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800hrs - 2000hrs Optional

* Limitations imposed respectively by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 185) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

NILS MICHAELIS - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center, Audi, 55 Ulu Road, Singapore 408699 52662328

For other Approved Reporting Centres/Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6290. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 185), Part IV of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125231

PREMIUM LEASING - CK

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938


Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

0504125231

For more information, please contact your broker or AIG Singapore at +65 6338 6290.

0504125231



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0710/2019/DY/TF
Date : 1-Jun-19

Vehicle NOT IN workshop

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Steve,
5 days - ok - Jy - 03 Aug 2019

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Nils Michaelis
Address : 9 Keppel Bay View
#02-39
Singapore 098407
Telephone : HP +65 97360050
Type of Claim : Own Damage Claims
: 2100420888-03
Vehicle No : **SKT 3260 K**
Model Code : Audi Q5 2.0 TFSI QU
Model / Year : May-15
Engine No : CNC 055567
Chassis No : WAUZZZ8R2EA120319
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-May-19
Place of Accident : Jelita Shopping Centre

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKT 3260 K

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer lhs front door and lhs rear door's multi-lock systems and power window devices. Inspect for damages.	S/N \$ 560.00 ✓
2	To dismantle and renew lhs front door, lhs rear door and lhs wing mirror assy. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,800.00 1250 ✓
3	To respray lhs front door, lhs rear door, door handle, wing mirror cover and door covers.	\$ 3,300.00 1950 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 6,852.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 3260 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR - LH / <i>DN</i>	\$ 2,829.00	2263.20
2	GROMMET X <i>ACC</i>	\$ 8.00	X <i>NN</i>
3	FRONT DOOR ATTACHMENT PARTS - LH ?	\$ 117.00	X <i>NN</i>
4	FRONT DOOR OUTER SEAL - LH / <i>ACC</i>	\$ 185.00	147.60
5	BONDING AGENT / <i>ACC</i>	\$ 45.00	35.92
6	CLEANING SOLUTION / <i>ACC</i>	\$ 65.00	51.68
7	APPLICATOR X <i>ACC</i>	\$ 7.00	X <i>NN</i>
8	FRONT DOOR CATCH - LH X	\$ 132.00	X <i>NN</i>
9	FRONT DOOR HANDLE - LH / <i>ACC</i>	\$ 137.00	109.20
10	FRONT DOOR HANDLE SENSOR - LH ?	\$ 237.00	X <i>NN</i>
11	FRONT DOOR HANDLE CAP - LH / <i>ACC</i>	\$ 27.00	20.96
12	FRONT DOOR HANDLE MOUNTING BAR - LH ?	\$ 286.00	X <i>NN</i>
13	WIND MIRROR MOUNTING - LH (<i>ACC</i>) <i>ACC</i>	\$ 1,132.00	905.60
14	WIND MIRROR CAP - LH X <i>R</i>	\$ 382.00	X
15	WIND MIRROR GLASS - LH X	\$ 1,132.00	X <i>NN</i>
16	WIND MIRROR TURN SIGNAL - LH / <i>ACC</i>	\$ 149.00	119.20
17	WIND MIRROR ENTRY LIGHT - LH X	\$ 196.00	X <i>NN</i>
18	FRONT DOOR WINDOW CHROME SLOT SEAL - LH ?	\$ 285.00	X <i>NN</i>
19	FRONT DOOR LOWER COVER - LH / <i>ACC</i>	\$ 467.00	373.60
20	REAR DOOR - LH / <i>DN</i>	\$ 2,829.00	2263.20
SUB- TOTAL SPARE PARTS		\$ 10,647.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 3260 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR DOOR GROMMET <i>X A</i>	\$ 8.00	<i>X N/A</i>
22	REAR DOOR OUTER SEAL - LH <i>/ MC</i>	\$ 193.00	<i>154</i>
23	BONDING AGENT <i>/ MC</i>	\$ 45.00	<i>35.92</i>
24	CLEANING SOLUTION <i>/ MC</i>	\$ 65.00	<i>51.68</i>
25	APPLICATOR <i>X</i>	\$ 7.00	<i>X N/A</i>
26	REAR DOOR INNER STONE CHIP PROTECTION FILE - LH <i>? net</i>	\$ 71.00	<i>56.43</i>
27	REAR DOOR CATCH - LH <i>X</i>	\$ 132.00	<i>N/A</i>
28	REAR DOOR ATTACHMENT PARTS - LH <i>X</i>	\$ 112.00	<i>X N/A</i>
29	SILL PANEL SEAL - LH <i>X</i>	\$ 201.00	<i>X N/A</i>
30	REAR DOOR LOWER COVER - LH <i>/ MC</i>	\$ 374.00	<i>298.80</i>
31	SUNDRIES <i>?</i>	\$ 300.00	<i>X N/A</i>
TOTAL SPARE PARTS		\$ 12,155.00	
TOTAL LABOUR CHARGES		\$ 6,852.00	
GRAND TOTAL		\$ 19,007.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax



Name : Steve (LKK)
Surveyed Date : 4/6/19, 10.10 am
Authorised Date : 00 - Not Auth (Revt)
Excess Cost : EXCESS - ?
Liability : S dly
Remarks : P/P
Ry bel spj

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKT 3260 K

S/N	Nature of Jobs	Estimated Charges			
1	To remove and transfer lhs front door and lhs rear door's multi-lock systems and power window devices. Inspect for damages.	S/N	\$ 560.00	\$ 560.00	/
2	To dismantle and renew lhs front door, lhs rear door and lhs wing mirror assy. Re-organise rear crash management components. Reinstall all parts removed.		\$ 2,800.00	\$ 1,250.00	/
3	To respray lhs front door, lhs rear door, door handle, wing mirror cover and door covers.		\$ 3,300.00	\$ 1,950.00	/
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00	/
TOTAL LABOUR CHARGES		:	\$ 6,852.00	\$ 3,952.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 3260 K

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
1	FRONT DOOR - LH	\$	2,829.00	\$ 2,263.20
2	GROMMET	\$	8.00	
3	FRONT DOOR ATTACHMENT PARTS - LH	\$	117.00	
4	FRONT DOOR OUTER SEAL - LH	\$	185.00	\$ 147.60
5	BONDING AGENT	\$	45.00	\$ 35.92
6	CLEANING SOLUTION	\$	65.00	\$ 51.68
7	APPLICATOR	\$	7.00	
8	FRONT DOOR CATCH - LH	\$	132.00	
9	FRONT DOOR HANDLE - LH	\$	137.00	\$ 109.20
10	FRONT DOOR HANDLE SENSOR - LH	\$	237.00	
11	FRONT DOOR HANDLE CAP - LH	\$	27.00	\$ 20.96
12	FRONT DOOR HANDLE MOUNTING BAR - LH	\$	286.00	
13	WIND MIRROR MOUNTING - LH	\$	1,132.00	\$ 905.60
14	WIND MIRROR CAP - LH	\$	382.00	
15	WIND MIRROR GLASS - LH	\$	1,132.00	
16	WIND MIRROR TURN SIGNAL - LH	\$	149.00	\$ 119.20
17	WIND MIRROR ENTRY LIGHT - LH	\$	196.00	
18	FRONT DOOR WINDOW CHROME SLOT SEAL - LH	\$	285.00	
19	FRONT DOOR LOWER COVER - LH	\$	467.00	\$ 373.60
20	REAR DOOR - LH	\$	2,829.00	\$ 2,263.20
SUB- TOTAL SPARE PARTS			\$ 10,647.00	\$ 6,290.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 3260 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
	c/f	\$	6,290.16
21	REAR DOOR GROMMET	\$ 8.00	
22	REAR DOOR OUTER SEAL - LH	\$ 193.00	\$ 154.00
23	BONDING AGENT	\$ 45.00	\$ 35.92
24	CLEANING SOLUTION	\$ 65.00	\$ 51.68
25	APPLICATOR	\$ 7.00	
26	REAR DOOR INNER STONE CHIP PROTECTION FILE - LH	\$ 71.00	\$ 56.48
27	REAR DOOR CATCH - LH	\$ 132.00	
28	REAR DOOR ATTACHMENT PARTS - LH	\$ 112.00	
29	SILL PANEL SEAL - LH	\$ 201.00	
30	REAR DOOR LOWER COVER - LH	\$ 374.00	\$ 298.80
31	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		\$ 12,155.00	\$ 6,887.04
TOTAL LABOUR CHARGES		\$ 6,852.00	\$ 3,952.00
GRAND TOTAL		\$ 19,007.00	\$ 10,839.04

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKT 3260 K

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0710/2019/KK

9 Sep 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

1 total pages

RE: INSURANCE CLAIM FOR SKT 3260 K, Audi Q5 2.0 TFSI QU.

With reference to the above-mentioned vehicle, no. **SKT 3260 K**, claimant, **Mr Nils Michaelis**, please find the related document per attached.

1. A copy of the Original invoice no. 85014220 – S\$ 10,527.77.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept


Encls

AIG – SKT 3260 K

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 1 15:16

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014220 Date : 06/09/2019 Order : SKT3260K Term : 30	Account: A0006 (T) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SKT3260K (V 23848) Regn Date: 29/05/2015 Mileage: 52715 WIP No.: 55165

Model: Q5 2.0 TFSI QU 8RB0AA (YOM 201 Chassis: WAUZZZ8R2EA120319 Engine: CNC 055567 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1000.00	1.00	-1,000.00
S	BODYWORK	M: TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	560.00	1.00	560.00
S	BODYWORK	M: TO DISMANTLE AND RENEW LHS FRONT DOOR, LHS REAR DOOR AND LHS WING MIRROR ASSY. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, DOOR HANDLE, WING MIRROR COVER AND DOOR COVER	1950.00	1.00	1,950.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8R2857409L 01C	MOUNTING	Less 020%	1.00	1132.00
X	A8R0831051E	DOOR	Less 020%	1.00	2829.00
X	A8R0833051B	DOOR (LAST)	Less 020%	1.00	2829.00
X	A8T0837205A GRU	HANDLE (LAST)	Less 020%	1.00	136.50
X	A8R0837911L	SEAL (LAST)	Less 020%	1.00	184.50
X	A8R0839981C	FOIL	Less 020%	1.00	70.60
X	A8K0839879 GRU	(A) (SK) CAP 11/6/19	Less 020%	1.00	26.20
X	A8R0839911L	SEAL LH (LAST)	Less 020%	1.00	192.50
X	AD 355205A2	(A) (SK) BONAGENT 11/6	Less 020%	2.00	44.90
X	AD 00940104	(A) (SK) CLEANER 11/6/	Less 020%	2.00	64.60
X	A4L0949101A	TURN SIGNAL (LAST)	Less 020%	1.00	149.00
X	A8R0853959L GRU	(A) (SK) COVER 11/6/19	Less 020%	1.00	467.00
X	A8R0853969L GRU	(A) (SK) COVER 11/6/19	Less 020%	1.00	373.50
Parts 6,887.04					
Labour 0.00					
Sublet 3,952.00					
Menus 0.00					
Lubricant 0.00					
Sub-Total					9,839.04
7% GST					688.73
Grand Total					10,527.77



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKT3260K

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/710/2019/TF
5 July 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

1 total pages

Make & Model : Audi Q5 2.0 TFSI QU
Vehicle Chassis No. : WAUZZZ8R2EA120319
Vehicle Regn No. : **SKT3260K**
Vehicle Mileage : 52715 KM
Vehicle Owner : Mr. Nils Michaelis
Certificate No : 2100420888-03
Own Damage Excess : \$1,070.00 (7% GST)
Accident Date : 29 May 2019
Place : Jelita Shopping center carpark
Repair Cost : \$ 10,527.77
WIP No. : 55165
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : Nils Michaelis
Time : 12/07/2019
Date : 11:00 am

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jun 2019		06 Jun 2019 10:01 Edit Adj Rpt	S\$10,839.04 Edit Estimates	S\$10,839.04 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NILS MICHAELIS , ID: G5463960R, Tel: +6597360050								
Vehicle Reg. No.:	SKT3260K	Date of Loss:	29/05/2019 08:00 - :59 [48 Months From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 5766788854SG	Policy/Cover Note No.:	2100420888-03 (Comprehensive)						
		Excess:	S\$1,000.00						
Repairer:	Premium Automobiles Pte Ltd - Alexandra (HQ) 281 Alexandra Pte Ltd, Level B2, 159938 Alexandra - Tel: 63882233								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Yoke Shi] yokeshi.chan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 17/06/2019]								
Driver/Custodian:	PARENZEE-MICHAELIS PAMELA ELISE (40 / Female), NRIC: G5465004W, Tel: +6597360050 Email: PARNZEE.MICHAELIS@ME.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (07/06/2019): Alert - Adj Mandate Approved (S\$12517.00) - SKT3260K - Claim Handler: Chan, Yoke... - AIG_SG (06/06/2019): SKT3260K / OD / 29/05/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKT3260K (5766788854SG)

OD

May 29 2019 8:30AM

[NILS MICHAELIS]

Premium Automobiles Pte Ltd - Alexandra

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)
[View](#) [View in Browser](#)

Assessment Reports

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/19 12:03	Adjuster Immediate Advice	 Load HTM	☒

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/08/19 19:50	General View	 Load JPG	☒
2	13/08/19 19:50	General View	 Load JPG	☒
3	13/08/19 19:50	General View	 Load JPG	☒
4	13/08/19 19:50	General View	 Load JPG	☒
5	13/08/19 19:50	General View	 Load JPG	☒
6	13/08/19 19:50	Odometer Reading	 Load JPG	☒
7	13/08/19 19:50	Chassis Number	 Load JPG	☒
8	13/08/19 19:50	General View	 Load JPG	☒
9	13/08/19 19:50	General View	 Load JPG	☒
10	13/08/19 19:50	General View	 Load JPG	☒
11	13/08/19 19:50	General View	 Load JPG	☒
12	13/08/19 19:50	General View	 Load JPG	☒
13	13/08/19 19:50	General View	 Load JPG	☒
14	13/08/19 19:50	General View	 Load JPG	☒
15	13/08/19 19:50	General View	 Load JPG	☒
16	13/08/19 19:50	General View	 Load JPG	☒
17	13/08/19 19:50	General View	 Load JPG	☒
18	13/08/19 19:50	General View	 Load JPG	☒
19	13/08/19 19:50	General View	 Load JPG	☒
20	13/08/19 19:50	General View	 Load JPG	☒
21	13/08/19 19:50	General View	 Load JPG	☒
22	13/08/19 19:50	General View	 Load JPG	☒
23	13/08/19 19:50	General View	 Load JPG	☒
24	13/08/19 19:50	General View	 Load JPG	☒
25	13/08/19 19:50	General View	 Load JPG	☒
26	13/08/19 19:50	Before Repair Photo	 Load JPG	☒
27	13/08/19 19:50	Before Repair Photo	 Load JPG	☒
28	13/08/19 19:50	Before Repair Photo	 Load JPG	☒
29	13/08/19 19:50	Before Repair Photo	 Load JPG	☒
30	13/08/19 19:50	Before Repair Photo	 Load JPG	☒

Documentation

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/19 11:42	Certificate of Insurance	 Load JPG	☒
2	06/06/19 11:42	Driver's Driving License and NRIC	 Load JPG	☒
3	06/06/19 11:42	ESTIMATE	 Load PDF	
4	06/06/19 11:42	Singapore Accident Statement	 Load PDF	
5	17/09/19 11:46	DISCHARGE VOUCHER	 Load PDF	
6	17/09/19 11:46	WORKSHOP INVOICE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser ▼
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1 per page ▼	☒
1	29/05/19 14:39	Accident Statement	 Load HTM	☐
Photos/Images			3 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	29/05/19 14:30	Accident Photo	 Load JPG	☒
2	29/05/19 14:30	Accident Photo	 Load JPG	☒
3	29/05/19 14:30	Accident Photo	 Load JPG	☒
4	29/05/19 14:30	Accident Photo	 Load JPG	☒
5	29/05/19 14:30	Accident Photo	 Load JPG	☒
6	29/05/19 14:30	Accident Photo	 Load JPG	☒
7	29/05/19 14:30	Accident Photo	 Load JPG	☒
8	29/05/19 14:30	Accident Photo	 Load JPG	☒
9	29/05/19 14:30	Accident Photo	 Load JPG	☒
10	29/05/19 14:30	Accident Photo	 Load JPG	☒
11	29/05/19 14:30	Accident Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	29/05/19 14:37	Sketch Plan	 Load JPG	☒
2	29/05/19 14:37	Sketch Plan #2	 Load JPG	☒
3	29/05/19 14:38	INTERVIEW FORM	 Load JPG	☒
4	29/05/19 14:38	INTERVIEW FORM	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19009932/ETD3S2

Date: 17/09/2019

REFERENCE

Insured/Claimant:	NILS MICHAELIS	Policy No:	2100420888-03	
Date of Loss:	29/05/2019	Nature of Claim:	OD	Claim No: 5766788854SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT3260K		
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (A)	Engine No:	CNC055567
Reg. Date:	29/05/2015 (Man. Year: 2014)	Chassis No:	WAUZZZ8R2EA120319
Colour:	White	Odometer:	51187 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$112,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,155.00	6,887.04	5,267.96	43.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,852.00	3,952.00	2,900.00	42.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,007.00	10,839.04	8,167.96	42.97
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	18,007.00	9,839.04	8,167.96	45.36
+ GST 7.00/7.00% (S\$)	1,260.49	688.73	571.76	45.36
Nett Amount (S\$)	19,267.49	10,527.77	8,739.72	45.36

INSPECTION

Date of Assignment: 06/06/2019

Date Inspected: 04/06/2019 Inspected At:

281 Alexandra Pte Ltd, Level B2

Singapore 159938

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR - LH	Dented	2,829.00 FS	*2,263.20 FS
2	1	*GROMMET	Not Necessary	8.00 FS	*- FS
3	1	*FRONT DOOR ATTACHMENT PARTS - LH	Not Necessary	117.00 FS	*- FS
4	1	*FRONT DOOR OUTER SEAL - LH	Necessary	185.00 FS	*147.60 FS
5	1	*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
6	1	*CLEANING SOLUTION	Necessary	65.00 FS	*51.68 FS
7	1	*APPLICATOR	Not Necessary	7.00 FS	*- FS
8	1	*FRONT DOOR CATCH - LH	Not Necessary	132.00 FS	*- FS
9	1	*FRONT DOOR HANDLE SENSOR - LH	Not Necessary	237.00 FS	*- FS
10	1	*FRONT DOOR HANDLE CAP - LH	Necessary	27.00 FS	*20.96 FS
11	1	*FRONT DOOR HANDLE MOUNTING BAR - LH	Not Necessary	286.00 FS	*- FS
12	1	*WIND MIRROR CAP - LH	Repair	382.00 FS	*- FS
13	1	*WIND MIRROR GLASS - LH	Not Necessary	1,132.00 FS	*- FS
14	1	*WIND MIRROR TURN SIGNAL - LH	Cut	149.00 FS	*119.20 FS
15	1	*WIND MIRROR ENTRY LIGHT - LH	Not Necessary	196.00 FS	*- FS
16	1	*FRONT DOOR WINDOW CHROME SLOT SEAL - LH	Not Necessary	285.00 FS	*- FS
17	1	*FRONT DOOR LOWER COVER - LH	Necessary	467.00 FS	*373.60 FS
18	1	*REAR DOOR - LH	Dented	2,829.00 FS	*2,263.20 FS
19	1	*REAR DOOR GROMMET	Not Necessary	8.00 FS	*- FS
20	1	*REAR DOOR OUTER SEAL - LH	Necessary	193.00 FS	*154.00 FS
21	1	*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
22	1	*CLEANING SOLUTION	Necessary	65.00 FS	*51.68 FS
23	1	*APPLICATION	Not Necessary	7.00 FS	*- FS
24	1	*REAR DOOR INNER STONE CHIP PROTECTION FILE - LH	Necessary	71.00 FS	*56.48 FS
25	1	*REAR DOOR CATCH - LH	Not Necessary	132.00 FS	*- FS
26	1	*REAR DOOR ATTACHMENT PARTS - LH	Not Necessary	112.00 FS	*- FS
27	1	*SILL PANEL SEAL - LH	Not Necessary	201.00 FS	*- FS
28	1	*REAR DOOR LOWER COVER - LH	Necessary	374.00 FS	*298.80 FS
29	1	*WIND MIRROR MOUNTING - LH (BLACK)	Cut	1,132.00 FS	*905.60 FS
30	1	*FRONT DOOR HANDLE - LH	Cut	137.00 FS	*109.20 FS
31	1	*SUNDRIES	Not Necessary	300.00 FS	*- FS
			Total Parts (\$\$)	12,155.00	6,887.04

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEMS AND POWER WINDOW DEVICES. INSPECT FOR DAMAGE	New	560.00	560.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR, LHS REAR DOOR AND LHS WING MIRROR ASSY. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,250.00
3	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, DOOR HANDLE, WING MIRROR COVER AND DOOR COVERS	New	3,300.00	1,950.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			6,852.00	3,952.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >