

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lee, Ming-Yao

Date: 06 Jun 2019

Preliminary Advice

Vehicle No	: SLF6083Y	Accident Date	: 30/05/2019
Make	: AUDI A6	Policy No.	: 2100481148-02
Assignment Date	: 06/06/2019	Excess	: S\$0.00
Date of Inspection	: 04/06/2019	Est. Duration of Repair	: 4 days
Inspection At	: Premium Automobiles Pte Ltd - Alexandra (HQ) 281 Alexandra Pte Ltd, Level B2 Singapore 159938		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,489.00
Revised Amount	:S\$	13,687.00
Check Items (Estimated)	:S\$	2,134.00
Total	:S\$	15,821.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	72,506.00
Salvage Value	:S\$	
Margin for Repair	:S\$	47,494.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :