

(08/11/13)

ASS. REC. BY:

Steve

REF

CCS/AIG19009933/Ed302

ASSIGNMENT

From:

Date:

04/6/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLF 6083Y

at Workshop n/s

Premium

of

281 Alexandra Rd

Insured:

Policy No.

2100481148

Claims No.

511373648984

Sum Insured:

Excess:

\$0/-

(Client's Record)

Make of Veh:

10am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

120K

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLF 6083Y

Yr Regn:

31/8/16

Type:

M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A6

c.c

1798

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

38031

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAA 2224606N099857

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/5/19

D.O.I.

4/6/19

Survey held at

Premium Alexandra Rd.

Des. of Damages

Frt /

Rear /

O/S /

N/S /

U/C /

Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-120K

SLF6083Y-CCS/AIG19009933/Arbea DOA:7/8/2019

06/06/19

@ 13:50 pm revised IA to Lee May Yeo via merim.

06/06/19

@ 13:51 pm mandate requested authorize repair to AIG via merim.

16/08/19

Combined P/P \$11,453.84 @ delays with Steve

(\$11,055.16 Rd - 49%)

RECEIVED 27 AUG 2019

Date/Time, File Pass to?

23/08/19



Prel. Report



Final Report

1) Tipin

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

200

11

211

Report Format :

Lump Sum I.B.:

(\$ 11,453.84 P/P)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lee, Ming-Yao

Date: 06 Jun 2019

Preliminary Advice

Vehicle No	: SLF6083Y	Accident Date	: 30/05/2019
Make	: AUDI A6	Policy No.	: 2100481148-02
Assignment Date	: 06/06/2019	Excess	: S\$0.00
Date of Inspection	: 04/06/2019	Est. Duration of Repair	: 4 days
Inspection At	: Premium Automobiles Pte Ltd - Alexandra (HQ) 281 Alexandra Pte Ltd, Level B2 Singapore 159938		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,489.00
Revised Amount	:S\$	13,687.00
Check Items (Estimated)	:S\$	2,134.00
Total	:S\$	15,821.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	72,506.00
Salvage Value	:S\$	
Margin for Repair	:S\$	47,494.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 16 August 2019 11:54 AM
To: 'jiayee.yap@premiumauto.com.sg'; 'cs-a@lkkauto.com'; 'admin-a@lkkauto.com'; 'Adrian Ling'; 'stevechen@lkkauto.com'
Cc: 'Boo seng yak'; 'Carrine Leong'; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SLF6083Y - OD AIG - SURVEYED 4 JUNE 19

Dear Jia Yee,

Confirmed final fig \$ 11,453.84 @ 4 days of repair of repairs before excess \$ 0/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Monday, 5 August 2019 2:02 PM
To: SUR <sur@lkkauto.com>
Subject: FW: FINAL REVISION - SLF6083Y - OD AIG - SURVEYED 4 JUNE 19

From: jiayee.yap@premiumauto.com.sg <jiayee.yap@premiumauto.com.sg>
Sent: Saturday, 3 August, 2019 12:13 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Carrine Leong' <carrine.leong@premiumauto.com.sg>; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SLF6083Y - OD AIG - SURVEYED 4 JUNE 19

Hi Adrian, Steve and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$11,453.84 @ 4 days of repairs.

Your early closure is well appreciated.

Thanks & Best Regard
JiaYee Yap
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. jiayee.yap@premiumauto.com.sg w. www.audi.com.sg

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 7 June 2019 3:39 PM
To: 'Claims'
Cc: SUR
Subject: RE: OD CLAIM FOR SLF 6083 Y - AIG
Attachments: ESTIMATE.pdf

Hi Tony,

As instructed by our client, please proceed to repair the insured vehicle **SLF 6083Y (Excess \$ 0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Friday, 7 June 2019 1:56 PM
To: 'Claims' <claims@premiumauto.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SLF 6083 Y - AIG

Hi Tony,

Still pending approval from AIG.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Friday, 7 June 2019 1:39 PM
To: claims@premiumauto.com.sg; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'SUR' <sur@lkkauto.com>

View Received Message

This mail is associated with :

***SLF6083Y (5113736439SG)**

OD

May 30 2019 10:35AM

[YANG KAM SENG]

Premium Automobiles Pte Ltd - Alexandra

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 07/06/2019 15:31 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$15821.00) - SLF6083Y - Claim Handler: Nadaraja, Deeban

Approved:15821.00:To commence repairs. All awarded parts and labour to be justified with clear photographs.

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8476B
Vehicle Details	
Vehicle No.:	SLF6083Y
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jun 2019
Vehicle Make:	AUDI
Vehicle Model:	A6 1.8 TFSI ULTRA (PI) (NAV)
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	CYG010339
Chassis No.:	WAUZZZ4G0GN099857
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$39,400.00
Original Registration Date:	31 Aug 2016
First Registration Date:	31 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$42,160.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2026
PARF Rebate Amount:	\$31,620.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,956.00
COE Rebate Amount:	\$40,886.00
Total Rebate Amount:	\$72,506.00

The information contained herein is correct as at 04 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/05/2019 16:55
Date Of Accident	30/05/2019 10:35
Exact Location Of Accident	BLK 54 TEBAN GARDEN OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF6083Y
Insured/Policyholder	
Name Of Registered Owner	YANG KAM SENG
NRIC No	S7708476B
Email Address	AYANGKS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94508338
Alternative Phone No	OTHERS-94508338

Vehicle Particulars

Manufacturer	AUDI
Model	A5 1.8 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100481148-02
Cover Note Number	-

Driver

Name of Driver	YANG KAM SENG
NRIC No	S7708476B
Date Of Birth	26/03/1977
Occupation	INDOOR
Date Of Driving Pass	22/09/1999
Driving Experience	19 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94508338
Fax Number	
Contact Number	OTHERS-94508338
Email Address	AYANGKS@GMAIL.COM

Address	BLK 987B JURONG WEST STREET 93
	#04-573
Postcode	642987
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NPC
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO TRAFFIC POLICE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMG5823T
Vehicle Make/Model/Colour	RENAULT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:
31 May 11:00H

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Gary Foon
NRIC/FIN No: 620441679

Sketch Plan #2

SKETCH PLAN



A = SLF6083Y

B = SMG5823T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to the police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time

31 May 1100H

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: Tony Fong

NRIC/Fin No: 620461477

Police Report



**SINGAPORE
POLICE FORCE**



E201905311004

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 646818
Tel No: 1800-2689999

1 of 3

Report No: T201905311004

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/05/2019 07:47	vide Report No:	Station Diary No.: 24
--	-----------------	--------------------------

Informant's Particulars

Name of Informant: YANG KAM SENG		Address: APT BLK 987B JURONG WEST STREET 93 #04-573 SINGAPORE 642987	
ID Type / ID No: NRIC NO / S77084768		Contact No: Home/Office:	Mobile: 94508338
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 42	Date of Birth: 26/03/1977	Type of Informant: Vehicle Owner
Race: Chinese		Language:	Institution / School Name:
Occupation: Company director		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 30/05/2019 10:30	Type of Location: Car Park
Location: Along Road 1 TEBAN GARDENS ROAD IN FRONT OF BLK 54 TEBAN GARDENS OPEN SPACE CAR PARK			
Weather: Clear	Road Surface: Dry	Road Speed Limit	
Traffic Flow: Two Way	Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SLF6083Y	Car	AUDI	A5 1.8 TFSI ULTRA (PI) (NAV)	White		0
SMG5823T	Car	RENAULT	GRAND SCENIC IV 1.5 DCI AT EU6	Grey		0

Police Report



SINGAPORE
POLICE FORCE



7001900310024

Police Station Of Origin:
Jurong West N.P.C.
700 Corporation Road SINGAPORE 640018
Tel No: 1800 2699999

Page 1
Report No: 7001900310024

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report

J1

Sgt 2 SITI KHARUNISA BINTE RAMANAH

Signature Of Informant

Signature Of Interpreter

Not applicable

Date/Time

21/05/2019 07:47

Officer In Charge Of Case:

TP / HRT /

SSI GOH GEOK LYE

Contact No.: 65478148

Classification Of Case

Authentication Stamp

AP 104

SINGAPORE
POLICE FORCE

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Jurong West N.P.C
700 Corporation Road SINGAPORE 649618
Tel No. 1800-2689999



T/20190531/2024

2 of 3

Report No. T/20190531/2024

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Vehicle Owner			
Name	YANG KAM SENG	ID No.	S7708476B
Related Vehicle	SLF6063Y (Car)	Contact No.	94508338
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details

On 30/05/2019 at 1000hrs, I had parked my vehicle a White Audi, SLF6063Y at the open space car park in front of Blk 54 Teban Gardens Road. Later at about 1154hrs, I drove off and arrived at 54 Serangoon North for work and discovered there are scratches and a crack on my vehicle's front body panel. I then made a check on my in-car camera and discovered that a grey Renault vehicle, SMG5823T had parked his vehicle on my right on 30/05/2019 at 1028hrs and side swiped my vehicle when he was exiting his parking lot at 1034hrs. There were also white scratch marks on his left body panel. I also observed the driver had actually alighted from his vehicle to make a check on my vehicle. He then left without leaving his contact information. No traffic police was at scene.

I have an in-car camera recording the accident and it is available for traffic police to do their investigations.



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : YANG KAM SENG (YANG JINCHENG)
Period of Insurance : 31 Aug 2018 To 30 Aug 2019
Engine No. : CYG010339
Chassis No. : WAUZZZ4G0GN099857

Vehicle No. : SLF6083Y
Policy No. : 2100481148-02
Endorsement No. :
Issued Date : 30 Jul 2018

ABOUT THE COVER

Make/Model : AUDI
Engine Capacity/Tonnage : 1,798.00 CC
Sum Insured : Market Value
First Year of Registration : 2016
Driver Restriction : NA
Off Peak Car : No
Insuring with COE/PAF : Yes
Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorized Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 186) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 **Oen Damage - \$800** **Theft - \$0** **Flood Driver - \$0**

Section 2
Property Damage - \$0

Windscreen - \$100

Named Driver and Excess (where applicable)

YANG KAM SENG (YANG JINCHENG) - \$800 (Oen Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408500 63962323

For other Approved Reporting Centres/Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 186), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSP08A

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7708476B



Name

YANG KAM SENG
(YANG JINCHENG)

杨锦成

Race

CHINESE

Date of birth

26-03-1977

Sex

M

S7708476B

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number S7708476B

Name

YANG KAM SENG
(YANG JINCHENG)

Issue Date 26 Mar 1977

Valid Until 25 Aug 2005



4057789



NRIC No. S7708476B

Date of issue

18-06-2007

Address

APT BLK 987B JURONG WEST STREET 93
#04-573
SINGAPORE 642987

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

GROUP 1A/1B

Class 3

Motor Cars and Motor Tractors the weight of
which vehicle does not exceed 3500 kilograms

22 Sep 1999



License No. S7708476B

NP 428A

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0718/2019/DY
Date	:	04-Jun-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Yang Kam Seng
Address	:	Blk 987B Jurong West St 93 #04-573 Singapore 642987
Telephone	:	HP +65 94508338
Type of Claim	:	Own Damage Claims
Policy No.	:	2100481148-02
Vehicle No	:	SLF 6083 Y
Model Code	:	Audi A6 1.8 TFSI S-Tronic
Model / Year	:	31-08-16
Engine No	:	CYG 010339
Chassis No	:	WAUZZZ4G0GN099857
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	30-May-19
Place of Accident	:	Blk 54 Teban Garden Open Car-Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLF 6083 Y

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓ ✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	500 - 1.5 \$ 2,800.00	750 ✓
3	To respray front bumper and rhs front fender.	550 - 2 \$ 2,000.00	1100 ✓
4	To carry out diagnostic check.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 5,472.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 6083 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER COVER / CHT	\$ 2,443.00	1954.40
2	FRONT BUMPER GRILLE - CENTER ?	\$ 598.00	X NAI
3	FRONT BUMPER LOCKING CLIP ?	\$ 65.00	X NAI
4	FRONT BUMPER LOWER CHROME TRIM ?	\$ 276.00	X NAI
5	FRONT BUMPER FIXING PARTS ?	\$ 45.00	X NAI
6	FRONT BUMPER CLOSING ELEMENT - CENTER X NAI	\$ 199.00	
7	FRONT BUMPER SPOILER X NAI	\$ 227.00	
8	AIR GRILLE - RH ?	\$ 319.00	X NAI
9	AIR GRILLE COVER - RH ?	\$ 46.00	X NAI
10	FRONT WHEEL SPOILER - RH X NAI	\$ 242.00	
11	HEADLIGHT WASHER COVER - LH / RH ?	\$ 104.00	X NAI
12	FOAM FILLER PIECE X NAI	\$ 215.00	
13	FRONT REINFORCEMENT X NAI	\$ 754.00	
14	FRONT BUMPER GUIDE PIECE - RH ?	\$ 34.00	X NAI
15	FRONT BUMPER SENSOR ?	1 \$ 231.00	X NAI
16	SENSOR SEAL RING / MC	\$ 5.00	3.84
17	FRONT FENDER - RH X R	\$ 1,269.00	
18	FRONT FENDER ATTACHMENT PARTS X NAI	\$ 92.00	
19	FRONT FENDER STONE GUARD FILE - RH / MC	\$ 110.00	88
20	FRONT FENDER BRACE - RH X NAI	\$ 75.00	
SUB - TOTAL SPARE PARTS		\$ 7,349.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLF 6083 Y**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT WHEEL HOUSING LINER - RH X NAI	\$ 256.00	
22	FRONT WHEEL HOUSING LINER ATTACHMENT X NAI	\$ 66.00	
23	STONE CHIP GUARD - RH ?	\$ 66.00	X NAI
24	STONE CHIP GUARD ADHESIVE TAPE ?	\$ 50.00	X NAI
25	HEADLIGHT MOUNTING - RH X NAI	\$ 107.00	
26	HEADLIGHT - RH / CUT	\$ 8,607.00	6855.60
27	LIFT CYLINDER - RH X NAI	\$ 216.00	
28	SUNDRIES ?	\$ 300.00	X NAI
TOTAL SPARE PARTS		\$ 17,017.00	
TOTAL LABOUR CHARGES		\$ 5,472.00	
GRAND TOTAL		\$ 22,489.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Steve (LKK) 7/6/19, 12 32pm
: OD - Not Authorised (Direct)
: Excess - ?
: P/P
: Ry bef spy
: 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0718/2019/DY
Date : 04-Jun-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Steve,

4 days - ok - Jy - 03 AUG 19

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Yang Kam Seng
Address : Blk 987B Jurong West St 93
#04-573
Singapore 642987
Telephone : HP +65 94508338
Type of Claim : Own Damage Claims
Policy No. : 2100481148-02
Vehicle No : **SLF 6083 Y**
Model Code : Audi A6 1.8 TFSI S-Tronic
Model / Year : 31/08/2016
Engine No : CYG 010339
Chassis No : WAUZZZ4G00GN099857
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-May-19
Place of Accident : Blk 54 Teban Garden Open Car-Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLF 6083 Y

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor headlight washer	S/N	\$ 480.00	\$ 480.00
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise front crash management components Reinstall		\$ 2,800.00	\$ 750.00
3	To respray front bumper and rhs front fender.		\$ 2,000.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 5,472.00</u>	<u>\$ 2,522.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLF 6083 Y**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER COVER	\$ 2,443.00	\$ 1,954.40
2	FRONT BUMPER GRILLE - CENTER	\$ 598.00	
3	FRONT BUMPER LOCKING CLIP	\$ 65.00	
4	FRONT BUMPER LOWER CHROME TRIM	\$ 276.00	
5	FRONT BUMPER FIXING PARTS	\$ 45.00	
6	FRONT BUMPER CLOSING ELEMENT - CENTER	\$ 199.00	
7	FRONT BUMPER SPOILER	\$ 227.00	
8	AIR GRILLE - RH	\$ 319.00	
9	AIR GRILLE COVER - RH	\$ 46.00	
10	FRONT WHEEL SPOILER - RH	\$ 242.00	
11	HEADLIGHT WASHER COVER - LH / RH	\$ 104.00	
12	FOAM FILLER PIECE	\$ 215.00	
13	FRONT REINFORCEMENT	\$ 754.00	
14	FRONT BUMPER GUIDE PIECE - RH	\$ 34.00	
15	FRONT BUMPER SENSOR	1 \$ 231.00	
16	SENSOR SEAL RING	\$ 5.00	\$ 3.84
17	FRONT FENDER - RH	\$ 1,269.00	
18	FRONT FENDER ATTACHMENT PARTS	\$ 92.00	
19	FRONT FENDER STONE GUARD FILE - RH	\$ 110.00	\$ 88.00
20	FRONT FENDER BRACE - RH	\$ 75.00	
SUB - TOTAL SPARE PARTS		\$ 7,349.00	\$ 2,046.24

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 6083 Y

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 2,046.24
21	FRONT WHEEL HOUSING LINER - RH	\$	256.00	
22	FRONT WHEEL HOUSING LINER ATTACHMENT	\$	66.00	
23	STONE CHIP GUARD - RH	\$	66.00	
24	STONE CHIP GUARD ADHESIVE TAPE	\$	50.00	
25	HEADLIGHT MOUNTING - RH	\$	107.00	
26	HEADLIGHT - RH	\$	8,607.00	\$ 6,885.60
27	LIFT CYLINDER - RH	\$	216.00	
28	SUNDRIES	\$	300.00	
TOTAL SPARE PARTS		:	\$ 17,017.00	\$ 8,931.84
TOTAL LABOUR CHARGES			\$ 5,472.00	\$ 2,522.00
GRAND TOTAL			\$ 22,489.00	\$ 11,453.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLF 6083 Y

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0718/2019/KK

23 Aug 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

1

total pages

RE: INSURANCE CLAIM FOR SLF 6083 Y, Audi A6 1.8 TFSI S TRONIC.

With reference to the above-mentioned vehicle, no. **SLF 6083 Y**, claimant, **Mr. Yang Kam Seng**, please find the related document per attached.

1. A copy of the Original invoice no. 85014153 – S\$12,255.61.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLF 6083 Y

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6386 2323
24-hour Breakdown Service 9628 1233
Email: customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 1 14:59

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014153 Date: 22/08/2019 Order: SLF6083Y Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLF6083Y (V 28492) Regn Date: 31/08/2016 Mileage: 38320 WIP No.: 55276

Model: A6 1.8 TFSI S tronic 4GC06G (N Chassis: WAUZZZ4G0GN099857 Engine: CYG 010339 Dept: U

You have been assisted by :- UB-Kelvin Khoo (138)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHTS,HORNS,FOG LAMPS, OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT.REORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	750.00	1.00	750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A4G0941774J	HEADLIGHT	Less 020%	1.00	8607.00
X	A4G0807065APGRU	COVER(LAST)	Less 020%	1.00	2443.00
X	ALT0919133C 704	WASHER	Less 020%	4.00	1.20
X	A4G0890906	FOIL	Less 020%	1.00	110.00

Parts 8,931.84
Labour 0.00
Sublet 2,522.00
Menus 0.00
Lubricant 0.00



22/8

Sub-Total 11,453.84
7% GST 801.77
Grand Total 12,255.61

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLF 6083 Y

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0718/2019/KK
14 June 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 1.8 TFSI S TRONIC
Vehicle Chassis No. : WAUZZZ4G0GN099857
Vehicle Regn No. : SLF 6083 Y
Vehicle Mileage : 38320 KM
Vehicle Owner : Mr. Yang Kam Seng
Certificate No : 2100481148-02
Own Damage Excess : Waived
Accident Date : 30/5/2019
Place : Blk 54 Teban Garden Open Carpark
Repair Cost : \$ 12,255.61
WIP No. : 55276
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 12.45pm
Date : 14/6/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Jun 2019		06 Jun 2019 09:52 Edit Adj Rpt	S\$11,453.84 Edit Estimates	S\$11,453.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	YANG KAM SENG, ID: S7708476B, Tel: +6594508338, Email: AYANGKS@GMAIL.COM								
Vehicle Reg. No.:	SLF6083Y	Date of Loss:	30/05/2019 10:00 - :59 [32 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 5113736439SG	Policy/Cover Note No.:	2100481148-02 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Nadaraja, Deeban] Deeban@nadaraja.nadaraja@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 17/06/2019]								
Driver/Custodian:	YANG KAM SENG (42 / Male), NRIC: S7708476B, Tel: +6594508338 Email: AYANGKS@GMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (07/06/2019): Alert - Adj Mandate Approved (S\$15821.00) - SLF6083Y - Claim Handler: Nadaraja, ... - AIG_SG (06/06/2019): SLF6083Y / OD / 30/05/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLF6083Y (5113736439SG)
OD
May 30 2019 10:35AM
[YANG KAM SENG]
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer
Video							1 per page
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print		
1	31/05/19 17:11	Video - Accident (Linked Accident Report Documents)		1 Load MP4			
2	31/05/19 17:12	Video - Accident (Linked Accident Report Documents)		2 Load MP4			
3	31/05/19 17:13	Video - Accident (Linked Accident Report Documents)		3 Load MP4			
Assessment Reports							1 per page
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	06/06/19 13:50	Adjuster Immediate Advice		1 Load HTM			
Photos/Images							3 per page
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	06/06/19 11:43	General View		1 Load JPG			
2	06/06/19 11:43	General View		2 Load JPG			
3	06/06/19 11:43	General View		3 Load JPG			
4	06/06/19 11:43	General View		4 Load JPG			
5	06/06/19 11:43	General View		5 Load JPG			
6	06/06/19 11:43	General View		6 Load JPG			
7	06/06/19 11:43	General View		7 Load JPG			
8	06/06/19 11:43	General View		8 Load JPG			
9	06/06/19 11:43	General View		9 Load JPG			
10	06/06/19 11:43	General View		10 Load JPG			
11	06/06/19 11:43	General View		11 Load JPG			
12	06/06/19 11:43	General View		12 Load JPG			
13	06/06/19 11:43	General View		13 Load JPG			
14	06/06/19 11:43	General View		14 Load JPG			
15	06/06/19 11:43	General View		15 Load JPG			
16	06/06/19 11:43	General View		16 Load JPG			
17	06/06/19 11:43	General View		17 Load JPG			
18	16/08/19 11:51	Reinspection Photo		18 Load JPG			
19	16/08/19 11:51	Reinspection Photo		19 Load JPG			
20	16/08/19 11:51	Reinspection Photo		20 Load JPG			
21	16/08/19 11:51	Reinspection Photo		21 Load JPG			
22	16/08/19 11:51	Reinspection Photo		22 Load JPG			
Documentation							1 per page
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	06/06/19 11:41	SLF 6083Y GIA.pdf		1 Load PDF			
2	06/06/19 11:41	POLICE REPORT.pdf		2 Load PDF			
3	06/06/19 11:41	CI & DRIVING.pdf		3 Load PDF			
4	06/06/19 11:45	ESTIMATE.pdf		4 Load PDF			
5	16/08/19 11:51	ESTIMATE MARKED.pdf		5 Load PDF			
6	25/09/19 08:50	WORKSHOP INVOICE		6 Load PDF			
7	25/09/19 08:50	DISCHARGE VOUCHER		7 Load PDF			

Linked Accident Report Documents

View Use Viewer

Video				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	31/05/19 17:11	Video - Accident THIRD PARTY MOVE IN CAR PARK LOTS	 Load MP4		
2	31/05/19 17:12	Video - Accident THIRD PARTY MOVE OUT AND HIT INSURED CAR	 Load MP4		
3	31/05/19 17:13	Video - Accident AFTER ACCIDENT HAPPEN THIRD PARTY JUST TAKE ALOOK INSURED CAR AND MOVE OFF	 Load MP4		
Assessment Reports				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	31/05/19 17:14	Accident Statement	 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	31/05/19 17:05	Police Report	 Load JPG	☒	
2	31/05/19 17:05	Police Report	 Load JPG	☒	
3	31/05/19 17:05	Police Report	 Load JPG	☒	
4	31/05/19 17:05	Accident Photo	 Load JPG	☒	
5	31/05/19 17:05	Accident Photo	 Load JPG	☒	
6	31/05/19 17:05	Accident Photo	 Load JPG	☒	
7	31/05/19 17:05	Accident Photo	 Load JPG	☒	
8	31/05/19 17:05	Accident Photo	 Load JPG	☒	
9	31/05/19 17:05	Accident Photo	 Load JPG	☒	
10	31/05/19 17:05	Accident Photo	 Load JPG	☒	
11	31/05/19 17:05	Accident Photo	 Load JPG	☒	
12	31/05/19 17:05	Accident Photo	 Load JPG	☒	
13	31/05/19 17:05	Accident Photo	 Load JPG	☒	
14	31/05/19 17:05	Accident Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	31/05/19 17:10	Sketch Plan	 Load JPG	☒	
2	31/05/19 17:10	Sketch Plan #2	 Load JPG	☒	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☒ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19009933/ESD3N2

Date: 25/09/2019

REFERENCE

Insured/Claimant:	YANG KAM SENG	Policy No:	2100481148-02	
Date of Loss:	30/05/2019	Nature of Claim:	OD	Claim No: 5113736439SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF6083Y	Engine No:	CYG010339
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)	Chassis No:	WAUZZZ4G0GN099857
Reg. Date:	31/08/2016 (Man. Year: 2015)	Odometer:	38031 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	17,017.00	8,931.84	8,085.16	47.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,472.00	2,522.00	2,950.00	53.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	22,489.00	11,453.84	11,035.16	49.07
+ GST 7.00/7.00% (\$\$)	1,574.23	801.77	772.46	49.07
Nett Amount (\$\$)	24,063.23	12,255.61	11,807.62	49.07

INSPECTION

Date of Assignment:	06/06/2019	
Date Inspected:	04/06/2019	Inspected At: 281 Alexandra Road Repairer: Premium Automobiles Pte Ltd
		55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER COVER	Cut	2,443.00 FS	*1,954.40 FS
2	1	*FRONT BUMPER GRILLE-CENTER	Not Necessary	598.00 FS	*- FS
3	1	*FRONT BUMPER LOCKING CLIP	Not Necessary	65.00 FS	*- FS
4	1	*FRONT BUMPER LOWER CHROME TRIM	Not Necessary	276.00 FS	*- FS
5	1	*FRONT BUMPER FIXING PARTS	Not Necessary	45.00 FS	*- FS
6	1	*FRONT BUMPER CLOSING ELEMENT-CENTER	Not Necessary	199.00 FS	*- FS
7	1	*FRONT BUMPER SPOILER	Not Necessary	227.00 FS	*- FS
8	1	*AIR GRILLE-RH	Not Necessary	319.00 FS	*- FS
9	1	*AIR GRILLE COVER-RH	Not Necessary	46.00 FS	*- FS
10	1	*FRONT WHEEL SPOILER-RH	Not Necessary	242.00 FS	*- FS
11	2	*HEADLIGHT WASHER COVER-LH/RH	Not Necessary	104.00 FS	*- FS
12	1	*FOAM FILLER PIECE	Not Necessary	215.00 FS	*- FS
13	1	*FRONT REINFORCEMENT	Not Necessary	754.00 FS	*- FS
14	1	*FRONT BUMPER GUIDE PIECE-RH	Not Necessary	34.00 FS	*- FS
15	1	*FRONT BUMPER SENSOR	Not Necessary	231.00 FS	*- FS
16	1	*SENSOR SEAL RING	Necessary	5.00 FS	*3.84 FS
17	1	*FRONT FENDER-RH	Repair	1,269.00 FS	*- FS
18	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	92.00 FS	*- FS
19	1	*FRONT FENDER STONE GUARD FILE-RH	Necessary	110.00 FS	*88.00 FS
20	1	*FRONT FENDER BRACE-RH	Not Necessary	75.00 FS	*- FS
21	1	*FRONT WHEEL HOUSING LINER-RH	Not Necessary	256.00 FS	*- FS
22	1	*FRONT WHEEL HOUSING LINER ATTACHMENT	Not Necessary	66.00 FS	*- FS
23	1	*STONE CHIP GUARD-RH	Not Necessary	66.00 FS	*- FS
24	1	*STONE CHIP GUARD ADHESIVE TAPE	Not Necessary	50.00 FS	*- FS
25	1	*HEADLIGHT MOUNTING-RH	Not Necessary	107.00 FS	*- FS
26	1	*HEADLIGHT-RH	Cut	8,607.00 FS	*6,885.60 FS
27	1	*LIFT CYLINDER-RH	Not Necessary	216.00 FS	*- FS
28	1	*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 17,017.00 8,931.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,800.00	750.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,472.00	2,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >