


Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 11:48

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014511 Date : 27/11/2019 Order : SMD1861A Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SMD1861A (V 38378) Regn Date: 06/08/2018 Mileage: 22822 WIP No.: 54645

Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV, Chassis: WAUZZZF4XJA176588 Engine: CVK 062569 Dept: U

You have been assisted by :- UB-Kelvin Khoo (138)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1600.00	1.00	-1,600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	280.00	1.00	280.00
S	BODYWORK	M: TO REMOVE FRONT FITTINGS. TO DISMANTLE AND RENEW FRONT BUMPER AND LHS FRONT FENDER. REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY PAINT ON FRONT BUMPER AND LHS FRONT FENDER	1100.00	1.00	1,100.00
S	BODYWORK	M: TO REMOVE REAR FITTINGS, REAR BUMPER, REAR LID. CUT OUT AND REWELD RHS REAR FENDER AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY RHS REAR FENDER, REAR DOOR AND DOOR HANDLE. TO CARRY OUT STONE CHIP PRIMER, JOINT SEALER WORK AND STONE CHIP TREATMENT	1200.00	1.00	1,200.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8W0821105A	FENDER Less 020%	1.00	699.50	559.60
X	A8W0807065D GRU	COVER Less 020%	1.00	1999.00	1,599.20
X	A8W0821111	PLATE Less 020%	1.00	29.70	23.76
X	AN 0161857	POP-RIVET Less 020%	12.00	3.00	28.80

Parts 2,211.36
Labour 0.00
Sublet 4,772.00
Menus 0.00
Lubricant 0.00

Sub-Total 5,383.36

7% GST 376.84

Grand Total 5,760.20



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SMD 1861 A

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0681/2019/KK
28 June 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 2.0 TFSI
Vehicle Chassis No. : WAUZZZF4XJ4176588
Vehicle Regn No. : SMD 1861 A
Vehicle Mileage : 9582 KM
Vehicle Owner : Ms. Zhai Shuai
Certificate No : 1800087844
Own Damage Excess : \$1712.00 (Incl. 7% GST)
Accident Date : 23/5/2019
Place : 7 Sin Ming Walk Basement Car-Park
Repair Cost : \$ 5,760.20
WIP No. : 54645
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : _____
Time : 9.30a
m
Date : 2019.07.02