

(08/11/13) wel

ASS. REC.

REF:

LPC/

Date

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

N/S	O/S

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/7/19 1st \$201
 4/5 \$8200 covered under Alu.
 (Red \$15310.20/652)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

FASTECT AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883
VEHICLE NO: SKK 3007Z

not Authorised
5dy 2/5 @ 8200
6/6/19
the pre. Mr. My

QTY	PARTICULAR	
1 PCS	BOOTLID	1582.00
1 PCS	BOOTLID REAR LOGO	57.00
1 PCS	BOOTLID '523' EMBLEM	57.00
1 PCS	BOOTLID WEATHERSTRIP	297.66
1 PCS	BOOTLID INNER LOCK	
2 PCS	BOOTLID REFLECTORS @ \$420.00	
1 PCS	BOOTLID INNER TRIM	
1 SET	BOOTLID INNER TRIM CLIPS	
2 PCS	TAILLAMPS @ \$750.00	590
2 PCS	TAILLAMP HOUSING PANELS @ \$415.00	
1 PCS	REAR BUMPER	1521
1 PCS	REAR BUMPER INNER PAD	268.00
1 PCS	REAR BUMPER TOW COVER	
4 PCS	REAR BUMPER PDC SENSORS @ \$313.00	215 x 2 = 430
1 PCS	REAR BUMPER PDC SENSOR WIRE	
1 PCS	REAR BUMPER TOP GUIDE	
1 PCS	REAR BUMPER REINFORCEMENT	
2 PCS	REAR BUMPER REINFORCEMENT STAY BRACKETS @ \$150.00	
1 PCS	REAR BUMPER TOP RETAINER	
2 PCS	REAR BUMPER SIDE HOLDERS @ \$95.00	
1 SET	REAR BUMPER CLIPS	
2 PCS	REAR BUMPER REFLECTORS @ \$95.00	
1 PCS	REAR END PANEL	
1 PCS	REAR END PANEL TOP GARNISH	
2 PCS	REAR FENDER INNER TRIMS @ \$380.00	
2 PCS	REAR FENDERS @ \$1650.00	
1 PCS	REAR WINDSCREEN MOULDING	
1 PCS	REAR EXHAUST	
3 PCS	REAR EXHAUST MOUNTINS @ \$80.00	
1 PCS	REAR BUMPER LOWER TRAY	
2 PCS	FRONT HEADREST RESTRAINTS @ \$250.00	235 x 2 = 470

no/sent	\$1,866.00	
rer	\$86.60	
rer	\$58.00	
Tw	\$275.00	
Tw / shield	\$299.08	
scr/cr	\$840.00	
11	\$366.00	X
11	\$50.00	X
olscr	\$1,500.00	1/2
11	\$830.00	X
no/2e	\$1,658.00	
cr	\$423.65	
11	\$36.00	X
shield	\$1,252.00	2/5
11	\$315.00	X
cr	\$199.02	
3rd	\$640.93	
ns	\$300.00	X
6/29	\$211.00	
cr	\$190.00	
rer	\$60.00	
11	\$190.00	X
no/sent	\$1,018.57	
11	\$211.35	X
11	\$760.00	X
11	\$3,300.00	X
11	\$185.00	X
11	\$1,550.00	X
11	\$240.00	X
11	\$269.00	X
Actual	\$500.00	
	\$19,680.20	

LABOUR CHARGES:

TO CHECK WIRING	\$80.00	30
TO DISMANTLE & REPLACING PDC SENSOR	\$80.00	50
TO TRANSFER BOOTLID MECHANISM	\$100.00	80
TO DISMANTLE & REFIX REAR EXHAUST	11 \$120.00	X
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR WINDSCREEN	11 \$150.00	X
TO SPRAY RUST PROOFING	\$100.00	80
TO DISMANTLE & REPLACING FRONT HEADREST	\$80.00	
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,500.00	600
TO PUTTY & SPRAY PAINTING	\$1,500.00	1000
TOTAL	\$23,510.20	

8698.60
52
8263.67
10263.67

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	4217J

Vehicle Details

Vehicle No.:	SKK3007Z
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jun 2019
Vehicle Make:	B.M.W.
Vehicle Model:	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV

Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	02927761N52B25AF
Chassis No.:	WBAFP32010C866449
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$49,093.00
Original Registration Date:	11 Jul 2011
First Registration Date:	11 Jul 2011
Transfer Count:	1
Actual ARF Paid:	\$49,093.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jul 2021
PARF Rebate Amount:	\$29,455.00

Intended COE Rebate Details

COE Expiry Date:	10 Jul 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$68,501.00
COE Rebate Amount:	\$14,344.00
Total Rebate Amount:	\$43,799.00

The information contained herein is correct as at 06 Jun 2019

OK

Shu Pei (LKKAUTO)


From: ONG LI LI <lilong@lonpac.com>
Sent: Monday, 10 June 2019 11:09 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Admin A; Jia Le (LKK Auto)
Subject: RE: Direct Settlement - Accident Involving XD8898T (OI : LPC - 19/19/19/VC05/021868) AND SKK3007Z (TP : LKK REF - CC6/LPC19009977/Udb3) on 29.05.2019 [External General]
Attachments: XD8898T 290519.PDF

Lonpac External - General

Dear Shu Pei

Please see attached for our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Friday, 7 June, 2019 5:03 PM
To: GERALD POH WEE BIN; ONG LI LI
Cc: MT_Claim_SG; Admin A; Jia Le (LKK Auto)
Subject: Direct Settlement - Accident Involving XD8898T (OI : LPC - TBA) AND SKK3007Z (TP : LKK REF - CC6/LPC19009977/Udb3) on 29.05.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SKK 3007Z at M/s Fastech Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:
- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your Insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jia Le and she can be contacted at DID: 6749 5792.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883

Tel No: 67465405 / 67465376 Fax No: 67458520

Tax Reg No: 200006262D

Date : 16.07.2019

Lonpac Insurance BHD
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Attn: Motor Claim Department

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES : SKK 3007Z / XD 8898T ON 29.05.2019

We are the authorized repair workshop for the owner of motor vehicle no: **SKK 3007Z**, which was involved in the captioned accident with your insured vehicle no: **XD 8898T**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$ 8,774.00
2) Loss of Rental	\$ 400.00
3) GIA Search Fee	\$ 2.00
	<u>\$ 9,176.00</u>

We enclosed herewith the following documents to support the claims:

- | | |
|--------------------------|------------------------------------|
| a) Final Repair Invoice | b) Car Rental Invoice / Agreement |
| c) GIA Search Result | d) Letter of Authorisation, etc... |
| e) GIA Report | f) I/C & Driving Licence |
| g) Insurance Certificate | h) Vehicle Registration Log Card |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.
Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)
For Fastech Auto Pte Ltd

TAX INVOICE

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

Lonpac Insurance BHD
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Attn : Motor Claim Department

Tax Invoice : 21146

Date : 16.07.2019
Vehicle No : SKK 3007Z
Make/Model : BMW 523i
Chassis/Eng# :
Accident Date : 29.05.2019
Claim No :
Reference : 0619 -21146
Policy No :

	Amount
To proceed on lump sum repair	SS 8200.00

E. & O. E.	Total : S\$	8200.00
	GST @ 7% : S\$	574.00
	Amount Due : S\$	8774.00


for FASTECH AUTO PTE LTD

All Invoices are subjected to GST

DYNAMIC CAR RENTAL

1 Kaki Bukit Ave 6 #01-46 Autobay

Singapore 417883

Tel No: 6741 7244 / 6746 5405 Fax No: 6745 8520 / 6746 5786

Co. Reg No: 52928467K

To: MOHAMED FAROUK BIN ABDUL LATIFF

Invoice : DCR-2019-06-24

Date : 10.06.2019

Agreement No : 20767

Payment Term : LOD

DESCRIPTION

AMOUNT

Rental charges for vehicle : SLH 7631Z (0619-21146) \$ 400.00

Rental Period from 06.06.2019 to 10.06.2019

E. & O. E.

Total \$ 400.00

LINA PANG

for Dynamic Car Rental

Dynamic Car Rental

1 KAKI BUKIT AVENUE 6, #01-46/48/50 AUTOBAY, SINGAPORE 417883.

TEL: (+65) 6741 7244, 6746 5405 FAX: (+65) 6745 8520, 6746 5786

Co. Reg. No. 52928467K

RENTAL TERMS AND CONDITIONS

No. 20767

Name Mohamed Farouk Bin Abdul Latiff.			REG. No. SLH 76312		MAKE MODEL:									
ADDRESS					DIESEL		PETROL		E	1/4	1/2	3/4	F	
			KM IN		DATE & TIME IN 10.06.2019 @ 10.43am									
			KM OUT		DATE & TIME OUT 06.06.2019 @ 10.15am									
			KM DRIVEN		TIME USED									
NAMED DRIVER														
DRIVING LICENCE NO S1054217J			DATE OF EXPIRY			PLACE OF ISSUE			HOURS		@S\$			
PASSPORT NO			DATE OF ISSUE			PLACE OF ISSUE			4 DAYS		@S\$ 100.00		\$ 400.00	
ADD NAMED DRIVER														
DRIVING LICENCE NO			DATE OF EXPIRY			PLACE OF ISSUE			WEEKS		@S\$			
PASSPORT NO			DATE OF ISSUE			PLACE OF ISSUE			MONTHS		@S\$			
BY INITIALLING, RENTER AGREES TO PAY ADD FEE FOR COLLISION DAMAGES WAIVER (C.D.W.)										SUB-TOTAL		\$ 400.00		
IMPORTANT NOTES: This vehicle is licensed to carry 04 passengers only. No refund will be given for vehicle returns early. No refund will be given for period left in vehicle. Hirer is liable to pay first \$4000 under section I & II in any accident plus loss of earnings while damaged vehicle is under repair. Hirer is liable to pay all parking fee and traffic summonses. Vehicle return during office hour only. No Service on Public Holiday and Sunday. EXCESS: *Sec I - Used in S'pore Only :SGD2000 *Sec II - Used in S'pore Only :SGD2000 *Sec I - Used Outside S'pore Only :SGD4000 *Sec II - Used Outside S'pore Only :SGD4000 Widescreen Excess in S'pore: SGD100 Widescreen Excess Outside S'pore: SGD200 ADDITIONAL CONDITIONS: * Geographical areas: Singapore & West Malaysia. * Driver must be: a) 18 years old and above; b) holding a valid relevant class of driving license. * Additional Own Damage Excess of \$51,000 is applicable for any named/unnamed drivers who: a) age 22 to 25 years old; b) age 66 to 70 years old; c) with driving experience of 1 year to less than 2 years in Singapore on the relevant classes of driving license. * Additional All Claims excess of \$52,000 is applicable for any named/unnamed drivers who: a) is 18 years old to 25 years old and/or b) is 71 years old and above and/or c) with driving experience of less than 1 year on the relevant classes of driving license. * Upon returning the replacement vehicle, you must ensure that all expensive and important items to be removed away from this replacement vehicle. Weir will not be responsible for any reporting of such losses. * Hirer is liable to pay first \$4000 under section I & II in any accident plus loss of earnings while damage vehicle is under repair. Hirer is responsible for Additional \$4,000.00 Excess to the THIRD PARTY DAMAGE / INJURY claims.														
X PER DAY PER WEEK PER MONTH \$ \$ \$ BY INITIALLING, RENTER AGREES TO PAY ADD FEE FOR PERSONAL ACCIDENT INSURANCE (P.A.I.) X PER DAY PER WEEK PER MONTH \$ \$ \$ PREPAYMENT TOTAL CHARGE CHECK DEPOSIT CASH RECEIPT NO. NETT CHARGE AMOUNT DUE / REFUND														

I HAVE READ THE TERMS AND CONDITIONS ON BOTH SIDES OF THIS RENTAL AGREEMENT AND AGREE THEREOF

SIGNED BY THE PARTIES HERETO ON THE

DAY OF

X

DYNAMIC CAR RENTAL

X

RENTER'S/DRIVER'S SIGNATURE

Third Party Insurer Enquiry

Our Ref No: GR-19-085909

Date of Request: 30/05/2019

Your Ref No:

Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 30/05/2019

Enquiry By: Tang Kok Wee, Allan

TP Vehicle No.: XD8898T

Accident Date: 29/05/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
XD8898T	Lonpac Insurance Bhd	03/03/2019-02/03/2020	+65 62507388

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

TAX INVOICE

Our Ref No: GR-19-085909

Date of Request: 30/05/2019

Your Ref No:

Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 30/05/2019
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. XD8898T
Accident Date 29/05/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

DATE : 06.06.2019

TO : Lompac Insurance Bhd

RE : ACCIDENT INVOLVING VEHICLE NO. SKK 3007Z / XD 8898 T

ALONG Telok Kurau Lorong K Twds Siglap Park Connector

ON 29.05.2019

I/We, Mohamed Farouk Bin Abdul Latiff

of (NRIC No./ROC No.) S 1054217J

of Blk 161 Bedok South Avenue 3, # 01-509 Singapore 460161

owner of vehicle no. SKK 3007Z in consideration of M/s FASTECH AUTO

PTE LTD repairing my/our vehicle SKK 3007Z at my/our instruction and hereby

authorise M/s FASTECH AUTO PTE LTD to demand claim settlement whatever

amount settled/payable by the Insurance Company and/or third party or to commence legal proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use,

etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and

all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the above-mentioned claim cost

which may arisen therewith.

Signature of Owner :

Name of Owner :



Jia Le (LKK Auto)


From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 26 December 2019 2:55 PM
To: Jia Le (LKK Auto)
Cc: MT_Claim_SG
Subject: RE: Direct Settlement - Accident Involving XD8898T (OI : LPC - 19/19/19/VC05/021868) AND SKK3007Z (TP : LKK REF - CC6/LPC19009977/Udb3) on 29.05.2019 [External General]

Lonpac External - General

Dear Jia Le

Ok, please proceed with your recommendation.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Jia Le (LKK Auto) [mailto:JiaLe@lkkauto.com]
Sent: Monday, 23 December 2019 9:41 AM
To: ONG LI LI
Cc: MT_Claim_SG
Subject: RE: Direct Settlement - Accident Involving XD8898T (OI : LPC - 19/19/19/VC05/021868) AND SKK3007Z (TP : LKK REF - CC6/LPC19009977/Udb3) on 29.05.2019 [External General]

Dear Li Li,

We have spoke to insured driver and he mentioned that he did not hit onto Third Party vehicle.

Third Party did not have the video footage to prove that our insured had collided onto his vehicle.

In view of the above, we are intending to reject Third Party claim.

Kindly let us have your approval/instruction.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]

Sent: Thursday, 3 October 2019 4:14 PM

To: Jia Le (LKK Auto)

Cc: MT_Claim_SG

Subject: RE: Direct Settlement - Accident Involving XD8898T (OI : LPC - 19/19/19/VC05/021868) AND SKK3007Z (TP : LKK REF - CC6/LPC19009977/Udb3) on 29.05.2019 [External General]

Lonpac External - General

Dear Jia Le

Please engage our Insured before proceeding further.

Regards,


Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse

Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Jia Le (LKK Auto) [<mailto:JiaLe@lkkauto.com>]

Sent: Thursday, 3 October 2019 4:08 PM

To: ONG LI LI

Cc: MT_Claim_SG

Subject: RE: Direct Settlement - Accident Involving XD8898T (OI : LPC - 19/19/19/VC05/021868) AND SKK3007Z (TP : LKK REF - CC6/LPC19009977/Udb3) on 29.05.2019 [External General]

Dear Li Li,

Insured reported there was no collision with TP.

We have checked with Third Party and there was no video footage available.

Insured being a long and heavy lorry, driver wouldn't feel anything upon impact.

Kindly let us have your instruction if we may proceed to prepare 50% liability due to conflicting version.

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]

Sent: Monday, 10 June 2019 11:09 AM

To: Shu Pei (LKKAuto)

Cc: MT_Claim_SG; Admin A; Jia Le (LKK Auto)

Subject: RE: Direct Settlement - Accident Involving XD8898T (OI : LPC - 19/19/19/VC05/021868) AND SKK3007Z (TP : LKK REF - CC6/LPC19009977/Udb3) on 29.05.2019 [External General]

Lonpac External - General

Dear Shu Pei

Please see attached for our Insured's GIA report.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]

Sent: Friday, 7 June, 2019 5:03 PM

To: GERALD POH WEE BIN; ONG LI LI

Cc: MT_Claim_SG; Admin A; Jia Le (LKK Auto)

Subject: Direct Settlement - Accident Involving XD8898T (OI : LPC - TBA) AND SKK3007Z (TP : LKK REF - CC6/LPC19009977/Udb3) on 29.05.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SKK 3007Z at M/s Fastech Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jia Le and she can be contacted at DID: 6749 5792.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Jia Le (LKK Auto)

From: Jia Le (LKK Auto)
Sent: Thursday, 26 December 2019 3:37 PM
To: 'jason@fastechauto.com.sg'
Cc: Admin A
Subject: RE: Your Ref: SKK3007Z *Our Ref: CC6/LPC19009977/Udb3 [ACCIDENT INVOLVING XD8898T & SKK3007Z ON 29/05/2019]

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING XD 8898T & SKK 3007Z ON 29/05/2019

We refer to the above matter.

There is no concrete evidences to prove our insured had collided onto your client's vehicle.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's claim.

Thank you.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jia Le (LKK Auto)
Sent: Tuesday, 11 June 2019 2:49 PM
To: jason@fastechauto.com.sg
Cc: Admin A
Subject: Your Ref: SKK3007Z *Our Ref: CC6/LPC19009977/Udb3 [ACCIDENT INVOLVING XD8898T & SKK3007Z ON 29/05/2019]

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING XD8898T AND SKK3007Z ON 29/05/2019

We refer to the above matter.

Please be informed that liability is unclear for this matter. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage/witness statement/scene photos(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Carlton Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC19009977/Uda3q2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 07-01-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 8898T	Veh. Inspected	SKK 3007Z
Policy No.	Z19VC05001867	Coverage (\$)	0.00
Claim No.	19/19/19/VC05/021868	Excess (\$)	0.00
Assign From		Assign Date	06/06/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 523I (A)	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAFP32010C866449	Colour	GREY
Odometer	111741	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R18	GOODYEAR	6 mm
L/H Front Tyre	245/45 R18	GOODYEAR	6 mm
R/H Rear Tyre	245/45 R18	GOODYEAR	6 mm
L/H Rear Tyre	245/45 R18	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/05/2019	Inspection Date	06/06/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 3007Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	DENTED / BENT	1,866.00	1,562.00
1	BOOTLID REAR LOGO	NECESSARY	86.60	57.00
1	BOOTLID '523I' EMBLEM	NECESSARY	58.00	57.00
1	BOOTLID WEATHERSTRIP	TWISTED	275.00	275.00
1	BOOTLID INNER LOCK	TWISTED / SHORTED	299.08	299.08
2	BOOTLID REFLECTORS @\$420.00	SCRATCHED / CRACKED	840.00	840.00
1	BOOTLID INNER TRIM	NOT NECESSARY	366.00	-
1	SET BOOTLID INNER TRIM CLIPS	NOT NECESSARY	50.00	-
2	TAILLAMPS @\$750.00	O/S SCRATCHED	1,500.00	590.00
2	TAILLAMP HOUSING PANELS @\$415.00	NOT NECESSARY	830.00	-
1	REAR BUMPER	DENTED / DEFORMED	1,658.00	1,531.00
1	REAR BUMPER INNER PAD	CRACKED	423.65	268.00
1	REAR BUMPER TOW COVER	NOT NECESSARY	36.00	-
4	REAR BUMPER PDC SENSORS @\$313.00	SHORTED (2 PCS ONLY)	1,252.00	430.00
1	REAR BUMPER PDC SENSOR WIRE	NOT NECESSARY	315.00	-
1	REAR BUMPER TOP GUIDE	CRACKED	199.02	199.02
1	REAR BUMPER REINFORCEMENT	BENT	640.93	640.93
2	REAR BUMPER REINFORCEMENT STAY BRACKETS @\$150.00	NO SUCH PARTS	300.00	-
1	REAR BUMPER TOP RETAINER	CRACKED	211.00	211.00
2	REAR BUMPER SIDE HOLDERS @\$95.00	CRACKED	190.00	190.00
1	SET REAR BUMPER CLIPS	NECESSARY	60.00	60.00
2	REAR BUMPER REFLECTORS @\$95.00	NOT NECESSARY	190.00	-
1	REAR END PANEL	DENTED / BENT	1,018.57	1,018.57
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	211.35	-
2	REAR FENDER INNER TRIMS @\$380.00	NOT NECESSARY	760.00	-
2	REAR FENDERS @\$1650.00	NOT NECESSARY	3,300.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	185.00	-

Report Ref No. CC6/LPC19009977/Uda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST	NOT NECESSARY	1,550.00	-
3	REAR EXHAUST MOUNTINGS @\$80.00	NOT NECESSARY	240.00	-
1	REAR BUMPER LOWER TRAY	NOT NECESSARY	269.00	-
2	FRONT HEADREST RESTRAINTS @\$250.00	ACTIVATED	500.00	470.00
	LESS 5% DISCOUNT		-	-434.93
			19,680.20	8,263.67
	LABOUR			
	TO CHECK WIRING		80.00	30.00
	TO DISMANTLE & REPLACING PDC SENSOR		80.00	50.00
	TO TRANSFER BOOTLID MECHANISM		100.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST	NOT NECESSARY	120.00	-
	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY		120.00	80.00
	TO DISMANTLE & REFIX REAR WINDSCREEN	NOT NECESSARY	150.00	-
	TO SPRAY RUST PROOFING		100.00	80.00
	TO DISMANTLE & REPLACING FRONT HEADREST		80.00	80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS		1,500.00	600.00
	TO PUTTY & SPRAY PAINTING		1,500.00	1,000.00
			3,830.00	2,000.00
	GRAND TOTAL		23,510.20	10,263.67
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,200.00

Report Ref No. CC6/LPC19009977/Uda3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.