



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3876 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 1 / 3

ESTIMATE

Date : 31/05/2019
To : CHINA TAIPING INSURANCE
(SINGAPORE) PTE. LTD.
Attn. :
Office / Mobile :
Email Address :
From : GOLDBELL ENGINEERING PTE LTD
Attn. : ENKWOKLONG
Office / Mobile : +65 6864 0637
Email / Fax No. : EngKwokLong@goldbell.com.sg

Reg No : YQ744B
Model : FEB21ER4SDEN CBU MT
Chassis No : FEB21EA30085
Engine No : 4P10D29310
Quotation No. : 88491
Ref. No. : GBE/SVC/SALES-4881/190531
D.O.A. : 21/05/2019
Policy No. : DMCVSN191681900
Claim Type : OD CLAIM - CHINA TAIPING
Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1	ML274721	CAP, SIDE MIRROR COVER LH FLAT <i>Smis</i>	1	28.83	-10	25.95	25.95
2	MK580752	MIRROR, UNDER VIEW <i>/</i>	1	55.22	-10	49.70	49.70
3	MC978995	GARNISH, FR PANEL <i>?</i>	1	373.08	-10	335.77	335.77
<i>mk707624</i>	ML230271	PANEL ASSY, FR <i>/ Pnc.</i>	1	2,367.22	-10	2,130.50	2,130.50
5	MK707820	RAIL ASSY, WINDSHIELD <i>?</i>	1	1,439.87	-10	1,295.88	1,295.88
6	MC978783	PANEL, CAB FR CORNER -LH <i>/ BR.</i>	1	492.41	-10	443.17	443.17
7	MC975899	GRILLE, FRONT (NATURALWH <i>/ Cut</i>	1	719.33	-10	647.40	647.40
8	MK546617	MARK, FUSO <i>/</i>	1	150.59	-10	135.53	135.53
9	MK546616	MARK, 3-DIA <i>/</i>	1	80.22	-10	72.20	72.20
10	MK675497	EMBLEM, CANTER <i>/</i>	1	76.22	-10	68.60	68.60
11	MX915952	LAMP ASSY, TURN SIGNAL, FR -LH <i>/ CRA</i>	1	197.31	-10	177.58	177.58
12	MK583357	AIR INTAKE BOX, HEATER UNIT <i>/ CRA (photo)</i>	1	845.66	-10	761.09	761.09
13	ML298316	HEATER ASSY (Superseded from MK583365) <i>/</i>	1	2,349.20	-10	2,114.28	2,114.28
14	MK654863	HOSE, HEATER WATER <i>/</i>	1	22.54	-10	20.29	20.29
15	MK450980	HOSE, HEATER WATER <i>/</i>	1	20.42	-10	18.38	18.38
16	MH021330	CLAMP <i>/</i>	2	7.32	-10	6.59	13.18
17	MK590330	RESERVOIR, P/S OIL <i>/</i>	1	541.44	-10	487.30	487.30
18	QZ010750	C FUSO LLC 4L <i>/</i>	1	62.00	-10	55.80	55.80

PARTS TOTAL : 8,852.60

SPECIAL NETT ITEMS

1 POWER STEERING FLUID */* 1 60.00

PARTS TOTAL: 60.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

biSAFE
STAR

AIA
SAC
Certificate No: AIA/090101242

AIA
UKAS
Certificate No: AIA/090101242



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 2 / 3

ESTIMATE

Date	: 31/05/2019	Reg No	: YQ744B
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER4SDEN CBU MT
Attn.	:	Chassis No	: FEB21EA30085
Office / Mobile	:	Engine No	: 4P10D29310
Email Address	:	Quotation No.	: 88491
		Ref. No.	: GBE/SVC/SALES-4881/190531
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 21/05/2019
Attn.	: ENKWOKLONG	Policy No.	: DMCVSN191681900
Office / Mobile	: +65 6864 0637	Claim Type	: OD CLAIM - CHINA TAIPING
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	600	2400	3000.00
2	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	350	1050	1400.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK		180	250.00
4	SUNDRIES		20	80.00
5	TO REMOVE AND REFIX FRONT WINDSCREEN TO ASSIST REPAIR		180	200.00
6	TO REMOVE AND REFIX FRONT DASHBOARD		600	750.00
7	TO REMOVE AND REFIX AIRCON SYSTEM. TO CHECK FUNCTION		600	750.00
8	AIRCON GAS		50	80.00
9	TOWING FEES		?	100.00

LABOUR TOTAL : 6,610.00

SUB-TOTAL : 15,522.60

GST @ 7% for \$ 15,522.60 1,086.58

GRAND TOTAL (S\$) : 16,609.18

7 Days. Not Authorised.
part by part.
before paint photos.
Guo Qiang - 82880282
Guo Qiang @ 1kk auto. com
Excess \$500 07/6/19.

P: 7556.72
S/N: 6000
L: 5080

Total: 12696.72

biSAFE

AIA SAC

AIA UTA