

ASS. REC. BY:

REF: NS/CT119010001/GVd301

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

Merimen

From (Person):

Elaine chong

of

CTE

Date/Time:

6/6/19 3:27pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YQ 744B

Insured:

at Workshop m/s

GoldBell Engineering

Tel:

of

NO. 10 tuas Ave 18

Policy No:

DMCVSN191681900

Claim No:

SNM1AD202458C01

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

21/05/2019

CA / REV / REP. / REV 24 HRS

7/6/19

H.O.D. Endorsement:

Date/Time:

4:07pm 6/6/19

Person Contacted:

Brian

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate

Insp: 8 tuas ave 18

YQ 744B-X

10/6/19

Revert via merimen

11/6/19

Recd approved \$14,030.60 from Elaine by merimen

11/6/19

Informed Brian c/A ex \$500 by email

21/6/19

Final fig \$12,340.95 confirmed by email (Red 3181.65, 20/6)

ASS. REC. BY: 60

REF: C11

C4612N

ASSIGNMENT

From:

Date:

7/6/2019

Veh No:

YQ 744B

Yr Regn:

15 Apr 2019

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

YQ 744B

Make:

Mitsubishi Canter c.c 2998

at Workshop m/s

Gold Bell

Colour:

white

A/C:

Insured / Std / NI / NA

of

No. 8 Tras Ave 18

Sp. Reading

4850

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

IEB 21 EA 300.85

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

\$500.00

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Brian @ 97557336

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 / 85 R15

R:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$85K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

D.O.I.

07-06-19

Survey held at

w/s

5pm

Des. of Damages

☒ Frt /

Rear /

O/S /

N/S /

U/C /

Rooftop or

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 21 JUN 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

21/6 - typist

Days Of Repair:

7

Resurvey No. of Trip:

1

Survey Fee:

270

Transportation:

S + RS. \$

Photos

Others

TOTAL

270

Report Format:

merimen

Lump Sum / U.C. (\$)

12,340.95

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 May 2019		06 Jun 2019 15:27 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	DIGO BUILDING CONSTRUCTION PTE LTD, Co. Reg. No.: 201714612N		
Vehicle Reg. No.:	YQ744B	Date of Loss:	21/05/2019 19:00 - :59
Claim Type:	OD / SNM19D202458C01	Policy/Cover Note No.:	DMCVSN191681900 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Goldbell Engineering Pte Ltd ((Tuas)) No. 10 Tuas Avenue 18, 638894 Tuas - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/06/2019]		
Driver/Custodian:	AMARAJI SUBRAMANI (25 / Male) , NRIC: G2472950N, Tel: +6583011220 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 11 June 2019 2:25 PM
To: SUR; Brian Eng Kwok Long
Subject: YQ 744B-DOA: 21/5/2019 (CHINA TAIPING OD)

Dear Brian,

As instructed by our client , please proceed to repair the **insured vehicle YQ 744B (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***YQ744B (SNM19D202458C01)**

OD

May 21 2019 7:00PM

[DIGO BUILDING CONSTRUCTION PTE LTD]

Goldbell Engineering Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **11/06/2019 13:49 PM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$14032.60) - YQ744B - Claim Handler: Elaine Cheong

Approved:14032.60.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn: Elaine Cheong Date: 10 Jun 2019

Preliminary Advice

Vehicle No	: YQ744B	Accident Date	: 21/05/2019
Make	: MITSUBISHI CANTER	Policy No.	: DMCVSN191681900
Assignment Date	: 06/06/2019	Excess	: S\$500.00
Date of Inspection	: 7/6/2019	Est. Duration of Repair	: 7
Inspection At	: GOLDBELL ENGINEERING PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,522.60
Revised Amount	:S\$	12,300.95
Check Items (Estimated)	:S\$	1,731.65
Total	:S\$	14,032.60

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	26,608.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,392.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	4612N

Vehicle Details

Vehicle No.:	YQ744B
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jun 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEN (CBU)
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	4P10D29310
Chassis No.:	FEB21EA30085
Maximum Power Output:	-
Open Market Value:	\$35,807.00
Original Registration Date:	15 Apr 2019
First Registration Date:	15 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$1,791.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	14 Apr 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$27,021.00
COE Rebate Amount:	\$26,608.00
Total Rebate Amount:	\$26,608.00

The information contained herein is correct as at 09 Jun 2019

OK



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Co. Reg. No. 200208384E

MZ300/C
E SN
AN0655A
Cov.Type: C

MOTOR COMMERCIAL VEHICLE

CERTIFICATE OF INSURANCE
Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1980
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE No. DMCVSN1916891900 Engine No :4P10D29310
ChaNo:FEB21EA30085

1. Index Mark and Registration Number of Vehicle YQ744B

2. Name of Policy Holder M/S DIGO BUILDING CONSTRUCTION PTE LTD

3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment 15 April 2019 (13:37 Hours) Excess Sect I S\$500.00
EX ON WINDSCREEN S\$100.00

4. Date of Expiry of Insurance 14 April 2020

5. Persons or Classes of Persons entitled to drive*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use:*

- (1) Use in connection with the Policyholder's business.
(2) Use for the carriage of passengers (other than for hire or reward) in connection with the policyholder's business.
(3) Use for social, domestic or pleasure purposes.
The Policy does not cover.
(1) Use for hire or reward or racing, pace-making, reliability trial or speed testing.
(2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

HIRE PURCHASE CO. : DAIMLER FINANCIAL SVCS AFRICA & ASIA PACIFIC

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

ACER INSURANCE AGENCY FOR CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

21 Woodlands Close
#08-44 Primz Bizhub
Singapore 737854

Tel: 6777 8323 Fax: 6776 8323

Issued By:

HO LI HWA IRENE

Authorised Officer

Authorised Signatory


WORK PERMIT
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
DIGO CORPORATION PTE. LTD.

Name
AMARAJI SUBRAMANI

Work Permit No.
O 36530634

Sector
CONSTRUCTION

 K0373036

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number **G2472950N**
Name
AMARAJI SUBRAMANI

Birth Date: 22 Oct 1993
Issue Date: 13 Nov 2015
Valid Till 12/11/2020

 002492946E

SG 50

VISIT PASS
Immigration Regulations

Name
AMARAJI SUBRAMANI

FIN
G2472950N

Date of Birth: 22-10-1993 Sex: M

Nationality
INDIAN

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

Download SGWorkPass App to check status




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class	Vehicle Class	Effective Date
C	Class 2B Motorcycles ≤ 200 CC	13 Nov 2015
C	Class 3 Motor cars ≤ 3000 kg with ≤ 7 passengers, exclusive of the driver; and motor tractors/vehicles ≤ 2500 kg	22 Jan 2018

S / No. 9000277536

G2472950N

 Licence No: G2472950N

NP: 428A

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/05/2019 14:54
Date Of Accident	21/05/2019 19:20
Exact Location Of Accident	ALONG KPE TWDS TPE AFTER OLD TAMPINES RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YQ744B
Insured/Policyholder	
Name Of Registered Owner	DIGO BUILDING CONSTRUCTION PTE LTD
Co Reg No	201714612N
Email Address	VEHICLE@DIGO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-67527477

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER FEB21
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN191681900
Cover Note Number	15/04/19 - 14/04/20

Driver

Name of Driver	AMARAJI SUBRAMANI
NRIC No	G2472950N
Date Of Birth	22/10/1993
Occupation	OUTDOOR
Date Of Driving Pass	22/01/2018
Driving Experience	1 YEAR AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83011220
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address C/O
Postcode
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES
Foreign Vehicle Registration Number JTJ7628 (BUS)
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 21
Passenger 1
NAME: : WORKER
GENDER: : MALE
Passenger 2
NAME: : WORKER
GENDER: : MALE
Passenger 3
NAME: : WORKER
GENDER: : MALE
Passenger 4
NAME: : WORKER
GENDER: : MALE
Passenger 5
NAME: : WORKER
GENDER: : MALE
Passenger 6
NAME: : WORKER
GENDER: : MALE
Passenger 7
NAME: : WORKER
GENDER: : MALE
Passenger 8
NAME: : WORKER
GENDER: : MALE
Passenger 9
NAME: : WORKER
GENDER: : MALE

Passenger 10	NAME: : WORKER GENDER: : MALE
Passenger 11	NAME: : WORKER GENDER: : MALE
Passenger 12	NAME: : WORKER GENDER: : MALE
Passenger 13	NAME: : WORKER GENDER: : MALE
Passenger 14	NAME: : WORKER GENDER: : MALE
Passenger 15	NAME: : WORKER GENDER: : MALE
Passenger 16	NAME: : WORKER GENDER: : MALE
Passenger 17	NAME: : WORKER GENDER: : MALE
Passenger 18	NAME: : WORKER GENDER: : MALE
Passenger 19	NAME: : WORKER GENDER: : MALE
Passenger 20	NAME: : WORKER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MARINE PARADE N.P.C
Police Station Address	ROAD: 300 MARINE PARADE ROAD , POSTCODE: 449296 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to police report attached. *OD CLAIM BY AGENT*

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JTJ7628
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

VEHICLE NO.: YQ 744 B
INSURER : China Taiping
DATE & TIME: 21/5/19 @ 19:20

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

A. Schanely 28/5/19.
Driver's Signature
(If driver is not the policyholder)
Date & Time:

/s/ 28/5/19
Reporting Centre Personnel's Signature
Name: (YS)
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

A=7Q744B
B=3T37628

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report NO: T/20190528/3072

Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

CLAIMANT'S SIGNATURE () Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/EP at other workshop (by Agent)



**SINGAPORE
POLICE FORCE**



T/20190528/2072

1 of 3

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

Report No. T/20190528/2072

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/05/2019 12:41		Vide Report No.:		Station Diary No.: 24	
Informant's Particulars					
Name of Informant: AMARAJI SUBRAMANI			Address: C/O 20 Senoko Drive SINGAPORE 758207		
ID Type / ID No.: FIN NO / G2472950N			Contact No.: Home/Office: Mobile: 83011220		
Nationality: INDIAN			Email:		
Sex: Male	Age: 25	Date of Birth: 22/10/1993	Type of Informant: Driver		
Race: Indian			Language:		Institution / School Name:
Occupation: CONSTRUCTION WORKER			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 21/05/2019 19:20	Type of Location: Straight Road
Location: Along Road 1 KALLANG PAYA LEBAR EXPRESSWAY Along KPE towards TPE, just after Old Tampines Rd exit.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JTJ7628	Bus/Coach/Mi nibus				Slightly Damaged	0
YQ744B	Lorry	MITSUBISHI	CANTER FEB21ER4S DEN (CBU)	White	Slightly Damaged	20

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190528/2072

2 of 3

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

Report No: T/20190528/2072

CONTINUATION OF REPORT

Driver			
Name	AMARAJI SUBRAMANI	ID No.	G2472950N
Related Vehicle	YQ744B (Lorry)	Contact No.	83011220
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B.3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I am the driver of a white in colour Mitsubishi Canter lorry bearing vehicle plate number YQ744B.

On the 21/05/2019 at about 1910hrs, I was driving my vehicle (YQ744B) along the third lane of KPE towards TPE. The vehicle (YQ744B) had 20 passengers inside. There was a Malaysian bus, bearing vehicle plate number JTJ7628, ahead of me. Out of a sudden, the bus (JTJ7628) applied its emergency brakes to which I did as well however my vehicle's (YQ744B) front portion collided with the rear of bus (JTJ7628). I then alighted and made a check.

There are passengers in the bus (JTJ7628) however I do not recall how many were there. Nobody was injured. There are damages to my vehicle (YQ744B); dent to front portion and damaged headlight however was still operatable. There was a small scratch to the bus (JTJ7628) rear and the Malay driver of JTJ7628 asked me for compensation of SGD\$80/- to which I gave him.


There was no attendance by Traffic Police or Ambulance.

I wish to state that I do not have an in car camera in my vehicle (YQ744B). I was instructed by my insurance company to lodge a Traffic Accident report.

PR



SINGAPORE
POLICE FORCE



T/20190528/2072

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

3 of 3

Report No. T/20190528/2072

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 3 MOHAMED ZAMIL BIN MOHAMED ANIS	Signature Of Informant: <i>A. Shumay</i>
Signature Of Interpreter: Not applicable	Date/Time: 28/05/2019 12:41
Officer In Charge Of Case: TP / AEIT / SSI 2 YEO GEAK ENG CECILIA Contact No.: 65476404	Classification Of Case:
Authentication Stamp NP168	 SIGNATURE

AUTHORISATION LETTER

Date: 28/05/19

To: Accident Reporting Centre (ARC)

I / We hereby approve (driver's name) Amaraji Subramani
NRIC/FIN G 2472950N, our employee / employee of Digo
Corporation Pte Ltd to drive our m/vehicle no. YQ 744B
and to file the accident report (Third Party claims/Own Damage Claims/Reporting
Only) which occurred on (date) 21/05/19 @ (time) 19:30
along (location) KPE Twns TPE after Old Tampines Rd Exit.

* Relationship between Insured and driver's company: -

Thank you.

Regards,

X S. Kumar



* SIGN & STAMP at the above *

Name of Owner: Digo Building Construction Pte Ltd

NRIC / ROC: 20171461211

Contact No: 6752 7433

Email: vehicle@digo.com.sg



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 10 Singapore 638094
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 1 / 3

ESTIMATE

Date	: 31/05/2019	Reg No	: YQ744B
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER4SDEN CBU MT
Attn.	:	Chassis No	: FEB21EA30085
Office / Mobile	:	Engine No	: 4P10D29310
Email Address	:	Quotation No.	: 88491
		Ref. No.	: GBE/SVC/SALES-4881/190531
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 21/05/2019
Attn.	: ENKWOKLONG	Policy No.	: DMCVSN191681900
Office / Mobile	: +65 6864 0637	Claim Type	: OD CLAIM - CHINA TAIPING
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1	ML274721	CAP, SIDE MIRROR COVER LH FLAT <i>/ Mis</i>	1	28.83	-10	25.95	25.95
2	MK580752	MIRROR, UNDER VIEW <i>/</i>	1	55.22	-10	49.70	49.70
3	MC978995	GARNISH, FR PANEL <i>/ X NN</i>	1	373.08	-10	335.77	335.77
4	ML230271	PANEL ASSY, FR <i>/ Panel</i>	1	2,367.22	-10	2,130.50	2,130.50
5	MK707820	RAIL ASSY, WINDSHIELD <i>/ X NN</i>	1	1,439.87	-10	1,295.88	1,295.88
6	MC978783	PANEL, CAB FR CORNER -LH <i>/ BR.</i>	1	492.41	-10	443.17	443.17
7	MC975899	GRILLE, FRONT (NATURALWH <i>/ Cut</i>	1	719.33	-10	647.40	647.40
8	MK546617	MARK, FUSO <i>/</i>	1	150.59	-10	135.53	135.53
9	MK546616	MARK, 3-DIA <i>/ MCL.</i>	1	80.22	-10	72.20	72.20
10	MK675497	EMBLEM, CANTER <i>/</i>	1	76.22	-10	68.60	68.60
11	MX915952	LAMP ASSY, TURN SIGNAL, FR -LH <i>/ CRA.</i>	1	197.31	-10	177.58	177.58
12	MK583357	AIR INTAKE BOX, HEATER UNIT <i>/ CRA (photo)</i>	1	845.66	-10	761.09	761.09
13	ML298316	HEATER ASSY (Superseded from MK583365) <i>/ CRA</i>	1	2,349.20	-10	2,114.28	2,114.28
14	MK654863	HOSE, HEATER WATER <i>/ STur</i>	1	22.54	-10	20.29	20.29
15	MK450980	HOSE, HEATER WATER <i>/</i>	1	20.42	-10	18.38	18.38
16	MH021330	CLAMP <i>/ MCL</i>	2	7.32	-10	6.59	13.18
17	MK590330	RESERVOIR, P/S OIL <i>/ Cut</i>	1	541.44	-10	487.30	487.30
18	QZ010750	C FUSO LLC 4L <i>/ MCL.</i>	1	62.00	-10	55.80	55.80

PARTS TOTAL : 8,852.60

SPECIAL NETT ITEMS

1	POWER STEERING FLUID <i>/ MCL.</i>	1	40	60.00
PARTS TOTAL:			40	60.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

bisSAFE
STAR





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 636894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No.: 198003963G

Page 2 / 3

ESTIMATE

Date	: 31/05/2019	Reg No	: YQ744B
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER4SDEN CBU MT
Attn.	:	Chassis No	: FEB21EA30085
Office / Mobile	:	Engine No	: 4P10D29310
Email Address	:	Quotation No.	: 88491
		Ref. No.	: GBE/SVC/SALES-4881/190531
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 21/05/2019
Attn.	: ENGKWOKLONG	Policy No.	: DMCVSN191681900
Office / Mobile	: +65 6864 0637	Claim Type	: OD CLAIM - CHINA TAIPING
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	600	2400	3000.00
2	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	350	1050	1400.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK		180	250.00
4	SUNDRIES		20	80.00
5	TO REMOVE AND REFIX FRONT WINDSCREEN TO ASSIST REPAIR		180	200.00
6	TO REMOVE AND REFIX FRONT DASHBOARD		600	750.00
7	TO REMOVE AND REFIX AIRCON SYSTEM. TO CHECK FUNCTION		600	750.00
8	AIRCON GAS		50	80.00
9	TOWING FEES		NN x 1	100.00

LABOUR TOTAL : 6,610.00

SUB-TOTAL : 15,522.60

GST @ 7% for \$ 15,522.60 1,086.58

GRAND TOTAL (S\$) : 16,609.18

Signature
11/6/19

7 Days. Not Authorised.
part by part.
before paint photos.
Guo Qiang - 82880282
Guo Qiang @ 1kk auto. com
Excess \$500 07/6/19.

biSAFE
STAR

AIA
SAC
Certificate No: AIA(1912124)

AIA
ULAS
Certificate No: AIA1054



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 636694
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 198003983G

Page 3 / 3

ESTIMATE

Date	: 31/05/2019	Reg No	: YQ744B
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER4SDEN CBU MT
Attn.	:	Chassis No	: FEB21EA30085
Office / Mobile	:	Engine No	: 4P10D29310
Email Address	:	Quotation No.	: 88491
		Ref. No.	: GBE/SVC/SALES-4881/190533
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 21/05/2019
Attn.	: ENGKWOKLONG	Policy No.	: DMCVSN191681900
Office / Mobile	: +65 6864 0637	Claim Type	: OD CLAIM - CHINA TAIPING
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

PREPARED BY : ENGKWOKLONG

DATE / TIME : _____

SURVEYOR : _____

MOBILE NO : _____

OFFICE FAX NO : _____

EMAIL ADDRESS : _____

EXCESS AMOUNT : _____

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : _____

REMARKS : _____



Certificate No: AJA/8/1914240

Certificate No: AJA/1914



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
10 Tuas Avenue 18 Singapore 836894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 168003983G

Page 1 / 3

ESTIMATE

Date : 31/05/2019
To : CHINA TAIPING INSURANCE
(SINGAPORE) PTE. LTD.
Attn. :
Office / Mobile :
Email Address :

From : GOLDBELL ENGINEERING PTE LTD
Attn. : ENKWOKLONG
Office / Mobile : +65 6864 0637
Email / Fax No. : EngKwokLong@goldbell.com.sg

Reg No : YQ744B
Model : FEB21ER4SDEN CBU MT

Chassis No : FEB21EA30085
Engine No : 4P10D29310
Quotation No. : 88491
Ref. No. : GBE/SVC/SALES-4881/190531
D.O.A. : 21/05/2019
Policy No. : DMCVSN191681900
Claim Type : OD CLAIM - CHINA TAIPING
Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1	ML274721	CAP, SIDE MIRROR COVER LH FLAT <i>5m/s</i>	1	28.83	-10	25.95	25.95
2	MK580752	MIRROR, UNDER VIEW	1	55.22	-10	49.70	49.70
3	MC978995	GARNISH, FR PANEL	1	373.08	-10	335.77	335.77
<i>mk207624</i>	ML230271	PANEL ASSY, FR <i>Panc.</i>	1	2,367.22	-10	2,130.50	2,130.50
5	MK707820	RAIL ASSY, WINDSHIELD	1	1,439.87	-10	1,295.88	1,295.88
6	MC978783	PANEL, CAB FR CORNER -LH <i>BR.</i>	1	492.41	-10	443.17	443.17
7	MC975899	GRILLE, FRONT (NATURALWH <i>cut</i>	1	719.33	-10	647.40	647.40
8	MK546617	MARK, FUSO	1	150.59	-10	135.53	135.53
9	MK546616	MARK, 3-DIA <i>McL.</i>	1	80.22	-10	72.20	72.20
10	MK675497	EMBLEM, CANTER	1	76.22	-10	68.60	68.60
11	MX915952	LAMP ASSY, TURN SIGNAL, FR -LH <i>CRA</i>	1	197.31	-10	177.58	177.58
12	MK583357	AIR INTAKE BOX, HEATER UNIT <i>CRA (photo)</i>	1	845.66	-10	761.09	761.09
13	ML298316	HEATER ASSY (Superseded from MK583365)	1	2,349.20	-10	2,114.28	2,114.28
14	MK654863	HOSE, HEATER WATER	1	22.54	-10	20.29	20.29
15	MK450980	HOSE, HEATER WATER	1	20.42	-10	18.38	18.38
16	MH021330	CLAMP	2	7.32	-10	6.59	13.18
17	MK590330	RESERVOIR, P/S OIL	1	541.44	-10	487.30	487.30
18	QZ010750	C FUSO LLC 4L	1	62.00	-10	55.80	55.80

PARTS TOTAL : 8,852.60

SPECIAL NETT ITEMS

1	POWER STEERING FLUID	1	40	60.00
PARTS TOTAL:			60.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638094
Tel: +65 6881 0007 Fax: +65 6881 3676 (Sales)
Fax: +65 6883 0425 (Service) +65 6882 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 2 / 3

ESTIMATE

Date	: 31/05/2019	Reg No	: YQ744B
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER4SDEN CBU MT
Attn.	:	Chassis No	: FEB21EA30085
Office / Mobile	:	Engine No	: 4P10D29310
Email Address	:	Quotation No.	: 88491
From	: GOLDBELL ENGINEERING PTE LTD	Ref. No.	: GBE/SVC/SALES-4881/190531
Attn.	: ENKWOKLONG	D.O.A.	: 21/05/2019
Office / Mobile	: +65 6864 0637	Policy No.	: DMCVSN191681900
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Claim Type	: OD CLAIM - CHINA TAIPING
		Workshop	: 8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	600	2400	3000.00
2	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	350	1050	1400.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK		180	250.00
4	SUNDRIES		20	80.00
5	TO REMOVE AND REFIX FRONT WINDSCREEN TO ASSIST REPAIR		180	200.00
6	TO REMOVE AND REFIX FRONT DASHBOARD		600	750.00
7	TO REMOVE AND REFIX AIRCON SYSTEM, TO CHECK FUNCTION		600	750.00
8	AIRCON GAS		50	80.00
9	TOWING FEES		x ?	100.00

LABOUR TOTAL :	6,610.00
SUB-TOTAL :	15,522.60
GST @ 7% for \$ 15,522.60	1,086.58
GRAND TOTAL (\$):	16,609.18

7 Days. Not Authorised.
part by part.

before paint photos.

Guo Qiang - 82880282

Guo Qiang @ 1kk auto. com

Excess \$500 07/6/19.

P: 7556.72
S/N: 60.00
L: 5080

Total: 12696.72

bizSAFE



Veron Chen (LKKAuto)

From: Brian Eng Kwok Long <EngKwokLong@goldbell.com.sg>
Sent: Friday, 21 June 2019 11:37 AM
To: Veron Chen (LKKAuto); SUR
Cc: Ramesh
Subject: Re: Finalise YQ 744 B

Hi Veron,

We accept finalise amount \$12,340.95 @ 7 working days.

Thanks and Best regards



Brian Eng Kwok Long | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>



From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Friday, 21 June 2019 11:04:55 AM
To: SUR; Brian Eng Kwok Long
Cc: Ramesh
Subject: RE: Finalise YQ 744 B

Dear Brian,

Our finalise amount \$12,340.95 @ 7 working days.

Parts-\$7220.95
SN-\$40
Labour-\$5080
Total-\$12,340.95

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Brian Eng Kwok Long <EngKwokLong@goldbell.com.sg>
Sent: Friday, 21 June 2019 8:40 AM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>

Cc: Ramesh <Ramesh@goldbell.com.sg>

* **Subject:** Finalise YQ 744 B

Hi Guo Qiang,

Kindly refer to the attached above.

Can we finalise the amount @ **\$12696.72?**

Thanks & Best Regards



Brian Eng Kwok Long | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 May 2019		06 Jun 2019 15:27 Edit Adj Rpt	S\$12,340.95 Edit Estimates	S\$12,340.95 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	DIGO BUILDING CONSTRUCTION PTE LTD , Co. Reg. No.: 201714612N								
Vehicle Reg. No.:	YQ744B	Date of Loss:	21/05/2019 19:00 - :59 [1 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D202458C01	Policy/Cover Note No.:	DMCVSN191681900 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Goldbell Engineering Pte Ltd ((Tuas)) No. 10 Tuas Avenue 18, 638894 Tuas - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 17/06/2019]								
Driver/Custodian:	AMARAJI SUBRAMANI (25 / Male) , NRIC: G2472950N, Tel: +6583011220 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (11/06/2019): Alert - Adj Mandate Approved (S\$14032.60) - YQ744B - Claim Handler: Elaine Cheon...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents




















*YQ744B (SNM19D202458C01)

OD


May 21 2019 7:00PM














[DIGO BUILDING CONSTRUCTION PTE LTD]

Goldbell Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	28/05/19 19:05	Accident Statement	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/06/19 14:59	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	28/05/19 18:50	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	28/05/19 18:50	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	28/05/19 18:50	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	28/05/19 18:50	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	28/05/19 18:50	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	28/05/19 18:50	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/06/19 14:54	General View	 Load PDF	
2	21/06/19 10:56	Reinspection Photo	 Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/06/19 15:29	OD - REPAIR ESTIMATE - YQ744B	 Load PDF	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	28/05/19 18:46	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	28/05/19 18:46	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	28/05/19 18:48	PR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	28/05/19 18:48	PR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	28/05/19 18:48	PR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	28/05/19 18:48	AUTHORISATION LETTER [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	28/05/19 18:48	WP & DL [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/06/19 14:54	MARK ESTIMATE	 Load PDF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	28/05/19 19:05	Accident Statement	 Load HTM	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	28/05/19 18:50	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	28/05/19 18:50	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	28/05/19 18:50	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	28/05/19 18:50	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	28/05/19 18:50	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	28/05/19 18:50	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	28/05/19 18:46	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	28/05/19 18:46	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>
3	28/05/19 18:48	PR		Load JPG	<input checked="" type="checkbox"/>
4	28/05/19 18:48	PR		Load JPG	<input checked="" type="checkbox"/>
5	28/05/19 18:48	PR		Load JPG	<input checked="" type="checkbox"/>
6	28/05/19 18:48	AUTHORISATION LETTER		Load JPG	<input checked="" type="checkbox"/>
7	28/05/19 18:48	WP & DL		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119010001/GVD3E2

Date: 01/07/2019

REFERENCE

Insured/Claimant:	DIGO BUILDING CONSTRUCTION PTE LTD	Policy No:	DMCVSN191681900	Claim No:	SNM19D202458C01
Date of Loss:	21/05/2019	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ744B		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (CBU) (M)	Engine No:	4P10D29310
Reg. Date:	15/04/2019 (Man. Year: 2018)	Chassis No:	FEB21EA30085
Colour:	White	Odometer:	4850 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	S\$85,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D)
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8/8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,992.60	7,280.95	1,711.65	19.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,530.00	5,060.00	1,470.00	22.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,522.60	12,340.95	3,181.65	20.50
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	15,022.60	11,840.95	3,181.65	21.18
+ GST 7.00/7.00% (S\$)	1,051.58	828.87	222.71	21.18
Nett Amount (S\$)	16,074.18	12,669.82	3,404.36	21.18

INSPECTION

Date of Assignment:	06/06/2019	
Date Inspected:	07/06/2019	Inspected At: Goldbell Engineering Pte Ltd ((Tuas)) No. 10 Tuas Avenue 18 Singapore 638894
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Jul 2019)	
Parts:	N/A	mitsubishi canter 3.0 D FEB21ER3SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ744B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CAP, SIDE MIRROR COVER LH FLAT	Missing	25.95 FS	*25.95 FS
2	1		*MIRROR, UNDER VIEW	Missing	49.70 FS	*49.70 FS
3	1		*GARNISH, FR PANEL	Not Necessary	335.77 FS	*- FS
4	1		*PANEL ASSY, FR	Buckled	2,130.50 FS	*2,130.50 FS
5	1		*RAIL ASSY, WINDSHIELD	Not Necessary	1,295.88 FS	*- FS
6	1		*PANEL, CAB FR CORNER - LH	Broken	443.17 FS	*443.17 FS
7	1		*GRILLE, FRONT (NATURALWH	Cut	647.40 FS	*647.40 FS
8	1		*MARK, FUSO	Necessary	135.53 FS	*135.53 FS
9	1		*MARK, 3-DIA	Necessary	72.20 FS	*72.20 FS
10	1		*EMBLEM, CANTER	Necessary	68.60 FS	*68.60 FS
11	1		*LAMP ASSY, TURN SIGNAL, FR - LH	Cracked	177.58 FS	*177.58 FS
12	1		*AIR INTAKE BOX, HEATER UNIT	Cracked	761.09 FS	*761.09 FS
13	1		*HEATER ASSY (SUPERSEDED FROM MK583365)	Cracked	2,114.28 FS	*2,114.28 FS
14	1		*HOSE, HEATER WATER	Twisted	20.29 FS	*20.29 FS
15	1		*HOSE, HEATER WATER	Twisted	18.38 FS	*18.38 FS
16	2		*CLAMP	Necessary	13.18 FS	*13.18 FS
17	1		*RESERVOIR, P/S OIL	Cut	487.30 FS	*487.30 FS
18	1		*C FUSO LLC 4L	Necessary	55.80 FS	*55.80 FS
19	1		*POWER STEERING FLUID	Necessary	60.00 FS	*40.00 FS
20	1		*SUNDRIES	Necessary	80.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	8,992.60	7,280.95
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	New	3,000.00	2,400.00
2	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	New	1,400.00	1,050.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	New	250.00	180.00
4	TO REMOVE AND REFIX FRONT WINDSCREEN TO ASSIST REPAIR	New	200.00	180.00
5	TO REMOVE AND REFIX FRONT DASHBOARD	New	750.00	600.00
6	TO REMOVE AND REFIX AIRCON SYSTEM. TO CHECK FUNCTION	New	750.00	600.00
7	AIR CON GAS	New	80.00	50.00
8	TOWING FEES	New	100.00	0.00
Gross Labour Cost (\$\$)			6,530.00	5,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >