

ASSIGNMENT

From

Date:

Estimated Cost

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop mth

of

Insured

Policy No

Claims No

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Mr - 70K

Veh No

SHB 8688H

Vt Regn.

8/11/17

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Hyundai 130

G.C 1582

Colour Silver

A/C Insured / Std / NI / N

Sp. Reading

136369

T/Ratio: Insured / Std / NI / N.

Eng/No:

Ci/No:

TMA 0281UVH J14/1990.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil ☒ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

R:

195/6SR15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

3/6/19

D.O.I.

19/6/19

Survey held at

Premier

Pos. of Damages: Frl ☒ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date/Time: File Pass to?

☐ : Procl. Report
☐ : Final Report

Date/Time: File Return to?

19/6 - typist

Report Format:

CWS

Lump Sum / I.B. /

1146.89

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation

1 - 3 - R5 - 2

1 - Premium

1 - Index

1 -

2/1/19

130

50

50

24

254

RECEIVED 19 JUN 2019



Auto
Consultants
Pte Ltd

Company Registration No. 19960719E

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 625643

Your ref: D19003702MFSH

Our ref: CS/FCI19010078/Evd3

Date : 12/6/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 8688H


We thank you for your instruction on 7/6/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10/6/2019 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$3,189.64
Revised Estimate Amount	: S\$1,146.89
"Check" Items Amount	: S\$1,142.75
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

STEVE CHEN
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	06-06-2019	Our Ref No. D19003702MFSH
Accident Date	03-06-2019	Claim Type. Third Party
Insured Vehicle	SHC2188T	Third Party Vehicle. SHB8688H
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GOH WEE DEK	
Contact No.	62148880/ 65446682	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 19 June 2019 10:29 AM
To: Goh Wee Dek; SUR
Subject: RE: SHB 8688H-DOA: 3/6/2019

Dear Wee Dek,

WITHOUT PREJUDICE

Confirm PxP \$1,146.89 before GST @ 2 working days

Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh Wee Dek <weedek.goh@premiertaxi.com>
Sent: Wednesday, 19 June 2019 8:45 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: SHB 8688H-DOA: 3/6/2019

Dear Veron

Yes, please confirm PxP \$1,146.89

No check items

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, 18 June, 2019 5:26 PM

To: Goh Wee Dek

Subject: SHB 8688H-DOA: 3/6/2019

Dear Wee Dek,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 12 June 2019 9:43 AM
To: 'CWS Motor Claims'
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003702MFSH/1, SHB 8688H
Attachments: SHB 8688H PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHB 8688H

Date of survey: 10/6/2019

Number of days : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 7 June 2019 2:05 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003702MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 7 June 2019 12:36 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003702MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Vehicle Details

Intended PARF Rebate Details

Intended COE Rebate Details

COE Expiry Date:	07 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$26,915.00
Total Rebate Amount:	\$36,538.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

OK

PREMIER TAXIS	HIRER / RELIEF / SUPER RELIEF
VEHICLE NO.	SHB 8688 H
CONTACT NO.	906 06500
NEW MAILING ADDRESS (if any)	/

REPUBLIC OF SINGAPORE

DRIVING LICENCE

 Licence Number: **S0549890B**
Name: **HENG AH NGO**

Birth Date: **10 Jan 1951**
Issue Date: **13 May 2004**

 0012172160

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S0549890B



HENG AH NGO

郡王山

CHINESE

10-01-1901	10
------------	----

SINGAPORE

Land Transport  Authority

VOCATIONAL LICENCE

License No : S0549890B

Name : HENG AH NGO

Issue Date : 13/10/2009

Please visit www.ita.gov.sg to check the status of this vocational licence

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

[illegible]

220148



UNIT No. 505498908



Block Group Date of issue
A- 08-08-1984

Address
APT BLK 205 MARSLING DRIVE
#12-252
SINGAPORE 2573

NP 425A

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
02	TAXI VL	05/06/1986
03	BUS VL	16/06/1981




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Steve CLKK)
8323 8813

WHL Repaired 10/6/19, 2:00pm
2 days
P/P Rg bef- spg

12/6/19

PREMIER AUTOMOTIVE SERVICES PTE LTD

Steve Chm @ LKKAUTH-COM

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

6th 65446682

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

100% - LKKA

8-Jun-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8688 H

1 pc	Rear bumper ✓ 00	\$	811.11
1 pc	Rear bumper sponge ? X N/A	\$	79.20
1 pc	Rear bumper reinforcement ? X N/A	\$	815.64
1 pc	Rear bumper reinforcement centre ? X N/A	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20 ? X N/A	\$	104.40
		\$	1,889.55
	Less 20%	\$	377.91
		\$	1,511.64

S/NETT

1 set	Rear bumper clips ✓ N/A	\$	48.00
1 set	Reverse sensor ? X N/A	\$	280.00

Sundry LKKA \$ 50.00 30

To dismantle and replace reverse sensor and test system \$ 80.00 20

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel etc. \$ 700.00 100

To putty and spray painting on the rear bumper, End panel \$ 400.00 200

To apply rustproofing on the repaired and replaced panels \$ 120.00 80 X

Total \$ 3,189.64

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKKA Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be requested and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19010078/Evd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-06-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2188T	Veh. Inspected	SHB 8688H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003702MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	07/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I30	c.c	1582	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	TMAD281UVHJ141990	Colour	SILVER	
Odometer	136369	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MAXXIS	7 mm	
L/H Front Tyre	195/65 R15	MAXXIS	7 mm	
R/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
L/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/06/2019	Inspection Date	10/06/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No, 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8688H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DENTED	811.11	811.11
1	REAR BUMPER SPONGE	NOT NECESSARY	79.20	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	815.64	-
1	REAR BUMPER REINFORCEMENT CENTRE	NOT NECESSARY	79.20	-
2	REAR BUMPER N/S & O/S SIDE BRACKET @\$52.20	NOT NECESSARY	104.40	-
	LESS 20% DISCOUNT		-377.91	-162.22
			1,511.64	648.89
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	SUNDRY (SN)	NECESSARY	50.00	30.00
			378.00	78.00
<u>LABOUR</u>				
	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM.		80.00	20.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS INCLUDING TO KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE OF THE END PANEL ETC.		700.00	200.00
	TO PUTTY AND SPRAY PAINTING ON THE FRONT BUMPER, END PANEL.		400.00	200.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,300.00	420.00
GRAND TOTAL			3,189.64	1,146.89
RECOMMENDED COST OF REPAIRS				1,146.89

Report Ref No. CS/FCI19010078/Evd3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.