

ASS. REC. BY:

REF:

C3/FCI17010079/T19d3/n2

Special Instruction:

Survey: Tanfikh

ASSIGNMENT (Office)

CWS

From (Person): Eileen Lee

of

FCI

Date/Time: 5:06pm @ 6/6/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 1576D

Insured:

SHB 6388L

at Workshop m/s

Cycle & Ceramic Industries

Tel:

91865112

of

188 Pandan Road

Policy No:

Claim No:

D190036 43MFST

Sum Insured:

Excess:

Make of Vehl:

(Client's Record)

D.O.A. 30/5/2019

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time: 9:51am @ 7/6/19

Person Contacted:

Alan

Vehicle IN/OUT

Date/Time	Action/Instruction
	SKQ 1576D - x
	SHB 6388L - NS/INC 18V18231/Klvbn2 D.O.A. 6/10/2018
6/6/19 @ 12:14pm	visited to Eileen Lee by email.
26/8/19 @ 1:30pm	confirmed with C&C for 4 days, 4 days.
	Used \$780, 21%.

Tanp

REF:

FC1

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop on/ in: _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAG Accident Report: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 4 days Res: Yes or No
Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Man

Veh No: SKQ15760 Yr Reg: 2014 NOV
Type: M/Cat / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or 2996

Make: Mercedes Benz 9400 C.C. 3498
Colour: Black A/C: Insured / Std / Nil / NA
Sp. Reading: 40866 T/Radio: Insured / Std / Nil / NA

Eng/No: _____
C/No: WDD22216529125788

Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD / STD A/Rim or
Tyre Size: F: 245/45R19
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: _____ Rear: _____
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm

D.O.A: _____ D.O.L: 17/6/17 @ 330pm
Survey held at: C&C Pandan Imp.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 20 AUG 2019

Date/Time, File Pass by: _____

1) 26/8/19 _____: Preli. Report

2) _____: Final Report

Date/Time, File Return by:

Report Format: TP
Lump Sum / L.B. (\$): 3020

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

3) 2 + 125 = 127

4) Photos:

5) Other:

TOTAL



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003643MFSH

Date: 18 June 2019

Our Ref: CS/FCI19010079/T1qd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKQ 1576D

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/06/2019 at the premises of M/s CYCLE & CARRIAGE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,800.00</u>
Revised Estimate Amount	: S\$ <u>3,020.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the n/s portion.



Yours faithfully

Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	03-06-2019	Our Ref No. D19003643MFSH
Accident Date	30-05-2019	Claim Type. Third Party
Insured Vehicle	SHB6388L	Third Party Vehicle. SKQ1576D
Survey Location	PANDAN LOOP SERVICE CENTER 188 PANDAN LOOP	
Contact Person.	ALAN QUEK	
Contact No.	67714377/ 91865112	Fax No. 68721272
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE INDUSTRIES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 26 August 2019 1:36 PM
To: 'Alan Quek'; Cheong Chin Leong
Subject: RE: SURVEYOR APPOINTED; OUR REF : D19003643MFSH ; YOUR REF: SKQ1576D

Dear Sir,

WITHOUT PREJUDICE

Confirm final fig \$3,020.00 before GST and 4 repair days.

Kindly send the relevant documents to MS First Capital Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 21 August 2019 2:02 PM
To: 'Alan Quek' <alan.quek@cyclecarriage.com.sg>; Cheong Chin Leong <chinleong.cheong@cyclecarriage.com.sg>
Subject: RE: SURVEYOR APPOINTED; OUR REF : D19003643MFSH ; YOUR REF: SKQ1576D

Dear Sir,

Re-send.

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 29 July 2019 3:24 PM
To: 'Alan Quek' <alan.quek@cyclecarriage.com.sg>; Cheong Chin Leong <chinleong.cheong@cyclecarriage.com.sg>
Subject: RE: SURVEYOR APPOINTED; OUR REF : D19003643MFSH ; YOUR REF: SKQ1576D

Dear Sir,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 18 June 2019 12:14 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003643MFSH/1
Attachments: CSFCI19010079T1qd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SKQ 1576D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 7 June 2019 9:53 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003643MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd



Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 6 June 2019 5:06 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003643MFSH/1

Dear Sir/Mdm,

Sketch Plan Pg. 3





MS First Capital Insurance Limited Co Reg No: 1950001060 CST Reg No: M2 0001676-3
5 Raffles Quay #21-00 Singapore 048500
Tel: (65) 6222 2311 Fax: (65) 6222 3547
Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877
Tel: (65) 6507 3848 Fax: (65) 6507 3849
www.msfirstcapital.com.sg

CERTIFICATE OF INSURANCE

ORIGINAL

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Type of Policy : PRIVATE CAR - FLEET
Type of Cover : Comprehensive
Certificate No : D-19093107MFPC
Vehicle No / Chassis No : SKQ1576D / WDD2221652A125788
Name of Insured : ONG BENG SENG S2158153D.
Period Of Insurance : 01.04.2019 To 31.03.2020
Insured Estimated Value : Market Value At Time Of Loss

Excess :

SGD750.00 SECTION I
COMPULSORY EXCESS OF ADDITIONAL SGD1,000.00 APPLIES TO :-
(1) DRIVERS BELOW THE AGE OF 25 YEARS AND/OR
(2) HAS LESS THAN 1 YEAR DRIVING EXPERIENCE

Authorised Driver*

ONG BENG SENG AND ANY AUTHORISED DRIVERS

Persons or classes of persons entitled to drive*

- 1) The Insured.
The Insured may also drive a Motor Car not belonging to or hired (under a hire purchase agreement or otherwise) to him or his employer or his partner.
- 2) Any other person who is driving on the Insured's order or with his permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitations as to use*

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or reward, racing, pacemaking, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

MS First Capital Insurance Limited
(Approved Insurers)

JENNY/B0020/MX1F

Issued at Singapore on 27.03.2019

Authorised Signature

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKQ1576D

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No **33942**
Reg No/Reg Date **SKQ1576D / 06/11/2014**
Date In/Mileage **/ 0**
Chassis No **WDD2221652A125788**
Engine No **27682430123091**
Make/Model **MB/S 400 L BlueEFFICIENCY SE**
Colour/Trim **021 197 Obsidian Bl/ 048 801 Nappa Black**

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	04/06/2019/ 10:25	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : D1903107MFPC // 30-05-2019 DRIVE IN: 03-06-2019 // TP CAR NO: SHB6388L (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB REPAIR FRONT LEFT FENDER & FRONT LEFT DOOR				1920.00
A BPIRES RESpray FRONT LEFT FENDER & FRONT LEFT DOOR				1500.00

18/6/19

Tayfun 97495789

WP

17/6/19 330pm

04 days

Renew after repair

sure Takant.com

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
Tel: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@c-and-c.com.sg

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer **7% GST on 3800.00**
Signature:
Date:

Confirmed & accepted by

Authorized signatory and company stamp

Nett **3,800.00**
266.00
Total Payable 4,066.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SKQ1576D

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Taufikh

Vehicle & Document Information

WIP No 33942
Reg No/Reg Date SKQ1576D / 06/11/2014
Date In/Mileage 17/06/2019 / 40866
Chassis No WDP2221652A125788
Engine No 27682430123091
Make/Model MB/S 400 L BlueEFFICIENCY SE
Colour/Trim 021 197 Obsidian Bl/ 048 301 Nappa Black

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	29/07/2019/ 23:36	AQ	305 / Alan Quek Al Lun
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount

M. BPN SUN

POLICY NO: ACC DATE: 01/03/10/MFBC // 30-03-2019
DRIVE IN: 03-06-2019 // TP CAR NO: SHB6388L (FIRST CAPITAL INSURANCE)
DATE IN/DATE SURVEY: 17-06-2019 // LKK TAUFIKH
BY/AUTHORIZED ON: EILEEN LEE // 06-06-2019

A BPILAB
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB
REPAIR FRONT LEFT FENDER & FRONT LEFT DOOR

A BPIRES
RESPRAY FRONT LEFT FENDER & FRONT LEFT DOOR

0.10 380.00
1440.00
1200.00

THIS IS NOT AN OFFICIAL TAX INVOICE
4 Days
ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DDD: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 3,020.00
7% GST on 3020.00 211.40
Total Payable 3,231.40

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
198 Pandan Loop
Singapore 128376
Tel: 6777 6388
Fax: 6779 5363
www.mercedes-benz.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19010079/Tqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-08-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 6388L	Veh. Inspected	SKQ 1576D
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19003643MFSH	Excess (\$)	0.00
	Assign From	EILEEN LEE	Assign Date	06/06/2019
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ S400	c.c	2996
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	WDD2221652A125788	Colour	BLACK
	Odometer	40866	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/45 R19	PIRELLI	6 mm
	L/H Front Tyre	245/45 R19	PIRELLI	6 mm
	R/H Rear Tyre	245/45 R19	PIRELLI	6 mm
	L/H Rear Tyre	245/45 R19	PIRELLI	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	30/05/2019	Inspection Date	17/06/2019
	Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 1576D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
	REPAIR FRONT LEFT FENDER & FRONT LEFT DOOR.		1,920.00	1,440.00
	RESPRAY FRONT LEFT FENDER & FRONT LEFT DOOR.		1,500.00	1,200.00
			3,800.00	3,020.00
	GRAND TOTAL		3,800.00	3,020.00
RECOMMENDED COST OF REPAIRS				3,020.00

Report Ref No. CS/FCI19010079/Tqd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.