## SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711 Tel: 67472112 (5 lines) Fax: 67438032 Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

## SM/SLA3703M/1906075

07<sup>TH</sup> June 2019

The Manager AIG Asia Pacific Insurance Pte Ltd CHARTIS Building 78 Shenton Way #07-16 Singapore 079120

Date of Accident

.

Location

:

Third Party Claim Vehicle No Repair Cost For Vehicle No 05/06/2019 Guillemard Road turning towards Lorong 22 Geylang

SLK7987G SLA3703M VOLVO XC90-2.5 T (A)

Estimate Supply of Parts & Labours

| No. | Particulars                  | Oty    | Price    | Amounts     |
|-----|------------------------------|--------|----------|-------------|
| 1   | Front door assy LH           | 1      | 2,700.00 | \$ 2,700.00 |
| 2   | Front door weather strips LH | 111    | 175.00   | \$ 175.00   |
| 3   | Front door protector LH      | C111   | 200.00   | \$ 200.00   |
| 4   | Front door sticker LH        | 11     | 33.00    | \$ 33.00 ×  |
| 5   | Rear door assy LH            | 20/201 | 2,369.00 | \$ 2,369.00 |
| 6   | Rear door weather strips LH  | ser 1  | 175.00   | \$ 175.00   |
| 7   | Rear door protector LH       | cuil   | 240.00   | \$ 240.00   |
| 8   | Rear door sticker LH         | nu 1   | 27.00    | \$ 27.00    |
|     |                              | 110    |          | \$ 5,919.00 |

|   | (   | \$ 5,919.00         |
|---|---|---------------------|
| Labour Charges :-   | . P-3011<br>2860.48   | Amounts             |
| Cut out, renew, knocking & welding, frodamage parts & re-align body               | ont and rear door LH, remove and install all  | \$ 00.008 \$        |
| Remove & install front & rear door boar locking, glass regulator, motor assy & et | \$ 280.00 Po  |                     |
| Tuff-kote on damage parts   | \$ 80.00 50   |                     |
| Spray painting on damage parts  | LKK Auto Consultants hence notify the Repairer of the following:  | \$ 800.00 600       |
| Check door wiring after repairs   | To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation | \$ 40.00 2          |
| Labour Charge   | Third party survey is on a "Without Prejudice" basis     No illegal modification(s) is allowed                              | \$ 2,000.00         |
| Total Amount  | Supplementary item(s) must be resurveyed and<br>is subject to final approval from Insurance Company                         | \$ 7,919.00 Y(10.48 |
| GST will be reflected in the final bills.   | Acknowledged by Repairer<br>Signature:  |                     |

Notes: -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs, of repairs, loss of use and storage.