

18/02/2019

INS. CASE OWNER:

CC 6 /AIG1900 10143, Ueb34

LKK:
IDAC:

Surveyor:

MARLUS

DOI:

ASSIGNMENT

10/6/19

Date / Time:

10/6/19

Registered in Merimen:

10/6/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLX 1023J

Claim No.:

Name of Insured:

123 LEASING PIV

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

9/6/19

Place of Accident:

Is driver the owner?

(YES NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SLX 1023J



INSRS:

WSP:

Tel:

Liability:

RMKS:

Fastech



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE/ PIC
	SLX 1023J - X	Non-Reporting Itr (1st):	
	SLX 1023J - X	Non-Reporting Itr (2nd):	
		Non-Reporting Itr (Final):	
		Notification Itr (if non-pickup):	
		Call OI:	12-07-19
		After call Itr to OI:	
		Documentation Check List:	Handler Typist
		Notification Itr (if non-pickup):	
		After call Itr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTATA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by: (CS)
FINALIZATION	Date/Time:	Confirm with:	Confirm by: (CS)
Repair Cost:	43 \$56,100	(7 days) Reduction:	68 %
FINAL SETTLEMENT	Date/Time: 27-08-19	Confirm with: 306029	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	9 100	(Agreed / Assessed) BOLA S/N No.:	38
Repair Cost:	43 \$56,327.00		3 VEH CL CO 200
Loss of Rental (LOR):	\$5 320.00	(3 days) x 400	
Loss of Use (LOU):	\$5 -	(5 x days)	
Loss of Income (LOI):	\$5 -	(5 x days)	
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search:	\$51.45		
Medical:	\$5 -		
Disbursement:	\$5 -	(e.g. Tow/ Independent)	
Legal Cost:	\$5 -		
Total:	\$5 6,334.45	Global Sum \$5:	
FINAL PAYMENT	Date/Time: 27-08-19	Confirm with: 306029	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$5 6,334.45	Name 1: FASTECH ASD DE TO	
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

(08/11/13) wef

REF:

A14/

Asher

ASS. REC. BY: Marcus

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/6/19 4/5 #6100 confirmed with Asher

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS. SI

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

VEHICLE NO SLS 3143J

QTY	PARTICULAR
1 PCS	BOOTLID
1 PCS	BOOTLID REAR LOGO
2 PCS	BOOTLID REFLECTORS @\$420.10
1 PCS	BOOTLID INNER LOCK
1 PCS	BOOTLID WEATHERSTRIP 225.00
1 PCS	REAR BUMPER 649.50
1 PCS	REAR BUMPER SPONGE 166.80
1 PCS	REAR BUMPER REINFORCEMENT 366.50
2 PCS	REAR BUMPER REINFORCEMENT STAYS @\$105.00
5 PCS	REAR BUMPER REINFORCEMENT TOP & LOWER BRACKETS @\$22.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$48.50
1 PCS	REAR BUMPER LOWER CENTRE GARNISH
1 PCS	REAR BUMPER LOWER SKIRTING 698.20
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL TOP GARNISH
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOP BOARD
2 PCS	TAILLAMPS @\$465.00
2 PCS	TAILLAMP HOUSING PANELS @\$215.00
2 PCS	REAR FENDERS @\$1105.00
2 PCS	REAR FENDER INNER TRIMS @\$399.20
1 SET	REAR FENDER INNER TRIM CLIPS
1 PCS	REAR EXHAUST
2 PCS	REAR EXHAUST MOUNTINGS @\$45.00

1 SET	S.NETT
1 SET	REAR BUMPER REVERSE SENSOR
1 PCS	REAR REVERSE CAMERA
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR license plate

LABOUR CHARGES:

TO CHECK WIRING	
TO DISMANTLE & REPLACING REVERSE SENSOR	
TO DISMANTLE & REFIX REAR EXHAUST	
TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY	
TO DISMANTLE & REFIX REAR WINDSCREEN	
TO DISMANTLE & REFIX BOOTLID MECHANISM	
TO CONDUCT CHASSIS ALIGNMENT	
TO SPRAY RUSF PROOFING	
LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED	
& REPLACING PARTS	
TO PUTTY & SPRAY PAINTING	

Not Authorised
1/5 6100
10/6/18
Hdy.

20/serf	\$1,120.30
net	\$66.80
che	\$840.20
tax	\$166.30
tax	\$266.50
dis	\$845.20
to-a	\$209.30
cm	\$488.20
11	\$210.00 X
11	\$110.00 X
11	\$97.00 X
ns	\$310.00 X
De	\$1,500.00
20/serf	\$688.20
tax	\$165.00
11	\$1,100.00 X
11	\$365.30 X
che	\$930.00
11	\$430.00 X
11	\$2,210.00 X
11	\$798.20 X
11	\$50.00 X
11	\$820.10 X
11	\$90.00 X
	\$13,876.60

shred	\$280.00
11	\$380.00 X
net	\$50.00
sch	\$50.00 40.

	\$50.00 30
	\$80.00 50
11	\$100.00 X
	\$120.00 80
11	\$150.00 X
	\$100.00 60
11	\$380.00 X
	\$120.00 60
	\$1,800.00 800
	\$1,800.00 1080
TO	\$19,336.60

5662.7
5096.43

102

7626.03
6000

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 9431G

Vehicle Details

Vehicle No.: SLS3143J

Vehicle to be Exported: No

Intended Deregistration Date: 10 Jun 2019

Vehicle Make: KIA

Vehicle Model: CERATO FORTE KOUP 1.6 AT SX ABS
D/AB SR

Primary Colour: Red

Manufacturing Year: 2010

Engine No.: G4FCAH381762

Chassis No.: KNAFW611MA5224565

Maximum Power Output: 92.7 kW (124 bhp)

Open Market Value: \$15,610.00

Original Registration Date: 07 May 2010

First Registration Date: 07 May 2010

Transfer Count: 2

Actual ARF Paid: \$15,610.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 06 May 2020

PARF Rebate Amount: \$7,805.00

Intended COE Rebate Details

COE Expiry Date: 06 May 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$34,001.00

COE Rebate Amount: \$3,077.00

Total Rebate Amount: \$10,882.00

The information contained herein is correct as at 10 Jun 2019

OK



Kia Cerato Price Range Depreciation 2010 Vehicle Type Submit

Advanced Search

Home > Used Cars > Car Auto Connection Pte Ltd > Kia Cerato Forte Koup 1.6A SX

Kia Cerato Forte Koup 1.6A SX

Overview Financial Accessories Similar Research Photos Map

Price	\$15,499		
Depreciation	\$7,530 /yr <small>View models with similar depre</small>	Reg Date	17-Jun-2010 (1yr 6days COE left)
Mileage	N.A.	Manufactured	2010
Road Tax	\$738 /yr	Transmission	Auto
Dereg Value	\$11,270 as of today (change)	OMV	\$15,654
COE	\$26,102	ARF	\$15,654
Engine Cap	1,591 cc	Power	92.7 kW (124 bhp)
Curb Weight	1,232 kg	No. of Owners	4
Type of Vehicle	Sports Car		

Features

1.6L 4 Cylinders DOHC 16 Valves Engine, 124 BHP, 5 Speed Auto Transmission With Steptronic, ABS, ABS, Knockdown Rear Seats, Keyless Entry/Start/Stop. View specs of the Kia Cerato Forte Koup (2009-2013)

Accessories

Sunroof, Leather Seats, Built In Audio With AUX/USB/Steering Controls, Retractable Side Mirrors, Reverse Sensors, Solar Film, Fog Lights.

Description

Sunroof Model! Well Maintained! Minimum PARF Value At \$7,827! Lowest Depreciation! Reverse Camera! Trade In And Loan Available! Do Call To Arrange For Viewing!

Category

PARF Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free
Find out the market value of your existing car for free. Get started

Posted on: 09-Jun-2019 | Last Updated on: 10-Jun-2019

Upfront Payment
Compare

> more Financial info



Location Map

Price Chart

Summary

Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Car Auto Connection Pte Ltd
• dealer's pricelist
• 23 vehs sold | 9 vehs available

Address

229 Mountbatten Road #02-41
Search cars nearby this location

- New Electricity Service providers
- Unusual or rare cars
- [AMA] I drove before cars of various makes before

Kia Cerato Price Range Depreciation 2010 Vehicle Type

Advanced Search

Home » Used Cars » Carbiz Pte Ltd » Kia Cerato Forte Koup 1.6A SX

Kia Cerato Forte Koup 1.6A SX

Overview Financial Accessories Similar Research Photos Map

Price	\$16,889		
Depreciation	\$9,340 /yr <small>View models with similar depre</small>	Reg Date	31-May-2010 (11mths 20days COE left)
Mileage	N.A.	Manufactured	2010
Road Tax	\$738 /yr	Transmission	Auto
Dereg Value	\$9,562 as of today (change)	OMV	\$15,610
COE	\$18,060	ARF	\$15,610
Engine Cap	1,591 cc	Power	92.7 kW (124 bhp)
Curb Weight	1,232 kg	No. of Owners	2
Type of Vehicle	Sports Car		

Features

Powerful 1.6L DOHC 16 Valves, Smooth 6 Speed Tiptronic Auto Transmission, Multi-Function Steering Control And Auto Headlights. Sunroof Model. View specs of the Kia Cerato Forte Koup (2009-2013)

Accessories

Electric Sunroof, Mood Interior Lighting, Bury Bluetooth System, Full Keyless Entry & Start System,Built-In Audio With AUX/USB/Steering Control

Description

Only 2 Owners. Superbly Maintained Almost Pristine Interior And Exterior! View To Appreciate! Low Depreciation Either As Short Term Drive Or COE Renewal! Easiest Maintenance And Lowest Cost Of Ownership Sports Coupe In The Market! Trade-In Welcome. Flexible Financing Packages Available. Lease Or Rental Available.

Category

PARF Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 23-May-2019 | Last Updated on: 31-May-2019


Compare



Location Map

Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Carbiz Pte Ltd

• dealer's prelist

• 16 vels sold | 4 vels available

Address

1 Commonwealth Lane #01-19

Search cars nearby this location

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

Date : 08.08.2019

AIG Asia Pacific Insurance Pte Ltd
Chartis Building
78 Shenton Way #07-16
Singapore 079120

Attn: Motor Claim Department

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES : SLS 3143J / SLX 1023J AND OTHER ON 09.06.2019

We are the authorized repair workshop for the owner of motor vehicle no: **SLS 3143J**, which was involved in the captioned accident with your insured vehicle no: **SLX 1023J**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$ 6,527.00
2) Loss of Rental	\$ 300.00
3) LTA Search Fee	\$ 7.45
	<u>\$ 6,834.45</u>

We enclosed herewith the following documents to support the claims:

- | | |
|--------------------------|------------------------------------|
| a) Final Repair Invoice | b) Car Rental Invoice / Agreement |
| c) LTA Search Result | d) Letter of Authorisation, etc... |
| e) GIA Report | f) I/C & Driving Licence |
| g) Insurance Certificate | h) Vehicle Registration Log Card |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.
Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)
For FASTECH AUTO PTE LTD



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG19010143/Ueb3

12 JULY 2019

123 LEASING PTE LTD
210 TURF CLUB ROAD
#LOT-A8 THE GRANDSTAND
SINGAPORE 287995

Dear Sir/Madam,

ACCIDENT INVOLVING SLX 1023J / SLS 3143J / OTHERS ON 09/06/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Gan Wei Yi, Edwin ("the third party claimant")
of Blk 140 Bedok Reservoir Road #08-1513 Singapore 470140 (address),
owner of SLS 3143J (vehicle no.) hereby authorize
Fastech Auto Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLS 3143J that was
damaged pursuant to the accident which occurred on 09.06.2019 (date) along
PIE Twys Changi Airport Near To Eunos (location)
involving vehicle no/s SLX 1023J ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 10 day of June (month) 20 19 (year)



Signed by "the third party claimant"





Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

"We/I, Fastech Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd, LKK Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 6,531.00 (repair costs), S\$ 300.00 (loss of use/rental) S\$ 1.45 (search fees) for vehicle no. SLS3143J that was damaged pursuant to the accident which occurred on 09.06.2019 (date) along PTE Tnds Changi Airport Near To Eunos (location) involving vehicle no/s SLX 1023J

This is pursuant to the inspection conducted on 10.06.2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Gan Wei Yi, Edwin ("third party claimant") of vehicle no. SLS3143J to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLS3143J (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 21 day of Aug (month) 2019 (year)



Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

TAX INVOICE

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

AIG Asia Pacific Insurance Pte Ltd
Chartis Building
78 Shenton Way #07-16
Singapore 079120

Attn : Motor Claim Department

Tax Invoice : 21155

Date : 08.08.2019
Vehicle No : SLS 3143J
Make/Model : KIA CERATO
Chassis/Eng# :
Accident Date : 09.06.2019
Claim No :
Reference : 0619 -21155
Policy No :

	Amount
To proceed on lump sum repair	SS 6100.00

E. & O. E.	Total : S\$	6100.00
	GST @ 7% : S\$	427.00
	Amount Due : SS	6527.00


for FASTECH AUTO PTE LTD

All Invoices are subjected to GST

DYNAMIC CAR RENTAL

1 Kaki Bukit Ave 6 #01-46 Autobay

Singapore 417883

Tel No: 6741 7244 / 6746 5405 Fax No: 6745 8520 / 6746 5786

Co. Reg No: 52928467K

To: GAN WEI YI, EDWIN

Invoice : DCR-2019-06-34

Date : 13.06.2019

Agreement No : 20813

Payment Term : LOD

DESCRIPTION	AMOUNT
Rental charges for vehicle : <u>SJV 7392M</u> (0619-21155)	\$ 300.00
Rental Period from <u>10.06.2019</u> to <u>13.06.2019</u>	
<hr/>	
E. & O. E.	Total \$ <u>300.00</u>

LINA PANG

for Dynamic Car Rental

Dynamic Car Rental

1 KAKI BUKIT AVENUE 6, #01-46/48/50 AUTOBAY, SINGAPORE 417883

TEL: (+65) 6741 7244, 6746 5405 FAX: (+65) 6745 8520, 6746 5786

Co. Reg. No. 52928467K

RENTAL TERMS AND CONDITIONS

No. 20813

Name: Gan Wei Yi, Edwin			REG. No.	MAKE MODEL:						
ADDRESS:			SJV 7392M	DIESEL	PETROL	E	1/4	1/2	3/4	F
			KM IN	DATE & TIME IN: 13.06.2019 @ 10.27am						
			KM OUT	DATE & TIME OUT: 10.06.2019 @ 10.50am						
			KM DRIVEN	TIME USED						
NAMED DRIVER										
DRIVING LICENCE NO S9049431G	DATE OF EXPIRY	PLACE OF ISSUE	HOURS		@ \$					
PASSPORT NO	DATE OF ISSUE	PLACE OF ISSUE	3 DAYS		@ \$ 100.00		\$ 300.00			
ADD NAMED DRIVER			WEEKS		@ \$					
			MONTHS		@ \$					
DRIVING LICENCE NO	DATE OF EXPIRY	PLACE OF ISSUE								
PASSPORT NO	DATE OF ISSUE	PLACE OF ISSUE								
IMPORTANT NOTES:			BY INITIALLING, RENTER AGREES TO PAY ADD FEE FOR COLLISION DAMAGES WAIVER (C.D.W.)		SUB-TOTAL		\$ 300.00			
<p>This vehicle is licensed to carry 04 passengers only. No refund will be given for vehicle returns early. No refund will be given for period left in vehicle. Hirer is liable to pay first \$4000 under section I & II in any accident plus loss of earnings while damaged vehicle is under repair. Hirer is liable to pay all parking fee and traffic summonses.</p> <p>Vehicle return during office hour only. No Service on Public Holiday and Sunday.</p> <p>EXCESS: *Sec I - Used in S'pore Only :\$GD2000 *Sec II - Used in S'pore Only :\$GD2000 *Sec I - Used Outside S'pore Only :\$GD4000 *Sec II - Used Outside S'pore Only :\$GD4000 *Wholesen Excess, In S'pore : \$GD100 *Wholesen Excess Outside S'pore : \$GD200</p> <p>ADDITIONAL CONDITIONS: * Geographical areas: Singapore & West Malaysia * Driver must be: a) 18 years old and above; b) holding a valid relevant class of driving license.</p> <p>* Additional Own Damage Excess of \$51,000 is applicable for any named/unnamed drivers who: a) age 22 to 23 years old b) age 66 to 70 years old c) with driving experience of 1 year to less than 2 years in Singapore on the relevant classes of driving license.</p> <p>* Additional All Claims excess of \$52,000 is applicable for any named/unnamed drivers who: a) is 18 years old to 21 years old and/or b) is 71 years old and above and/or c) with driving experience of less than 1 year on the relevant classes of driving license.</p> <p>* Upon returning the replacement vehicle, you must ensure that all expensive and important items to be removed away from this replacement vehicle. We'll not be responsible for any reporting of such losses.</p> <p>* Hirer is liable to pay first \$4000 under section I & II in any accident plus loss of earning while damage vehicle is under repair.</p> <p>Hirer is responsible for Additional \$4,000.00 Excess to the THIRD PARTY DAMAGE / INJURY claims.</p>			TOTAL RENTAL							
			DELIVERY FEE							
			COLLECTION FEE							
			X PER DAY PER WEEK PER MONTH \$ \$ \$							
			BY INITIALLING, RENTER AGREES TO PAY ADD FEE FOR PERSONAL ACCIDENT INSURANCE (P.A.I.) X PER DAY PER WEEK PER MONTH \$ \$ \$							
			PREPAYMENT		TOTAL CHARGE					
			CHECK		DEPOSIT					
			CASH							
			RECEIPT NO.		NETT CHARGE					
			AMOUNT DUE / REFUND							
I HAVE READ THE TERMS AND CONDITIONS ON BOTH SIDES OF THIS RENTAL AGREEMENT AND AGREE THEREOF.										
SIGNED BY THE PARTIES HERETO ON THE _____ DAY OF _____										
X _____ DYNAMIC CAR RENTAL			X _____ RENTER'S/DRIVER'S SIGNATURE							



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 10 Jun 2019 / 10:34:17

Receipt Date/Time : 10 Jun 2019 / 10:34:17

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190610-000674

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - SLX1023J				
As at 09 Jun 2019/17:30:00				
Insurance Co; AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLX1023J Enquiry Fee 20190610103221823989	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx8333	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jun 2019 Edit Reg		10 Jun 2019 00:00 Edit Adj Rpt	\$56,100.00 Edit Estimates	\$56,100.00 View Rpt		Pending for Survey Report Cancel Case














































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: 123 Leasing Pte Ltd , Co. Reg. No.: 201801338W									
Main Claimant: GAN WEN YI EDWIN , ID: S9049431G									
Vehicle Reg. No.:	SLS3143J	Date of Loss:	09/06/2019 17:00 - :59 [109 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7219616809SG	Policy/Cover Note No.:	0999994200 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLX1023J	Policy No. (Claimant):	GA41098611						
		Excess:							
Repairer: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 19/06/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (27/06/2019): Re: No OI GIA Report AIG_SG (11/06/2019): Request To Upload TP GIA Report AIG_SG (11/06/2019): No OI GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





Claim Documents

*SLS3143J (7219616809SG)
[SLX1023J]

TP
GAN WEN YI EDWIN
Jun 9 2019 5:00PM
[123 Leasing Pe Ltd]
Fastech Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Photos/Images				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/06/19 18:48	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	10/06/19 18:48	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
4	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
5	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
6	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
7	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
8	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
9	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
10	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
11	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
12	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
13	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
14	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
15	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
16	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
17	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
18	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
19	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
20	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
21	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
22	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
23	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
24	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
25	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
26	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
27	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
28	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
29	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
30	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
31	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
32	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
33	10/06/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
34	10/06/19 18:49	Reinspection Photo	Load JPG	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	10/06/19 18:49	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
81	10/06/19 18:49	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
82	10/06/19 18:49	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
83	10/06/19 18:49	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	10/06/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	17/06/19 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	17/06/19 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	17/06/19 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	17/06/19 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	17/06/19 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	17/06/19 17:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/06/19 08:44	TP GIA REPORT	 Load PDF	
2	12/06/19 11:24	Non reporting letter	 Load PDF	
3	12/07/19 13:47	LETTER TO OI	 Load PDF	
4	06/09/19 08:25	WORKSHOP INVOICE	 Load PDF	
5	06/09/19 08:25	AUTHORISATION TO ACT FORM	 Load PDF	
6	06/09/19 08:25	Release Voucher	 Load PDF	
7	06/09/19 08:25	RENTAL RECEIPT	 Load PDF	
8	06/09/19 08:25	LTA SEARCH	 Load PDF	
9	06/09/19 08:25	LOD	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/06/19 17:26	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLX1023J (Insd veh)	Model:	KIA CERATO FORTE 1.6 (A)
	SLS3143J (TP veh)		
Date of Accident:	09/06/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	20,690.16
Final Repair Cost	:	\$	6,527.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	300.00 3 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	6,834.45

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 6,834.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

06 Sep
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19010143/UEB3Q2

Date: 06/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994200
Claimant Vehicle No : SLS3143J **Insured Vehicle No :** SLX1023J
 Date of Loss: 09/06/2019 Nature of Claim: TP Claim No: 7219616809SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS3143J**
 Make & Model: KIA CERATO FORTE, 1.6 (A) Engine No: G4FCAH381762
 Reg. Date: 05/05/2010 (Man. Year: 2010) Chassis No: KNAFW611MA5224565
 Colour: Red Odometer: 129352 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45Z R17 Rear Tyre Size: 215/45Z R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,636.60	5,466.43	9,170.17	62.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	2,160.00	2,540.00	54.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,336.60	7,626.43	11,710.17	60.56
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	19,336.60	6,100.00	13,236.60	68.45
+ GST 7.00/7.00% (S\$)	1,353.56	427.00	926.56	68.45
Nett Amount (S\$)	20,690.16	6,527.00	14,163.16	68.45
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,834.45		

INSPECTION

Date of Assignment: 10/06/2019
 Date Inspected: 10/06/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	1,120.30 F	*1,120.30 FL
2	1		*BOOTLID REAR LOGO	Necessary	66.80 F	*66.80 FL
3	2		*BOOTLID REFLECTORS	Cracked (1 PCS ONLY)	840.20 F	*420.10 FL
4	1		*BOOTLID INNER LOCK	Twisted	166.30 F	*166.30 FL
5	1		*BOOTLID WEATHERSTRIP	Twisted	266.50 F	*225.00 FL
6	1		*REAR BUMPER	Distorted	845.20 F	*649.50 FL
7	1		*REAR BUMPER SPONGE	Torn	209.30 F	*166.80 FL
8	1		*REAR BUMPER REINFORCEMENT	Cracked	488.20 F	*366.50 FL
9	2		*REAR BUMPER REINFORCEMENT STAYS	Not Necessary	210.00 F	*- FL
10	5		*REAR BUMPER REINFORCEMENT TOP & LOWER BRACKETS	Not Necessary	110.00 F	*- FL
11	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	97.00 F	*- FL
12	1		*REAR BUMPER LOWER CENTRE GARNISH	No such part	310.00 F	*- FL
13	1		*REAR BUMPER LOWER SKIRTING	Deformed	1,500.00 F	*698.20 FL
14	1		*REAR END PANEL	Dented / Bent	688.20 F	*688.20 FL
15	1		*REAR END PANEL TOP GARNISH	Twisted	165.00 F	*165.00 FL
16	1		*REAR FLOOR PANEL	Repair	1,100.00 F	*- FL
17	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	365.30 F	*- FL
18	2		*TAILLAMPS	Cracked	930.00 F	*930.00 FL
19	2		*TAILLAMP HOUSING PANELS	Repair	430.00 F	*- FL
20	2		*REAR FENDERS	Repair	2,210.00 F	*- FL
21	2		*REAR FENDER INNER TRIMS	Not Necessary	798.20 F	*- FL
22	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
23	1		*REAR EXHAUST	Repair	820.10 F	*- FL
24	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
25	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*280.00 FS
26	1		*REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
27	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
28	1		*REAR LICENCE PLATE	Scratched	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,636.60	6,032.70
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	566.27
Total Parts (S\$)	14,636.60	5,466.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
4	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
6	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	100.00	60.00
7	TO CONDUCT CHASSIS ALIGNMENT	New	380.00	0.00
8	TO SPRAY RUST PROOFING	New	120.00	60.00
9	LABOUR FOR PANEL BEATING ,CUT ,WELD,STRAIGHTENED & REPLACING PARTS	New	1,800.00	800.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,080.00
Gross Labour Cost (\$\$)			4,700.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >