



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/LPC19010176/K1hb3

Date: 10.06.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SH6761E

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 07.06.2019 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	1,855.13
Revised Estimate Amount	: S\$	814.45
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE No: SH 6761E

4/6/2019 8:38

MAKE :

MODEL : TOYOTA PRIUS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR BUMPER <i>x rga</i>			\$ 458.60
REAR BUMPER UNDER COVER <i>- Behl</i>			\$ 552.60
REAR BUMPER SIDE RETAINER <i>x 3m</i>			\$ 112.70
REAR BUMPER CLIPS <i>x 22</i>			\$ 22.00
SUB TOTAL			\$ 1,145.90
LESS 25%			\$ 286.48
DISCOUNTED TOTAL			\$ 859.43
REAR BUMPER REVERSE SENSOR <i>x 3m</i>			\$ 135.70
REAR BUMPER RUBBER MAT <i>x 22</i>			\$ 50.00
			\$ 185.70
LABOUR CHARGE			
Panel Beating			\$ 400.00 ²⁰⁰
Spray Painting Charge			\$ 300.00 ²⁰⁰
Wiring Charge			\$ 30.00 ^{x 22}
Remove/Refix Reverse Sensor			\$ 80.00 ^{x 22}
TOTAL LABOUR			\$ 810.00
ESTIMATE TOTAL			\$ 1,855.13

Kali 11/11/19

7/6/19 11:10 L

2 hrs

PR

DHE Repair pth

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No : 305300667
Date : 08.05.2019

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No : SH 6761E

Date of Accident : 31.05.2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: LONPAC — SDE 83L
- The finalized amount shall be:
 - Spare Parts after List discount \$414.45
 - Labour Charges \$400.00
 - Total for Part-By-Part Repair Cost** \$ 814.45
 - Lumpsum Repair (if applicable) 20% \$0.00
 - Total for Lumpsum repair cost after Less: 20% \$0.00
 - Final Lumpsum Repair cost**

- Estimated normal period for repairs: 2 working days.

- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

- Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : FAUZY BIN MOKHTAR

Tel : 62148319

Fax : 65468156

Signature : 

Name : Kahr

Date : 11/6/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.40			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 08.06.2019
Time: 09:33:27
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305300667
REGN NO : SH 6761E
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 25.05.2017
DATE/TIME IN : 03.06.2019 09:40
ACCIDENT DATE : 31.05.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2287-G PRIG4 GUARD-REAR BUMPER C 1 552.60 ²⁵²~~20.00~~ 442.08

SUB-TOTAL : 442.08

JOB NATURE

0000 L PANEL BEATING 200.00

0001 L SPRAY PAINTING CHARGE 200.00

SUB-TOTAL : 400.00

TOTAL : 842.08

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SH 6761E

MAKE :

MODEL : TOYOTA PRIUS

4/6/2019 8:38

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR BUMPER <i>X 1342</i>			\$ 458.60
REAR BUMPER UNDER COVER <i>-</i>			\$ 552.60
REAR BUMPER SIDE RETAINER <i>X</i>			\$ 112.70
REAR BUMPER CLIPS <i>X</i>			\$ 22.00
SUB TOTAL			\$ 1,145.90
LESS 25%			\$ 286.48
DISCOUNTED TOTAL			\$ 859.43
REAR BUMPER REVERSE SENSOR <i>X</i>			\$ 135.70
REAR BUMPER RUBBER MAT <i>X</i>			\$ 50.00
			\$ 185.70
LABOUR CHARGE			
Panel Beating			\$ 400.00 ²⁰⁰
Spray Painting Charge			\$ 300.00 ²⁰⁰
Wiring Charge			\$ 30.00 ^X
Remove/Refix Reverse Sensor			\$ 80.00 ^X
TOTAL LABOUR			\$ 810.00
ESTIMATE TOTAL			\$ 1,855.13

NETT
NETT

K. Li 11/11/19

7/6/19 11.10.4

2 hrs

P/R

R. H. K. P. H.



This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.


Team: ARC Repair TP(CLS0)1 JOB CARD Sales Order: 3927310 JC NO.: 305300667

OWNER COMFORT TRANSPORTATION PTE LTD 7010045 OWNER NO. 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 65508755 (R) (P) (O)	REGN NO.: SH 6761E MAKE: TOYOTA MODEL: PRIUS HYBRID(G4) YR OF MANUF: 25.05.2017 CHASSIS CODE: JTDKB3FU703556755	MILEAGE FUEL E 1/2 F DATE/TIME IN: 03.06.2019 09:40 TARGET DATE COMPLETION DATE/TIME:
---	---	--

Accident Date: 31.05.2019
NATURE: 3P 01.06.19/B

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Wedge Slip

No.: SH 6761E FZ LONPAC

Signature/Date

Returned to Service Reception upon collection

Exit Pass

Vehicle No.: SH 6761E

Name of Service Advisor Date

To be kept by Security Guard

Reply Delete Junk ...

RE: Y ref:- 18/19/19/VP05/021902 O ref:- SH 6761E - Accident Involving SH 6761E & SDE 83L on 31/05/19 (External General) [External General]

OL ONG LI LI <llong@lonpac.com>

Reply | v

Thu 6/6/2019 5:58 PM

To: Kazali Haji Selahudin; assignments@lkkauto.com; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Fauzy Bin Mokhtar; Lim Kwok Eng; MT_Claim_SG <mt_claim@lonpac.com>

Inbox



DSCN5963.jpg

481 KB

SH6761E (310519).mp4

1 MB

Show all 7 attachments (4 MB) Download all Save all to OneDrive - ComfortDelGro Corporation Limited

Lonpac External - General

Without Prejudice

Dear Kazali

Please liaise with LKK Auto Consultants Pte Ltd for survey.

Dear Nivitha

FYA


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Kazali Haji Selahudin [mailto:kazali@cdge.com.sg]

Sent: Thursday, 6 June, 2019 5:07 PM

To: ONG LI LI

Cc: Fauzy Bin Mokhtar; Lim Kwok Eng

Subject: Re: Y ref:- 18/19/19/VP05/021902 O ref:- SH 6761E - Accident Involving SH 6761E & SDE 83L on

Shu Pei (LKKAUTO)


From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 13 June 2019 3:01 PM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Admin A; Vic (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SDE83L (OI : LPC - 18/19/19/VP05/021902) AND SH6761E (TP : LKK REF - CC3/LPC19010176/K1hb3) on 31.05.2019 [External General]
Attachments: SDE83L 310519.PDF

Lonpac External - General

Dear Shu Pei

Attached is our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.


From: ONG LI LI
Sent: Tuesday, 11 June, 2019 1:20 PM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Admin A; Vic (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SDE83L (OI : LPC - 18/19/19/VP05/021902) AND SH6761E (TP : LKK REF - CC3/LPC19010176/K1hb3) on 31.05.2019 [External General]

Lonpac External - General

Dear Shu Pei

Our Insured has not reported the accident.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Shu Pei (LKKAuto) [<mailto:shupeij@lkkauto.com>]

Sent: Monday, 10 June, 2019 6:36 PM

To: GERALD POH WEE BIN; ONG LI LI

Cc: MT_Claim_SG; Admin A; Vic (LKKAuto)

Subject: Direct Settlement - Accident Involving SDE83L (OI : LPC - TBA) AND SH6761E (TP : LKK REF - CC3/LPC19010176/K1hb3) on 31.05.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SH 6761E at M/s ComfortDelGro Engineering Pte Ltd – Loyang on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeij@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19010176/K1hb3q2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 16-12-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDE 83L	Veh. Inspected	SH 6761E
Policy No.	Z18VP05018906	Coverage (\$)	0.00
Claim No.	18/19/19/VP05/021902	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	07/06/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU703556755	Colour	BLUE
Odometer	331798	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	7 mm
L/H Front Tyre	195/65 R15	DAVANTI	7 mm
R/H Rear Tyre	195/65 R15	DAVANTI	7 mm
L/H Rear Tyre	195/65 R15	DAVANTI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/05/2019	Inspection Date	07/06/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6761E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	458.60	-
1	REAR BUMPER UNDER COVER	DEFORMED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
	LESS 25% DISCOUNT		-286.48	-138.15
			859.42	414.45
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
1	REAR BUMPER RUBBER MAT (SN)	NOT NECESSARY	50.00	-
			185.70	-
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER .		400.00	200.00
	SPRAY PAINTING CHARGE.		300.00	200.00
	WIRING CHARGE.	NOT NECESSARY	30.00	-
	REMOVE/REFIX REVERSE SENSOR .	NOT NECESSARY	80.00	-
			810.00	400.00
	GRAND TOTAL		1,855.12	814.45
	RECOMMENDED COST OF REPAIRS			814.45

Report Ref No. CC4/LPC19010176/K1hb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.